eck our website frequently. Did You Know?

We have an agreement with the US Post Office They pickup at our dock daily! You receive your small packages much less than the UPS one pound minimum freight charge. This saves you "much" in shipping costs.

Prices Subject to Change

Sometimes freight, raw materials, or a vendor will change prices before a new catalog can be printed! Therefore, if in doubt on pricing, check our on-line catalogs. They are up to date and show all changes. Their pricing is correct!



on L Boed

E-mail: info@oldchevytrucks.com



...or Shop On line!

1-800-862-1913 oldchevytrucks.com



GENERAL INFORMATION

...visit our website for SPECIAL savings!

Placing Your Order

Merchandise can be ordered by... Phone, Mail, 24hr. Fax, ...or by visiting our Website! Showroom Hours: 9AM till 5PM central standard time. Closed Weekends

Phone: 1-800-842-1913 or 1-816-833-1913 24hr. Fax: 1-800-262-3749 or 1-816-252-3749 Mail Order Forms ...are located in the back of this catalog. Web: www.oldchevytrucks.com

Outside the U.S. and Canada: United Kingdom 0-800-89-5813 Germany 0130-815630 New Zealand 0-800-449196 Australia 1-800-123-510

Freight and Handling Policy!

We are well aware of your concern about freight and handling charges.



Our history will verify that shipping and handling fees are fair and as low as possible. Your invoice will give you the amount of your order including all shipping charges. *If...* you don't send enough money on freight, we will mail you a note requesting an additional payment. Please pay this quickly, as we reserve the right to hold future shipments if this is not paid. Overpayments on freight will usually be credited in our computer for your next order, - unless you request otherwise. Our computerized scales tell us the least expensive way to ship with UPS, FedEx, or U.S. Mail. Our high-volume, lower-freight discounts save you \$\$ with each order! Because we are in the heart of America, we don't charge across the country high freight.

How Shipped.....

Majority of items are sent Federal Express (Fed Ex) with each parcel insured up to \$100 at no extra cost.

US Postal Service is used for most lighter weight boxes... **Common Carrier Truck Line** for heavier or oversized items.

Service by Air Freight...

Need parts fast. We ship by air! For an extra fee, we offer next day, and second day delivery. Just tell us this requirement when you order!

Truck Line Orders...

All large items that must be shipped truck line **must be prepaid**. In addition, a crating or boxing charge may be added to your order if items are very heavy and require special handling. Remember, shipping to a commercial address rather than your home **always lowers** your freight charges! Inspect **all** incoming packages for damage. If damages are observed make sure the driver notes and signs the receipt as being damaged.

This **(TL)** icon is shown beside **all larger items** found in this catalog. Questions? E-mail us at: *info@jimcartertruckparts.com*



GENERAL INFORMATION



...visit our website for SPECIAL savings!



Back Orders

At times we are temporarily out of a part you requested. It will be put on backorder and shipped as soon as it arrives. We will notify you in 30 days (if we do not receive your merchandise) that your backorder is being cancelled. Any held money will be returned. Please notify our sales dept., or write a note on your MAIL ORDER FORM that you do not want unavailable items backordered.

Cores and Core Charges

A core is your **old part** that we must have in exchange when you buy certain rebuilt parts. The core must be rebuildable and must be the same as the part that was purchased. Core fees are charged plus the cost of the part.

Example: RESP230 300 plus core SPC233 100 = 400. The 100 core charge will be refunded when we receive your core (only if it is rebuildable). If a core is not rebuildable, you will be notified and we will return it if you so desire. Your core may be required for rebuilding. Cores must be shipped prepaid to us.

Special Order Items

Some unusual hard to find items are not stocked. We will try to locate them when we receive your order. These special order parts are non-returnable unless sent incorrectly.



Payment

We accept checks, money orders, or you can use your Visa, MasterCard, or Discover Card. NO C.O.D.'s. Foreign residents please pay in U.S. funds.

Damaged Merchandise

- United Parcel Service Contact our customer service! UPS or FedEx Contact your local office. Damaged items must be left in original container for UPS or FedEx to inspect. They will contact us after inspection.
- U.S. Post Office We insure your shipment only if you provide us with extra funds. If items are received damaged and you requested insurance, take entire container to your local post office, they will make a claim.
- Truck Lines Do not sign delivery receipt if product is damaged without the driver noting, or damaged items will not be covered. Contact their office at once. They will have a representative contact you!

Returning Items

- · We will accept returned unused merchandise within 30 days of our invoice date.
- Unused items over 30 days of purchase will be given a store credit toward future purchases.
- No items without "a Return Authorization number" on the outside of returned package.
- Return shipping by C.O.D. not accepted.
- If we ... filled the order incorrectly we will also reimburse you for freight.

If you ordered wrong or no longer want the item, you may return it within the 30 days and you are responsible for return freight cost. You are subject to a 20% restocking fee after 30 days. (Minimum \$5)

Important!:

NO returns without your invoice! **NO** return of special order items! NO cash returns after 30 days! PRICES ARE SUBJECT TO CHANGE WITHOUT NOTICE.





TABLE OF CONTENTS

15,98

101

...visit our website for SPECIAL savings!

Clutch Head Tools

Coffee Mugs

Α

| Accelerator Pedals, Seals, Etc. 32 Accessory Listings 59 Air Filters 42,89 Alternators Bracket 45 Alternators & Conversion 31, 45-46 Ash Tray Handle 51 Axle Bumpers 95 | Conree Mugs 101 Coils and Cut-Outs 27 Cooling System 71-72 Cowl Panels 114 Cowl Vent Gaskets 16 Cowl Vent Pivot Bolts 16 Crank Hole Cover & Surround 39 | Floorboard Sections, Screws 34, 115 Flywheel Ring Gear 70 Foglight 52 Front End and Steering Parts 85-86 Fuel System 86-90 G Gas Caps 90 Gas Filler Neck Grommets 17 |
|---|---|--|
| В | · Dash Trim 20 Dash Trim Clips 20, 126 | · Gas Tanks 89 · Gas Tank Sending Unit 89 |
| Bar/Counter Stool 107 Baseball Caps 101-102 Battery Cables & Etc. 28 Battery Floor Hole Cover 115 Battery Tray Assembly 33 Bed Cross Sills 14-15 Bed Floors, Metal 13 Bed Floors, Metal 13 Bed Mounting Blocks 10 Bed Items, Miscellaneous 15 Bed Panel 114-115 Bed Roll Custom Lights 56 Bed Strip Bolt Mounting Sets 10-11 Bed Strips 13-14 Bed Wood 12 Bed-To-Frame Bolt Kits 10 Blue Dots 100 Brake Cables & Etc. 67 Brake Division Blocks 66 | Dash Thin Clips 20, 126 Decals:Grille, Tailgate, Oil Filters, Hubcaps 21-22 Dimmer Switch 26 Distributor Items 46,75 Distributor Cap 76 Door Bumpers 25 Door Bottoms 115 Door Components 23-25 Door Ferrules 24 Door Handles 24 Door Hinges 23 Door Lubrication Stickers 98 Door Patch Panels, Exterior 23,114 Draglinks 85 Door Striker Plates 24 Drive Shaft Bushing 74 Drive Shaft Bushing 74 Driveshaft & Differential Items 73-74 E E Electrical Items 26-31 Dash/Courtesy Switch 26 Rear Door Switch, Panel/Sub. 26 | Gauges 122-124 Gauge Decals 122 Gauge Cluster Assembly 122 Generators, Rebuilt, Cutout 27,75 Glovebox Cardboard, Etc. 17 Glovebox Hinge 17 Grease Fittings 95 Grille, GMC Items 38-40 Grille Shells 38, 120 Grilles and Related Items 37-40 Grille Bar Clips, COE 38,126 H Halogen Headlights 58 Headlight Assembly & Items 52-53 Header Panels 19-20 Headlight Knobs 50 Headlight Stands 52 Headlight Switch 26 Headlight Switch 26 |
| Brake Lines Brake Conversion Brake Parts Brake Parts 47-48, 64-67 Bumper Bolts, Nuts, Etc. Bumper Brace Bumper Brace 104 Bumpers and Related Items 104 | Emblems and Ornaments 125 Engine Bolt Kit 42 Engine Components 75-84 Engine Gaskets 77-79 Engines, Used 84 Exhaust Manifold 44, 84 Exhaust Parts 84-85 | Heads, Engine Heat Riser Spring Heater Blower Switch Heater Duct Tubing High Performance Items Hinge Pins Hood related & Hinge 40,120-121 |
| | F | Hood Ornaments & Trim 125-126 Hood Related Items 40-41 |
| Cab Corners Cab Insulation Kit Cab Mount Kits Cab Over Engine Cab Part & Misc. Items Cab Repair Panels Cab Windlace Seals & retainer | Fan and Fan Belts Fender Bolts Fender Braces Fender Protectors Fender Welt & Inner Gaskets Fenders 119-120 Fender Medara Inteko 41 | Horn Button Assembly & Etc. 18-19 Hub Cap Wheel Clips 91 Hub Caps 99, 125-126 Hush Mats 16 Hydrovac Power Brake 64 |
| 16,17• Carburetors• Choke and Throttle Cables• Clutch Parts69-71 | Fenton Headers, Intake 43-44 Firewall Related Items 29, 37 Flashlight, Vintage 106 Floor Items 32-34 | Identification Tags Ignition Parts Intake Manifold, Warming kit |
| 4 oldchevytrucks.con | 1 ORDERS 1-800-862-1913 TI | ECH HELP 2-4pm 1-816-252-5857 |

| 5,98 101 27 -72 | Floor Mats 32 Floorboard Sections, Screws 34,115 Flywheel Ring Gear 70 Foglight 52 |
|--|---|
| 114 16 16 | Front End and Steering Parts 85-86 Fuel System 86-90 G |
| 39 20 126 -22 26 5,75 76 25 115 -25 24 24 24 23 98 | Gas Caps Gas Filler Neck Grommets Gas Tanks Gas Tanks Gas Tank Sending Unit Gauges Gauge Decals Gauge Cluster Assembly Generators, Rebuilt, Cutout Grovebox Cardboard, Etc. Glovebox Hinge Grease Fittings Grille, GMC Items Gas, 120 Grille Shells Grille Sand Related Items 37-40 Grille Bar Clips, COE 38, 120 |
| ,114 | · Halogen Headlights 58 |
| 85 24 74 -74 | Headlight Assembly & Items 52-53 Headers, Exhaust 43-44 Header Panels 19-20 Headlight Knobs 50 |
| -31 26 26 125 42 | Headlight Stands Headlight Switch Headliners Heads, Engine Heat Riser Spring 84 |
| -84 -79 84 , 84 -85 | Heater Blower Switch 26 Heater Duct Tubing 91 High Performance Items 42-49 Hinge Pins 96 Hood related & Hinge 40,120-121 Hood Ornaments & Trim 125-126 |
| 72 15 120 120 41 | Hood Related Items 40-41 Horn Button Assembly & Etc. 18-19 Hub Cap Wheel Clips 91 Hub Caps 99, 125-126 Hush Mats 16 Hydrovac Power Brake 64 |
| 120 | I |
| -44 , 37 106 -34 | Identification Tags Ignition Parts Intake Manifold, Warming kit 43 |

TABLE OF CONTENTS





| K Key Blanks Kick Panels Kingpins Knobs | 100 129 85 50-51 | Radiator Support Pads Radiators & Items Radio Antenna Restored Radio Ring & Pinion Rocker Arm Shaft Running Board to Bed Apt Running Boards Running Boards Items |
|--|--|--|
| Leaf Springs & Items 48 License Plate Bracket | 3,93-94 41 | S |
| License Plate Fasteners Lifters Light Bulbs, Six Volt Lug Nuts | 100 79 57 93 | Sales Brochures Salesman's Data Book Seat Bumpers & Rails Seat Covers Shift Knobs |
| Μ | | Shock Absorber and Li |
| Manuals, Miscellaneous Master Cylinder & Etc. Master Cylinder, Floor Hole Cover Mirror Arms Mirrors, Outside Motor Mounts 45 Muffler and Components | 59-63· Shop Manua64· Shop Signs64· Spare Tire A34· Spare Tire H96· Spark Plug V96· Spark Plugs45,76-77· Speedomete584-85· Speedomete | Shock Absorber Conve Shop Manuals Shop Signs Decals Spare Tire Assembly Spare Tire Hook Spark Plug Wire Sets Spaedometers Speedometer Cables Speedometer Items |
| 0 | | Splash Apron & Bracke |
| Offenhouser Oil Caps Oil Filter Assembly Oil Filter Lines Oil Engine Line Oil Pump Owner's Manuals | 44 92 42, 92 92 83 83 59,60 | Spring Bolts and Bush Spring Shackles Stake Pockets Starter & Items Starter Solenoid Starter Switch Steering Column Seal Steering Mast Bearing |
| Р | | Steering Parts Steering Wheel |
| Paint, Bumper and Grille Paint, Engine Paint, Exterior and Interior | | Step Plates Stoplight Switch Suspension Parts Switch, Under Dash |
| Park Brake Boot Parklight Assemblies, Lens | 33 & | т |
| Gaskets, & Etc. · Pistons and Rings · POR-15 · Pressure Plate | 53-54 · T-shirts 81 · Tail Pipe, He 112 · Tailgate Cha 69 · Tailgate Hin | |
| R | | Tailgates Taillights and Parts |
| Radiator Caps Radiator Hoses | 71 71 | Temperature Sending I Terminal Blocks |

| Radiator Support Pads 41 Radiators & Items 71-72 Radio Antenna 113 Restored Radio 113 Ring & Pinion 48 Rocker Arm Shaft 79 Running Board to Bed Apron 117 Running Boards 105 Running Boards Items 34,105-106 |
|--|
| S |
| Sales Brochures60Salesman's Data Books60Seat Bumpers & Rails20Seat Covers127Shift Knobs51Shock Absorber and Links94Shock Absorber Conversion48Shop Manuals59Shop Signs Decals98Spare Tire Assembly100Spare Tire Hook100Spare Tire Hook100Spare Redometers122Speedometer Cables92, 124Speedometer Cables92, 124Speedometer Items122, 124Splash Apron & Brackets36Spring Bolts and Bushing94Starter & Items34,75Starter & Items34,75Starter Solenoid26Steering Column Seal & Etc. 18,33Steering Mast Bearing19Steering Wheel18Step Plates106Stoplight Switch27Suspension Parts47-49, 93-95Switch, Under Dash26 |
| т |
| T-shirts Tail Pipe, Heat Shield & Etc. Tailgate Chains & Etc. Tailgate Hinges Tailgate Hinges Tailgates Tailgates Taillights and Parts 54-57 Temperature Sending Unit Terminal Blocks Tail 20 |

| Tire Tubes Tool Bag Transmission Parts 45,69 |)-81 98 100)-71 106 31 |
|---|---|
| | 3-74 127 132 |
| V | |
| Valves Valve Cover & Etc. Voltage Booster | 5-76 80 43 28 113 27 |
| W | |
| Wheel Seals Wheel Studs Wheels Window Channel Window Glass, Patterns 133, | 134 |
| Window, Rear Glass Rubber Kit Windshield Connecting V-Bars Windshield Connector Windshield Crank-Out Windshield Frames Windshield Gaskets Windshield Post Covers Wiper Arms and Blades 138- Wiper Items 20,138- | 136 135 135 135 134 135 139 |

ORDERS 1-800-862-1913 TECH HELP 2-4pm 1-816-252-5857 oldchevytrucks.com 5

INTRODUCTION



...visit our website for SPECIAL savings!

An introduction page may seem a little unusual for a parts catalog, however, it is an excellent way to tell you something about myself and my business. You should know some details about a company or a person you plan on dealing with. Since we sell parts worldwide, this is probably the best way to tell you who I am and why I have a Chevrolet and GMC truck parts business.

My first antique car, a Model A Ford, was purchased during my college years in the mid-1960's. Over several years, I personally gave it a ground-up restoration and became very active in local and national clubs. Though I still have a Model A, my interest has gradually drifted toward early GM pickups.

In 1978, I purchased my present 1950 Chevrolet 1/2 ton pickup to use as a driver. Though it worked well, the decision was finally made to give it a near total restoration. This began the truck parts business. While some parts waited for their turn in the restoration, persons would request them for immediate use. I would then reorder for my own use. This began to snowball and soon, with some experimental ads in national magazines, plus my enjoyment of trucks, the business took off.

After 15 years with a major national corporation, it was felt that this field was more rewarding. A decision was made that a mid-life career change should be made. All past sales and business expertise would be put into making this a successful enterprise. This has been done with many personal rewards. The goal is to continue to look ahead, develop and introduce new parts for the older



GM pickup. When we do what we enjoy, there are no limitations on achievements!

We are now seeing the early stepside pickup growing in popularity like the Model A Ford in the 1960's. I share the opinion, with many, that desirability of the Chevrolet and GMC stepside pickups has just begun to grow. It will far surpass the popularity of the Model A Ford. Even now, the choice lower production items for these trucks are becoming very difficult to find as more people visit the few remaining salvage yards having older vehicles. You own your old GM truck at the right time. It is an investment even if you enjoy using it as a driver.

Yes, this business sells parts, but it is based on service to the customer. My personal involvement in the restoration of pickups, plus more than 40 years enjoying antiques, results in this dealer loving the business I am in. Over 20 employees, many phone lines, two to three daily FedEx and US mail visits, 5 storage buildings, etc. makes service to our customers among the best!! Do not hesitate to call if we can be of assistance.

Thanks,

Jim Carter

E-mail: info@oldchevytrucks.com You'll like our web site: www.oldchevytrucks.com

TIPS & HINTS

...visit our website for SPECIAL savings!



One of the more common questions asked is, "How do I tell the different years of these trucks?"

Your truck may have come without a title, many do. Some have parts interchanged with several years, even though they are correct for only one year. Body and bed changes during the last 30 to 60 years, just to keep the truck going, now make some restorations confusing.

In the following, several items per year will be mentioned which might help you, in the field, when looking to buy a truck or just parts. The comment by each year does not mean it is always exclusive to that year. If you feel some errors exist, please let us know.

- 1934-35 Cab doors and body reinforced with wood. Windshield is held open with a wingnut on both windshield sides. Hood sides have four vertical louvers on each side. Chevrolet blue Bowtie emblem is on the front top of the grille shell, not attached to grille. No glovebox. Gauges are black with white letters. Engine as in 1936 is a 207 six cylinder. Brakes are cable activated, not hydraulic.
- Early 1936 Final use of the "high roof" cab. Doors have three hinges. Round dash gauges black with white letters. Headlights attach to short bar between fender and radiator. Top of windshield frame has square corners and round lower corners. Bowtie emblem attaches to grille and each side of hood. First year for hydraulic brakes.
- Late 1936 Beginning of the "low roof" cab. The only remaining body wood is the front door posts and a horizontal connector. Windshield frame has round corners and is 12" high. Half ton bed length continues 72". Running board tread still has diamond like raised spots. Doors have two hinges. Gas tank under rear of bed with filler through bed side behind fender. Round dash gauges have cream colored faces. First year for GMC pickup.
- **1937** Gas tank filler under seat results in half cushion bottom raised to fill tank. Windshield frame is 1936 except is 14" high. Chevrolet introduces the 216 engine. This was used through 1953. Half ton bed length 77". Chevrolet emblem attached to upper middle of grille. Running board tread runs length of board. The GMC pickup uses the valve-in block (flat head) six cylinder borrowed from Oldsmobile.
- **1938** Much like the 1937, however, by mid "38 gas tank fillers extend through the cab wall. Chevrolet front emblem is at top of the grille. The GMC 1/2 ton pickup uses the flat head six cylinder engine borrowed from Pontiac. This engine even has the Pontiac Indian head cast in the right side of the block. As in 1939 the Chevrolet bumpers have one full length groove on the face.
- 1939 As in 1940, Chevrolet tailgate has script lettering. Speedometer is round, not a rectangular type as 1940 to 1946. First year for the two piece windshield. Black dash knobs and window crank knobs. GMC introduces its own high pressure 228 engine. This basic engine design used through 1959. Last oval taillights on Chevrolet.
- 1940 Chevrolet bumpers have two full length grooves on face. One piece headliner. Hood lacing on cowl is fabric, not rubber as later. Rose tan dash knobs in 1940 to 1946. First year for sealed beam headlights. This results in small bullet-like parklights on top of front fenders. The rectangular taillight first introduced on Chevrolet and is carried through 1953.
- **1941** No stamped name in Chevrolet tailgate. Last year for right hand outside door lock in handle. Steering column is painted black. Six planks in bed. Rear window frame is die cast metal on outside over rubber. Rubber gas tank grommet. Headlight assemblies now secured to top of fenders.
- 1942 Right outside door lock moves down into the door. Late 1942 uses leather gas tank grommet. Two piece headliner.
- 1946 Seven planks in bed. Rear window now without metal exterior frame. Steering column painted brown. As in 1942, windlace around door opening covered with brown leatherette. As with earlier years, no weather seal secured to doors. Gas tank grommet went back to rubber. Gas tank continues to be located under seat.

1946 vs. 1947 Note: Occasionally a customer's truck is titled 1947 but the body design is 1946. It can make ordering parts confusing.

- Reasoning:
- (1) In several factories the 1946 design was carried over through about May 1947.
- (2) The GM "Master Parts Catalog" does not show an early 1947. When this year is mentioned it always refers to the 1947-55 1st series "Advanced Body Style".



1934-46 TRUCK TRIVIA

...visit our website for SPECIAL savings!

A great increase in GM truck rebuilding is now occurring throughout the country. Though most enthusiasts build a fun truck with numerous modifications and drive them daily, some require their vehicle to be as detailed as they were when new. For those involved in restoring their truck to this exact originality, the following data should be of interest. These appear to be several of the more asked questions about the subject of restoration by our customers.

- From 1939 and up, the GMC six cylinder was a high pressure insert bearing engine initially 228 and 248 cubic inches. Chevrolet trucks did not adopt the full insert bearing engine until 1954. This results in their similar appearing dash clusters with the of maximum oil pressure gauge reading of 80# for GMC and 30# for Chevrolet.
- Dark green was the standard exterior paint color. Most other colors, including black, were a non-cost option.
- The GMC with six-volt system uses a positive ground electrical system. Chevrolet uses negative ground.
- The GMC and Chevrolet pickups share bodies, most suspension, transmissions, etc. not engines, grilles, tailgates, exterior colors or hub caps.
- In 1946 the 8 hole split rim was introduced on the 3/4 tons. Prior to this, the 3/4 tons used a heavier 6 bolt wheel than the ones on the 1/2 tons. These are often referred to as the artillery or scalloped type wheel.
- Early trucks were titled on either the body ID plate or engine number. If your title used the engine number and it has been replaced over the years, you may have major problems in selling or licensing.
- The famous Chevrolet high pressure 235 engine was used between 1954 and 1962. It's big brother, with some larger internal parts, was the 261 engine. A low pressure Chevrolet 235 was available on larger trucks only between 1941 and 1953. This earlier 235 has little in common with it's later 235 relative.
- Whitewall tires were not available from the factory during these early years.
- The pickup running boards were black painted steel. The rubber covering was reserved for cars.
- Sealed beam headlights were first used on new trucks in 1940.
- The 4-speed transmission (optional on 1/2 ton) during these years is not synchronized. The driver must "double clutch" between shifts. The 3-speed was synchronized, but only in second and third gear.
- Electric wiper motors were not available from GM.
- The first year of the 1939-46 series had a different dash. Therefore, the 1939 glove box and windshield crankout assembly is used this one year only.
- These body style changes are grouped into the following years. 1934-36 high cab, 1936-38 low cab, and 1939-46.
- The right taillight was an option. Very few trucks had these dealer installed options.
- The Chevrolet 216 engine was used in both light trucks and cars between 1937-53. For the roads of the early years, they were great little engines!
- GMC began light truck production in 1936. Before this their primary market had been large trucks. With the "Great depression" GMC need to help sales!
- The pickup bed floors were oak until about 1940. From approximately 1941 until the last wood bottom stepside in 1987, the material was hard yellow pine. It was painted, not varnished. On at least 1946 and older the wood was painted black. Between 1941-1946 GMC, pickups used metal bottom beds, not wood.
- During 1939-40, the Chevrolet 1/2 and 3/4 ton tailgate displayed its lettering in script style. The other years between 1934-46 had plain tailgates with no letters. GMC however, always used their logo on the 1936-46 tailgates.

Truck users buy more CHEVROLET TRUCKS than any other make



Buy Wisely - Buy Chevrolets

The combined experience of truck buyers in all parts of the nation points irresistibly to the following plain, practical, hard-headed fact:

It pays in all ways to buy Chevrolets!

Large and small truck users alike buy more Chevrolet trucks than any other make because they *know* that Chevrolets stand up better and last longer than does any other truck offering anything like Chevrolet savings in purchase price, operation and upkeep.

And the rewards of buying Chevrolet trucks best savers, best sellers in t CHEVROLET MOTOR DIVISION, General Motors Sales Corporation, DETROIT, MICHIGAN

are even greater today than in any previous year.

Vitally important improvements in the Chevrolet line for 1940 have added still further to the strength of Chevrolet construction, to the efficiency of Chevrolet Valve-in-Head sixcylinder performance, and to the all-round economy of Chevrolet ownership.

Why gamble on your truck purchase? Buy the *proved* leader! Buy Chevrolet trucks—"The Thrift-Carriers for the Nation"—best haulers, best savers, best sellers in the entire truck field!





...visit our website for SPECIAL savings!

BED BOLTS BED-TO-FRAME BOLT KITS

Includes correct carriage bolts, hex nuts, lock washers, and difficult to find flat washers with offset square hole.

| | l onset square noie. | |
|----------|---|------------------------------|
| *** | • Zinc Plated For wood floor beds. Part No. Description BP1411 1934-46 Short bed (1/2 ton)set BP1421 1934-46 Long bed (1/2 ton and 3/4 ton)set BP1431 1934-46 Extra long bed (1 ton)set | 13.95 15.95 16.95 |
| | Stainless Steel Type | |
| | For wood floor beds. | |
| | Part No.DescriptionBP14411934-46Short bed (1/2 ton)set | 31.50 |
| | BP1441 1934-46 Short bed (1/2 ton)set BP1451 1934-46 Long bed (1/2 ton and 3/4 ton)set | 37.50 |
| | BP1461 1934-46 Extra long bed (1 ton) | 39.95 |
| | | |
| | GMC Metal Bottom Bed Bolt Kits | atad |
| | Includes special oval washers, carriage bolts, hex nuts, and lock washers. Zinc pl Part No. Description | ated. |
| | BP172 1940-46 Short bed (1/2 ton)set | 20.35 |
| | BP173 1940-46 Long bed (1/2 ton and 3/4 ton)set | 23.75 |
| | Bed Washers Though included in above kits, we also provide these individually. With corresquare hole. Part No. Description BP176 1934-66 Round, stamped steel with correct offset square holeseach BP177 1934-66 Round, stainless steel with correct offset square holeseach BP510 1934-66 High Polished Stainless steeleach BP178 1940-46 Oval, stamped steel. Used on GMC metal bottom bedseach | 1.25 2.95 4.95 1.75 |
| • | BED MOUNTING BLOCKS AND PADS | |
| •• | Cut and drilled hardwood and rubber pad set. Ready to install. • Short Bed 1/2 Ton Part No. Description | |
| | BP135 1934-40set | 19.95 |
| | BP136 1941-46set | 19.95 |
| \wedge | BP200 1940-46 GMC with original metal bed floorset | 18.95 |
| | Long Bed 1/2 and 3/4 Ton Part No. Description | |
| | BP138 1934-40set | 24.95 |
| | BP1381 1941-46set | 24.95 |
| | BP201 1940-46 GMC with original metal bed floorset | 18.95 |

oldchevytrucks.com ORDERS 1-800-862-1913 TECH HELP 2-4pm 1-816-252-5857

10

...visit our website for SPECIAL savings!



BED STRIP BOLT MOUNTING SETS

Includes the two sizes of carriage bolts, proper flat and lock washers. 250 to 400 pieces depending on year.

| | 22.95 23.95 |
|-------------------|----------------------|
| | 26.50 26.95 |
| | 28.95 29.95 |
| | s tight |
| BP187RC 1946set 3 | 37.50 38.50 |
| | 41.55 42.75 |
| | |
| | 51.45 53.75 11 |



| | P BOLT MOUNTING SETS (continued) Bed 1 Ton Stepside Description 1934-45 | 59.35 |
|--|--|--|
| BP189SS | 1946set | 59.90 |
| Planks cut a (O) is used | E BED WOOD SETS and grooved. Excellent quality "C" Grade hard yellow pine (P) or clear in the manufacturing of these replacement wood sets. Wood is smoo attractive grain. | |
| | d 1/2 Ton Stepside | |
| Part No. | Description | |
| BP123P | 1934-36 6 board 72"set | 195.00 |
| BP1230 | 1934-36 6 board 72"set | 235.00 |
| BP215P | 1937-39 6 board 76"set | 247.50 |
| BP2150 | 1937-39 6 board 76"set | 300.00 |
| BP216P | 1940-45 6 board 77" | 195.00 |
| BP2160 | 1940-45 6 board 77"set 1946 7 board 77 1/8"set | 235.00 |
| BP191P BP191O | 1946 7 board 77 1/8set | 195.00 235.00 |
| Part No. BP126P BP126O BP217P BP217O BP218P BP218O | 1/2 and 3/4 Ton Stepside Description 1934-36 6 board 84 3/4" 1934-36 6 board 84 3/4" 1937-39 6 board 85 3/4" 1937-39 6 board 85 3/4" 1937-39 6 board 85 3/4" 1940-45 6 board 85 3/4" 1940-45 6 board 85 3/4" | 250.00 215.00 250.00 215.00 250.00 |
| BP193P BP193O | 1946 7 board 85 3/4"set 1946 7 board 85 3/4"set | 215.00 250.00 |
| | ng Bed 1 Ton Stepside | |
| Part No. | Description | 040.00 |
| BP129P BP129O | 1934-36 6 board 107"set 1934-36 6 board 107"set | 240.00 |
| BP1290 BP220P | 1937-39 6 board 107set | 240.00 |
| BP2200 | 1937-39 6 board 107set | 240.00 |
| BP221P | 1940-45 6 board 107"set | 240.00 |
| BP2210 | 1940-45 6 board 107set | 280.00 |
| BP195P | 1946 7 board 107" | 240.00 |
| BP1950 | 1946 7 board 107" | 280.00 |
| | n and Panel Trucks 1/2 Ton | |
| Part No. | Description | |
| BP508P | 1939-45 6 boardset | 370.00 |
| BP508O | 1939-45 6 boardset | 450.00 |
| BP509P BP509O | 1946 7 boardset 1946 7 boardset | 215.00 250.00 |
| DF 3090 | IBHO I DUAIU | 200.00 |

...visit our website for SPECIAL savings!



STEPSIDE METAL BED STRIPS(TL)Over 97" Ship Truckline.

Cold Rolled Steel Bed Strips

1-1/2 inches wide as original. Punched strips have exact hole spacings and length. Non punched strips may be slightly longer and need to be trimmed to length.

| Part No. | Description | |
|----------|--|-------|
| BP114 | 1/2 ton (non punched) 77-1/8"each | 11.00 |
| BP11689 | 3/4 ton (non punched) 89"each | 12.50 |
| BP118 | 1 ton (non punched) 107"each | 18.00 |
| BP1151 | 1934-36 1/2 ton (punched)each | 11.00 |
| BP1152 | 1937-39 1/2 ton (punched)set | 55.00 |
| BP1153 | 1940-46 1/2 ton (punched)each | 11.00 |
| BP11701 | 1936 3/4 ton (punched) Chevrolet onlyeach | 12.50 |
| BP11702 | 1937-39 3/4 ton (punched) Chevrolet onlyset | 55.00 |
| BP12101 | 1937-39 1/2 ton longbed and 3/4 ton GMC 89-7/8"set | 50.25 |
| BP11703 | 1940-46 3/4 ton (punched)each | 12.50 |

Stainless Steel Bed Strips

For that extra touch. Eliminate the possible peeling of chrome plating. Will never rust. Always bright. Replaces the original cold rolled steel perfectly. B (N) Deeevination


| I | Part No. | Description | |
|---|----------|--|-------|
| | BP119 | 1/2 ton (non punched) 77-1/8"each | 18.50 |
| | BP12189 | 3/4 ton (non punched) 89"each | 19.50 |
| | BP262 | 1 ton (non punched) 107"each | 24.50 |
| | BP1201 | 1934-36 1/2 ton (punched)each | 20.00 |
| | BP1202 | 1937-39 1/2 ton (punched)set | 89.90 |
| | BP1203 | 1940-46 1/2 ton (punched)each | 20.00 |
| | BP12202 | 1937-39 3/4 ton (punched) Chevrolet onlyset | 92.50 |
| | BP12012 | 1937-39 1/2 ton longbed and 3/4 ton GMC 89-7/8"set | 92.50 |
| | BP12203 | 1940-46 3/4 ton (punched)each | 21.90 |
| | | | |

• Bed Strips for the Custom, Non-Original Truck

When you want a completely smooth "no bolt" look in your bed. These anodized high shine aluminum strips secure the wood planks as well as the originals. Special fasteners slide in the underside groove to the location of original bolts. Uses original grooves in wood planks. Note: You cut length to fit.

Part No. Description

| BP1225 | For short beds, 80 inches with fastenerseach | 39.95 |
|--------|---|-------|
| BP1226 | For long beds, 97 inches with fastenerseach | 44.50 |
| BP171 | Fastener Kit set of 8, with 3 fender washers (for 1 strip)set | 34.95 |





1/2 ton (non punched) 77-1/8"each

3/4 ton (non punched) 89"each

1 ton (non punched) 107"each

1934-36 Mid (Center curve as original) 1/2 ton (punched)pair

1934-36 (straight only) 1/2 ton (punched).....pair

1937-39 1/2 ton (punched)pair

1940-46 1/2 ton (punched)pair

1937-39 3/4 ton (punched) Chevrolet onlypair

1937-39 1/2 ton longbed and 3/4 ton GMCpair

1940-46 3/4 ton (punched)pair

17.95

22.95

25.95

46.00

39.50

39.50

39.50

42.70

42.70

44.00

...visit our website for SPECIAL savings!

STEPSIDE METAL "CORNER" BED STRIPS

(\mathbb{TL}) Over 97" Ship Truckline.

Description

Description

Welds to bed sides and lays over edge of wood bed plank.

Cold Rolled Steel

Part No.

BPSN077

BPSN089

BPS0007

BPS0001

BPS0002

BPS0003

BPS0102


BPS0101 BPS0103

Part No.

Stainless Steel

BPSN0107

BPS0007



BPS1009

| BPSN177 | 1/2 ton (non punched) 77-1/8"each | 27.90 |
|----------|--|-------|
| BPSN189 | 3/4 ton (non punched) 89"each | 29.95 |
| BPSN1107 | 1 ton (non punched) 107"each | 35.95 |
| BPS1009 | 1934-36 Mid (Center curve as original) 1/2 ton (punched)pair | 69.50 |
| BPS1001 | 1934-36 (straight only) 1/2 ton (punched)pair | 58.25 |
| BPS1002 | 1937-39 1/2 ton (punched)pair | 69.50 |
| BPS1003 | 1940-46 1/2 ton (punched)pair | 69.50 |
| BPS1102 | 1937-39 3/4 ton (punched) Chevrolet onlypair | 69.50 |
| BPS1101 | 1937-39 1/2 ton longbed and 3/4 ton GMCpair | 69.50 |
| BPS1103 | 1940-46 3/4 ton (punched)pair | 69.50 |

Corner Bed Strip Covers, Stainless Steel

We have the answer for those wanting stainless steel corner angles, but don't like the burn spots from welding them to the bed sides. These are made to fit over your pre-existing steel corners. You maintain the strength of the originals but now have the stainless appearance. Saves body shop expense.

Note: This item does not fit well over reproduction corners.

| Part No. | Description | |
|----------|---------------------------|-------|
| BPS1097 | 77-1/8" (non punched)pair | 52.75 |
| BPS1096 | 97" (non punched)pair | 52.75 |

BED CROSS SILLS

Cross Sills, Front and Middle. Made in USA!

Like original. Includes the two pad support plates with each sill. Drill 1/4" holes for bed strips depending on the width of the boards in your bed.

Part No.DescriptionBP1011934-53Ste

 1934-53
 Stepside. Shorten on 1934-46

 (1/2 and 3/4 ton only).....each
 24.95

...visit our website for SPECIAL savings!



| C. | BED CROSS SILLS (continued) • Cross Sills, Rear. Made in USA! Fits below tailgate. Heavy steel for wood floor as original. Part No. Description BP104 1934-39 50 7/8" |
|----|---|
| | Cross Sill, 1940-46 GMC Rear. Made in USA! Used with original metal bed floor. Includes the two stamped strips which you weld over the corrugated bed floor end. Part No. Description BP273 1940-46 Metal flooreach 134.50 |
| | MISCELLANEOUS BED PARTS• Tailpipe Shields. Made in USA!A must for that exact restoration. Perfectly replaces the lost or damaged factory metal platethat secures to the underside of bed. Protects bed wood from tailpipe heat damage.Part No.DescriptionBP1471934-46each7.95 |
| | Rear Fender Bolts Secures fender to bedside. Correct pan head design. Part No. Description BP149 1934-72 Phillips headeach .75 BP148 1941-54 Clutch head as original on most pickupseach 1.15 |
| | • Clutch Head Drivers We stock the three clutch head drivers used in these early trucks. This includes the large 5/16" size that fits the above stepside rear fender bolt. Part No. Description MS313 Clutch head drivers |

ORDERS 1-800-862-1913 TECH HELP 2-4pm 1-816-252-5857 oldchevytrucks.com 15



Floor Kit

Rear Cab Kit

CAB RELATED PARTS

...visit our website for SPECIAL savings!

CAB INSULATION KITS

Cab Insulation Kits

Most people love our older GM trucks but some wish for the more quiet riding comfort found in modern vehicles. We have the solution with new "state of the art" truck acoustic technology. Our kits use a multistage, automotive insulation, and dampening system that nicely controls cab noise, metal vibration, and heat.

In about two hours you can install these pre-sized self-adhesive sound damper pads plus the pre-trimmed heat absorber / barrier panels that are custom cut to the size of your trucks interior. Once the headliner, door panels, floor mat, seat cushions and rear metal interior panels are put back in place, no one will see the barrier material, but you will know immediately on the first drive! Instructions include location and labels on each panel. Spray adhesive and sealing tape help complete the improvements. (Vertical portion of firewall insulation included in FP147 cover in our Front Parts section.)

Part No. Description

| | CBK150 | 1934-46 Cab Insulationkit | 483.00 |
|--|--------|---------------------------|--------|
|--|--------|---------------------------|--------|

HUSH MAT! • Cab Insulation Sheets by HushMat, Black

Now an inexpensive way to quiet your ride on all early trucks and cars! Eliminates much road noise and vibration plus provides thermal insulation.

Apply to door and roof skin, cab panels, and floors from firewall to rear panel. Virtually no pre-cleaning. One-Step application simply cut, peel, and stick. Approx: .07 inches thick. Bends and forms easily. Cut sheets to the size needed. The black color helps hide it in dark places.

| Part No. | Description | | |
|--------------|---|--------|--|
| CBK161 | 10 sheets 12" x 12" (covers 10 sq. ft)set | | |
| CBK162 | 20 sheets 12" x 23" (covers 38 sq. ft)set | 249.95 | |
| | | | |

COWL VENT GASKETS • Cowl Vent Gaskets (Between hood and windshield.)

| Part No. CB219 CB108 | Description 1934-46 Foam material as originaleach 1934-46 Molded rubber typeeach | 7.00 11.50 |
|--|--|----------------|
| Cowl Ven Part No. CBC199 CBC200 | t Pivot Bolts. Made in the USA. Description 1939-40 With shoulder, 2 per truck. Stainless steelpair 1941-46 With shoulder, 2 per truck. Stainless steelpair | 16.50 16.50 |
| CAB WIN • Cab Wind Part No. | llace | |

| and a state of the | i artito. | Becomption | |
|--|-----------|---|-------|
| | CB117 | 1934-40 Black 3/8" bead as originalpair | 39.50 |
| | CB118 | 1934-40 Brown 3/8" bead as originalpair | 39.50 |
| 20 49 2 00 | CB183 | 1941 Black 1/2" bead as originalpair | 36.75 |
| | CB166 | 1942-46 Black 1/2" bead | 36.75 |
| | CB184 | 1942-46 Brown 1/2" bead as original | 37.75 |
| 4 | | | |

Cab Windlace Vertical Retainer



| _ | | | | | |
|--------|--|--|---|--|---|
| 0 0 | | • Lower Cab Part No. CB121 | Windlace (Attaches to floor edge.) Description 1936-46 Black as original | pair | 14.50 |
| / | | Glovebox (Formed to sh | CARDBOARD Cardboard hape. Chevrolet or GMC. Die stamped and assembled. on the market. Show quality! Made in the USA. Description | Felt lined to | make it |
| | | CB1301 CB1302 CB1303 | 1936-38 1939 1940-46 | each | 24.50 24.50 24.50 |
| | () and the second secon | • Glovebox S Part No. CB228 | Screws Description For installing glovebox in dash | set | 1.95 |
| | 0 0 | • Glovebox I Part No. CB426 CB427 | Door Hinge, Made in USA! Description 1936-38 1939 | | 44.50 44.50 |
| | CB227 | • Glovebox I Part No. CB420 CB227 | _ock and Key Description 1936-39 Doesn't use a locking cylinder or key, chrome 1940-46 With lock and key | | 32.50 26.95 |
| | | • Glovebox I Included in C Part No. CB131 | _atch Hook With Slide B227. Description 1940-53 | set | 5.00 |
| | 1 | • Glovebox I Part No. CB232 | Bumpers Description 1940-72 Black rubber | pair | .95 |
| | | • Glovebox I Part No. CB133 | _ight Description Universal type, with socket and pigtail wiring | each | 15.95 |
| | THE INC. | Gas Filler I | R NECK GROMMETS Neck Grommets ody hole where gas neck protrudes. Description 1934-36 Panel and Suburban | each each the four hole tages each er | 12.50 11.90 15.95 11.75 e metal 9.50 6.50 |
| | | | - · · · | | _ |
| | | | | - I | |



| | V | | |
|----------|--------|--|--------------------------------------|
| | А | STEERING COLUMN COMPONENTS | |
| Z'N Y | | Steering Wheel, New The correct steering wheels for the 1941-46 Chevrolet/GMC trucks! They are just like made in black for the 1941-45 or brown for 1946. Other than color they are the sa Part No. Description CB508 1941-45 Blackeach CB508BN 1946 Brown as per originaleach | originals me. 174.00 174.00 |
| | Combo! | Steering Wheel, Combo When your truck lacks the total steering wheel and horn parts, We can help. This includes the steering wheel, horn button retainer, horn button, horn button retainer and horn button coil spring. Part No. Description CB519 1941-45 Combo with black steering wheeleach CB518 1946 Combo with brown steering wheel | bumper, |
| | | • Steering Wheel Nut Part No. Description CB204 1936-46each | .65 |
| | | • Steering Column Clamp Rubber Bushing Part No. Description CB162 1934-46each | 1.95 |
| | | • Steering Column Metal U-Clamp Threaded ends. Secures column to underside of dash. Part No. Description CBS165 1936-40each CBS166 1941-46each | 21.50 21.50 |
| | | Horn Button Assemblies, Metal Button Part No. Description EL119 1929-40 With rubber retainer and securing "S" wireset EL204 1941-46 With threaded stud, base plate, and securing wire spring. Available July 2013set | 21.50 23.95 |
| | | • Horn Bracket Secures original horn to intake manifold. Part No. Description EL336 1937-52each | 19.50 |
| | NEW! | Horn Button Retainer The die cast three fingers extend through the steering wheel hub and holds the hole EL204 in place. Part No. Description EL422 1941-46 Chevy/GMCeach | rn button 29.00 |
| | | Horn Button Cup, Metal Fits in center of steering wheel and holds horn components. Mirror polished stainle edge and zinc plated steel lower cap just like original. Part No. Description EL200 1931-40each | ess outer 19.95 |
| | | | |



| 0 | Horn Button Retainer Bumper Fits below steering wheel. 2 1/4" diameter rubber. Part No. Description EL423 1941-46each | 4.75 |
|--------------------------|--|--|
| | • Horn Button Coil Spring Keeps pressure on horn button. Touches top of steering wheel. 1 1/8" diameter. Part No. Description EL201 1941-46each | 1.95 |
| EL107 | Steering Mast Bearing, Upper Fits at top of steering column below steering wheel. Includes the insulated wire t through the mast jacket to harness. Part No. Description EL107 1931-40 correct bushing (Made in the USA)each EL155 1941-46 correct bearingeach NOTE: Other Steering Parts Available in Mechanical Section. | hat goes 49.00 22.50 |
| Stop Sbody noise W | CAB MOUNT KITS, All made in the USA.• Cab Mount Kits"Complete" with specialized bushings, washers, bolts, blocks, springs, cylinders aPart No.DescriptionCBK1531931-35 High cab (special custom made parts)kitCBK1541936-38 Low cab (special custom made parts)kitCB2051939-46 Pickup and Large TruckskitCBK1551939-46 Panel and Suburbankit | nd pads. 129.95 129.95 74.50 64.50 |
| | • Wood Blocks, Floor Rail Connects cowl assembly to cab side rails at floor. Shaped and drilled as original. two blocks with the proper six tapered machine bolts. Made in the USA! Part No. Description CB206 1934-46 | Includes 11.90 |
| | • Wood Blocks, Cab Mount Fit at rear under cab. Part No. Description CB247 1936-46 (included in CB205)pair | 7.95 |
| | MISCELLANEOUS CAB ITEMS• Clutch Head ScrewsBlack interior screws. Approximately 100 items.Part No.DescriptionCB1011934-46 Chevrolet | 24.50 |
| | Header Panel Fits above windshield in cab interior and has holes for left and right windshield wiper mot Touches front edge of headliner board. Part No. Description CBH151 1936-38 Fiberglass | or plates. 145.00 145.00 |



| \mathbf{v} | | |
|-------------------------|--|--|
| CBH156 CBH157 CBH159 | Header Panel Wiper Cover Plate These wiper motor access plates nicely replace those that are often rusted out or Attach to CBH151, CBH155 or your original metal panel. Part No. Description CBH156 1939-46 Left, with indention, fiberglass | missing. 19.75 19.75 19.75 24.95 |
| | Seat Cushion Rails Secures bottom cushion. Attaches above gas tank on seat riser. Part No. Description CBS304 1939-46 Set of 4set | 39.50 |
| | • Seat Bumpers Protects rear of cab from upper seat frame. Part No. Description CBS309 1936-46pair | 4.50 |
| A State | • Dash Trim These three horizontal strips are usually rusted beyond repair. We made them with over stainless steel. Show quality. Even includes the nine twist clips to secure ther dash. Sold in a set of 3 strips. Installs easily. Part No. Description CB635 1940-46 Chrome Available Dec.2014set | h chrome m to your 74.95 |
| ß | • Dash Trim Clips Secures the horizontal dash trim. Hand made! Part No. Description TRC116 1940-46 (Included in Trim Set CB635)each | 2.00 |
| | <section-header></section-header> | |

DECALS



| CHEVROLET | The same de | ales and Service Sign ecals used on our MS102 and MS103 signs. Use on windows, your o rproof vinyl approximately 11-3/4" diameter. Just like displayed in dea Description Chevroleteach GMCeach | |
|-----------------------------------|--|--|------------------------------|
| Restoration Parts | • Decals, Mi Weatherprod | niature Service Sign of vinyl approximately 3" diameter. One of each - Chevrolet and GMC ur own signs, etc. A miniature of DE101 and DE102 above. Description Miniature decals | C. Use on |
| | Weatherproo • Chevrolet Approximate Part No. DE104 | Block Letters ely 1" x 8-1/4". Description Black decalseach | 2.75 |
| <u>M</u> Restoration Parts | • GMC Fame Approximate Part No. DE106 DE107 DE108 | Red decalseach ous Script ely 2" x 7-3/4". Also fits 1947-55 hubcaps. Description Red decalseach White decalseach Black decalseach | 4.50 2.75 2.75 2.75 |
| GM Restoration Parts | | GRILLE ers and horizontal line indentions on the factory grills. No need to h aterless stick-on type. | and paint |
| Chevrolet CHIVROLLT | • Chevrolet Part No. DE236 DE234 DE235 | Description 1939 Red letters and strips (upper grill bar)set 1940 Red letters and strips (upper grill bar)set 1941-46 Red letters and strips (upper grill housing)set | 14.50 |
| GM Restoration Parts | | FAILGATE of decals in exact size and shape as letters on stamped tailgates. Als lem plain tailgates. 3" x 24" long. | o fits well |
| Chevrolet | • Chevrolet Part No. DE116 DE117 DE118 | Description 1939-40 Black rolling scripteach 1939-40 White rolling scripteach 1939-40 Chrome rolling scripteach | 9.05 9.05 12.45 |



DECALS

| GM Restoration | <pre>DECALS, TAILGATE (continued) • GMC</pre> | |
|--|--|----------|
| <u>GYC</u> | Part No.DescriptionDE1271936-46 Black rolling script (does not include oval)each7.0 | 00 00 |
| VALUES | REPRODUCED FACTORY ORIGINAL DECALS For the perfectionist wanting his truck very authentic, we have reproduced the followin decals for mechanical items. They are exact! Made from factory original samples. All a waterless Mylar material. | |
| Ac Bark Pug Fu Mode and the Cleaner of the Cleaner | | 50 50 |
| <image/> | • Decals, Oil Filter Exact colored waterless decals plus cartridge restoration instructions. The six cylind cartridge housing is secured to intake manifold with two U-bolts. Fram Type - For use on the more popular aftermarket six cylinder oil filter assembly. Beauti 4-color waterless decals to perfectly detail the filter unit. Includes the three decals. Note: Fram uses a corrugated cone bottom. Part No. Description DE216 All yearseach 4.9 | |
| | AC Type - Exact as used on the filter assembly installed by General Motors dealers of trucks. Exact two color, waterless decal. Attaches to lid and cannister. Note: AC uses a smooth cone bottom. Part No. Description | |
| NOTICE THIS TRUCK EQUIPPED WITH TWO SPEED AXLE CONTROL LEVER IN REAR POSITION FOR STARTING, LOW SPEED AND HILLS CONTROL LEVER IN FORWARD POSITION FOR OPEN ROAD OPERATION, SPEED AND ECONOMY | Decal, Rear Axle Part No. Description DE228 1934-46 2-speed rear axle decal. Attaches to dasheach 3. Decals for speedometer and gauges - See Speedometer and Gauge Section | 70 |
| | | |

DOORS AND COMPONENTS



| 00 | DOOR COMPONENTS Image Half • Door Hinge Half We have made the wearing part of the 1934-38 door hinge, This turns on the hinge pin. Attaches to door post on cab. The attaching holes can be easily modified to fit the 1934-36 high-cab. Includes correct door pin DP112. Part No. Description DPH119 1934-38 upper and lower, right and lefteach 29.95 |
|----|---|
| | • Door Hinges We have produced authentic door hinges for the 1939-46 cabs. Most originals are worn or rusted beyond repair and after 60 years the bolts are ruined when removed. These will exactly replace your damaged hinges. Includes mounting bolts and hinge pins. (Reverse the hinge pin to make them right or left. Part No. Description DPH120 1939-46 upper |
| | • Door Hinges, Panel and Suburban (Rear) The upper and lower, right and left are all the same. We have them in stock with pin and fasters (Reverse the pin to use them on left or right.) Part No. Description DPH121 1936-38 Panel/Suburban complete rear door hingeeach 39.95 |
| | • Door Hinge Bolts When you want to use your original hinges these bolts should be of interest; Part No. Description DPH112 1934-36 Door side of hinge. Oval head, "Standard threads" and hex nuts, 3/4" longeach 1.45 DPH113 1934-36 Cab post side of hinge. 1 3/4" long. Nuts included which anchor to vertical door post woodeach 1.45 DPH114 1937-38 Cab post side of hingeeach 5.95 DPH125 1939-46 Door side of hinge. Oval head, "fine threads"each 1.45 DPH123 1939-46 Cab post side of hinge. Oval head, "fine threads"each 1.95 DPH124 1939-46 Panel and Suburban. Side by side rear door hinge bolts. longer than side door, "fine threads"each 1.70 |
| | • Door Patch Panels Part No. Description These hand rolled and formed panels nicely replace your rusted out door skins. Includes the three right angle edges to bend over your door frame. The shorter panel will repair the spotted rust on the door bottom edge if all else is good. Professional installation recommended to insure a perfect final appearance! NOTE: Welding panels without warpage is difficult for an amateur! Hand made in the USA! Part No. Description SMD146L 1936-38 left, approx:6" higheach 55.00 SMD146R 1936-38 right, approx:6" higheach 55.00 SMD147L 1939-46 left, approx:6" higheach 55.00 SMD147R 1939-46 right, approx:6" higheach 55.00 SM308L 1936-38 Left, extends to under door trim belteach 98.00 SM309R 1939-46 Left, extends to under door trim belteach 98.00 SM309R 1939-46 Right, extends to under door trim belteach 98.00 SM309R 1939-46 Right, extends to under door trim belteach 98.00 SM309R 1939-46 Right, extends to under door trim belt |

| Carter Carter Truck Parts | DOORS AND COMPONENTS <i>visit our website for SPECIAL savings!</i> | 5 |
|---------------------------------|---|-------------------------|
| | | |
| | Door Handles Finally after 50 years these are available. Identical to the original GM handles. Show o Outside, Non-locking style Part No. Description | quality! . |
| DPH105 | DPH117 1934-38 Chrome as originaleach DPH105 1939-46 Chrome as originaleach DPH105NC 1939-46 Non-chromeeach Inside | 39.50 37.50 29.00 |
| DPH100 DPH118 | Part No.DescriptionDPH1181934-38 Chrome slider threaded knob. Like GM made them!.eachDPH1011939-40 Chrome as original, small endeachDPH1001941-46 Chrome as original, large endeach | 29.50 38.50 38.50 |
| NEW! | • Door Handle Lock and Key Fits below handle on right door. Just like GM! Includes gasket. Part No. Description DP469 1942-46 includes 2 keyseach | 49.50 |
| | Door Handle Ferrules Includes high shine stainless ring and rubber seal. Part No. Description DP110 1929-37 With inside rubber sealeach | 9.50 |
| DP110 DP111 | DP111 1938-46 With outside rubber sealeach | 8.90 |
| | • Door Handle Ferrule Tool Critical for installation of the above ferrules. Part No. Description DP102 1929-46each NOTE: 50% of DP102 cost is refundable with a gift certificate towards parts! | 34.50 |
| WIB204 🔮 | Door Handle Retaining Screw as Original, Correct Headsize | |
| | Part No.DescriptionWIB2041939-46 Inside door handleeachDPH1031936-46 Secures outside door handle. (plus spacer)each | 3.90 4.50 |
| | • Door Handle "Anti-droop" Spring Fits in latch. Helps keep exterior door handle in horizontal position. Made in the US Part No. Description | SA! |
| | DP146L 1939-46 lefteach DP146R 1939-46 righteach | 4.50 4.50 |
| | • Door Weather Seal - Panel and Suburban Black sponge rubber. Fits around door edge. The best available. Glues in place. | |
| | Part No.DescriptionDP1361936-66Panel and Suburban, rear doorspair | 34.50 |
| Adhesive and against | • Door Rubber Seal Adhesive Quality 3M special black glue. Part No. Description DP120 Door adhesiveeach | 10.25 |
| | Door Striker Plate Part No. Description DP126 1936-46 Left or righteach | 9.75 |
| QO | • Door Handle Inside Repair Springs Part No. Description DPH106 1939-46 behind door panel. Returns it to correct position Pair | 9.95 |
| ²⁴ oldchevytr | rucks.com ORDERS 1-800-862-1913 TECH HELP 2-4pm 1-816-25 | 2-5857 |

DOORS AND COMPONENTS





| | | cks or Stops DPD107, (6 1/2" long) | |
|-------------------------|--|---|-------------------------|
| DP137 | Part No. DPD107 DP131 DP137 | Description ⁹ ⁹ ⁹ ⁹ ¹⁹ 1934-36 Leather strap with both metal bracketseach 1937-38 Spring steel bracket with pin and rubbereach 1939-46 Spring steel bracket with pin and rubbereach | 19.50 24.95 24.95 |
| | • Door Chee Part No. DPD108 | ck Bracket, Made in the USA. Description 1939-46 Welds to door interior. Attaches to DP137each | 17.50 |
| | • Door Bum Part No. DP808 | Description 1936-46 Exact duplicates. 8 Pieces. (For both doors)set | 16.50 |
| | Tooling is co | etail Bumper Stops mplete on the 2 rubber bumpers and the 2 metal shoes. The more import our door secure when it is in the closed position. Just like original. Description 1933-46 Fits in door post. 2 pair required per truckpair | ortant part 22.00 |
| | These are e | etail Wedge Plate exact as original. Holds door correctly in place on the rear of post on on nals. Works best with DPD109 above. Description 1934-46 Spot weld on the dooreach | door. Just 14.95 |
| | • Door Hing Part No. DP112 DP135 | | 2.50 2.75 |
| | | ber Hinge Seals, Rear Suburban with side by side rear doors. Description 1936-59 (4 per set)set | 13.95 |
| SE | • Door Lock Small chrom Part No. DP129 DP138 | K Knobs ne T-handle for inside of left door. Description 1934-40 3/16" Square holeeach 1941-46 1/4" Square holeeach | 11.50 11.50 |
| 0 | • Door Lock Part No. DP176 | Gasket Description 1942-51 (Included with door lock DP469)each | 1.25 |
| | | h Connecting Link nk inside door. Connects latch to inside handle. Made in USA! Description 1934-36 High cab, With threaded hole, 13" longeach 1936-38 Low cab, With threaded hole, 11 11/16" longeach 1939-46 (11 1/2" long)each | 29.75 29.75 10.90 |
| | | DPD120 DP264 and DP265 | 9 |
| URDERS 1-800-862 | -1913 TECI | HELP 2-4pm 1-816-252-5857 oldchevytrucks.com | n 25 |



| visit | our w | ehsite | for | SPEC | IAL | savings! |
|-------|-------|--------|------------|------|-----|----------|
| | Uui w | CUSILC | jUI | | | Juvings |

| | SWITCHES • Dash and Courtesy Light Switch Finally after 60 years! We are making an exact copy of the original 3 position limited quanities for under the dash. Just like GM made them. The receiving under the dash of all 1940-46 Chevrolet/GMC trucks. Operates the map at lights. 6 or 12 volts. Part No. Description EL157 1940-46 Under dash, light switch. | three ho nd dash | oles are |
|---------------|--|---------------------|------------------------|
| | Dimmer Switch Part No. Description EL101 1936-54 | each | 13.95 |
| of the second | Headlight Switch With Rheostat Control Good replacement. Disregard the rheostat on this unit as originally they were not used . The unused rheostat is not visible behind dash panel. Part No. Description EL104 1936-46 6 volt, Universal type no rheostat EL1491 1936-46 12 volt. | | 19.50 19.50 |
| | Heater Blower Switches Secures under dash with included mounting bracket. Rheostat type with light Part No. Description EL117 6 volt EL118 12 volt | each | 18.00 13.95 |
| | Starter Switches For six cylinders with foot operated linkage. Part No. Description EL202 1934-37 (Limited quanities.) EL102 1938-54 | | 28.45 13.75 |
| | • 1937-55 Rear Panel Truck/Suburban Door Taillight Switch Prevents taillight from operating with doors open. Impressions are in door and to GM. Part No. Description EL409 1937-55 | - | dentical 69.50 |
| | Starter Solenoid Attaches to top of a Powerglide starter when using a car "push button on da Part No. Description EL216 6 volt EL217 12 volt | each each | tem. 38.00 13.75 |

26 oldchevytrucks.com ORDERS 1-800-862-1913 TECH HELP 2-4pm 1-816-252-5857



| Stoplight Switches With snap on terminals. Check your master cylinder for the type you need. Part No. Description EL152 1936-42 Hydraulic type (threads into master cylinder) EL106 1936-55 Mechanical type (attaches to toeboard) | | 13.50 8.95 |
|---|----------|----------------|
| COILS• Ignition Coils, When you don't have the original type.Part No.DescriptionEL1436 voltEL14212 volt | | 28.50 26.50 |
| Ignition Coils This item is a traditional round 12 volt coil with a built-in reducer. Eliminal outside reducer EL181 when changing to a 12 volt system. Includes mount Part No. Description EL158 1955-72 Resistor ignition coil | ting bra | |
| VOLTAGE REGULATORS AND CUT-OUTS, ETC.• For GeneratorsAttaches to firewall, as original.Part No.DescriptionEL1401940-55 Chevrolet 6 volt, negative ground | each | 69.00 |
| Generator Cut-out, Universal Used prior to voltage regulators. Attaches to top of generator. Not exact in a Part No. Description EL139 1929-39 | | nce. 41.00 |
| Generator CutOut Repair Kit If you are fortunate to have the original rectangular Delco-Remy cut-out, v make it work better then new. We provide high-tech diode and instructions. T is hidden inside your Delco-Remy cut-out. Part No. Description EL136 1929-39 | | addition |
| | | |



...visit our website for SPECIAL savings!

| | Drops 12 volt current to 6 volt. Place in line to 6 volt accessories if you convert to a 12 volt system. Part No. Description EL181 Medium duty, keeps the necessary 6 volt current to ignition pointseach 14.75 EL135 Heavy duty, for accessories such as radio or heatereach 19.95 EL10 Light duty, for gas gaugeeach 3.25 EL311 Light duty, for gas gauge from 12 volts, but on some applications it does not give totally accurate readings. This one amp "Runtz" voltage reducer (EL311) gives exact readings by otherwise good gauges. Negative ground only. |
|---------------------|--|
| | VOLTAGE BOOSTER, 6 to 12 VoltsWill operate 12 volt negative ground accessories from 6 or 8 volt negative ground electrical systems. This booster is very small (3-1/2" x 2-1/8" x 1-5/8") and is easily mounted under dash. It can continuously supply about 1-3/4 amps, which is adequate for small stereos, CB radios, cellular phone chargers, radar detectors, etc. One year warranty.Note:Will not work with positive ground systems.Part No.DescriptionEL219Voltage booster for 6 volt systems |
| EL146 C EL113 | MISCELLANEOUS ELECTRICAL ITEMS *• Ground Straps (Six Volt Vehicles need two ground straps) Open braided flat strands as original. Plated to resist corrosion! Part No. Description EL146 1934-55 1st Engine to frame (12")each 9.00 EL113 1934-55 1st Battery to frame (14")each 12.00 |
| | *• Battery Cable, (27 1/4") These are the heavier gauge battery to starter style. Necessary for 6 volt systems. We have EL114 covered with an original cloth braiding so they are show quality. Part No. Description EL114 1934-46 Original style, coth coveredeach 38.00 EL427 1934-46 Vinyl covered replacementeach 18.50 *Important: The 6 volt system must have much more grounding than a 12 volt. On Chevrolet for example, two ground cables and one oversize positive cable are required! |
| | Battery Positive Cable Clip Secures (EL114 and EL427) Chevrolet battery to starter switch cable to frame rail. Part No. Description EL407 1941-54each 2.95 |
| | • Battery Ground Cable Clip Holds original woven braided cable away from starter rod coil spring. Attaches to bell housing top bolt. Made in USA! Part No. Description EL425 1941-53each 4.95 |



| | MISCELLANEOUS ELECTRICAL ITEMS (continued) | |
|----|--|------------------------|
| | Wire, Cotton Braided Use for replacing sections of your original harness. (Sold per foot.) Part No. Description EL18014 14 gauge cotton braided covering as originalfoot 1. | 10 |
| | 5 (5) | 55 25 |
| | • Terminal Blocks Fits on each inner fender. Connects headlight wires to main harness. Part No. Description EL137 1937-53 Two 3 position blockspair 18. | 75 |
| | Spark Plug Wires (Includes coil wire) These are custom made with proper ends and lengths for each type engine. Select these we sets when you expect the best on the market. They are not just "get by" universal wire set (The inside has a carbon core to protect a radio from iginition noise.) Chevrolet and GMC Part No. Description EL130 1934-53 Black wires with correct open metal ends | ets. 50 95 95 |
| 00 | Rubber Rings for Spark Plug Wires Part No. Description EL147 For holding spark plug wires as original, included in EL130pair 1. | 95 |
| O | Firewall Wiring Loom Grommet Protects main wiring loom as it passes through sheet metal firewall. Part No. Description FP129 1936-59each 3. | 25 |
| | Taillight Wiring Grommet Fits in the frame hole near taillight to protect wiring. Part No. Description LG1061 1940-72pair 2. | 75 |



...visit our website for SPECIAL savings!

WIRING HARNESSES, COTTON

For the two most popular harnesses we can provide original appearing cotton covered wires. These look just like the originals 70 years ago. Separates the mens from the boys in shows. Made in USA!

Part No. Description ELW102 1936 Chevrolet for generator cutout with voltage regulator each 600.00 1934-39 Chevrolet for generator cutout,w/o voltage regulator...each ELW104 600.00 ELW108 1940 Chevrolet for voltage regulator.....each 600.00 ELW109 1941-46 Chevrolet for voltage regulator.....each 600.00 ELW109G 1941-46 GMC.....each 755.00 **Note:** ELW104 harness is for the truck with a correct voltage cutout on the generator. No voltage regulator. WIRING HARNESSES, PVC

A complete quality wiring harness using the modern PVC coated copper wire. Made in USA! These are close to original harness, however some modifications may be required to fit your truck (for example: length of wire because of bed length or connector changes). These changes are not complicated and are easily modified with the harness installed in the truck.

Part No. Description

ELW3439 1934-39 Chevrolet and GMC with generator cutouteach 235.00 1940-46 Chevrolet and GMC with voltage regulator.....each 235.00 ELW4046 Note: If your 1934-39 truck has been converted to a voltage regulator (instead of the generator cutout) the ELW4046 is more appropriate. Made in USA!


For Trucks With Alternators Part No. Description

| r art NO. | Description | |
|-----------|-------------------------------|--------|
| EL128 | 1934-39 Chevrolet and GMCeach | 235.00 |
| EL168 | 1940-46 Chevrolet and GMCeach | 235.00 |

Ρ Ε



| Part No. | • | | |
|-------------------------|-----------------------------|------|------|
| ELW46 | 1942-46 | each | 9.95 |
| • Wiring Ha Part No. | arness Clips Description | | |
| | • | | |
| EL175 | Fits all years | each | 1.75 |
| | - | | |



oldchevytrucks.com 30 ORDERS 1-800-862-1913 TECH HELP 2-4pm 1-816-252-5857



| r O | ALTERNATOR CONVERSIONFor those wanting the more modern alternator. This part dapts our Type #2 wiring hwith generator to an alternator. Will also work with your original generator harness.Part No.DescriptionELW1221934-62 Alternator conversion harnesseach | |
|-----|---|--|
| | TURN SIGNAL KITSThese kits are designed to fit behind the dash out of sight and do not clamp on so column. Only a toggle switch lever is seen below dash. A beep-beep from behind indicates that the signal is flashing. This keeps a more original dash appearance, and allows for this convenient accessory. Includes wiring, double filament sockets, switch stoplight bulbs! This kit can be made to operate original park lights or custon American made. Top quality!Part No.DescriptionEL13166 volt6 voltsetEL1311212 volt | nd dash and still witches, ent from |
| | • Turn Signal Lever Assembly Clamps on steering column. For those wanting a visible lever at the side of steering of Part No. Description EL13312 Seven wireseach | column. 24.95 |
| | • Turn Signal Flashers Part No. Description EL1762 6 volt, 2 prongeach EL1763 6 volt, 3 prongeach EL1772 12 volt, 2 prongeach EL1773 12 volt, 3 prongeach | 14.50 14.50 10.75 10.75 |
| | At this Sign | |
| | FRIENDS MEET FRIENDS | |



| \mathbf{v} | | |
|--------------|---|-------------------------|
| NEW | FLOOR MATS• High Quality Molded Rubber Floor MatWe just made with our own new tooling. You will like these mats! Use with felt pad FL1Part No.DescriptionFL1011941-46 3 and 4-speedeach11Note: Our mat has perforations on the back side to help make openings for pedals and lever. If it is for a non-original truck, the mat can remain without holes. | 15.00 |
| | Floor Mat Rubber Material Cut your own shape to make an excellent pebble grain rubber mat. Good if your year not reproduced. Simply make a paper pattern and cut this shape on the mat material. Enough material for one cab floor. Part No. Description FL147 Per truckeach 6 | |
| 6 - 1 - 1 | Floor Mat Felt Pad Helps reduce engine heat and road noise in cab. Fits under floor mats. Part No. Description FL107 1934-55 1st 36" x 54"each 1 | 14.50 |
| FL130 | FL112 1938-40 1/2 and 3/4 ton (can fit 1941-42)each 2 FL130 1943-46 1/2, 3/4, 1, 1-1/2, and 2 ton. | 23.50 26.95 26.95 |
| | • Accelerator Felt Floor Seal Fits in the factory metal floor pocket. Part No. Description FL111 1941-59each | 3.50 |
| FL109 | 5 | 27.00 14.00 |
| FL155 | Brake and Clutch Floor Seals Part No. Description FL233 1929-High cab 1936 Brake and clutch floor grommetspair FL155 1941-46 Seals steering column, brake and clutch at floor on toeboardeach | 19.00 7.50 |
| | | |



| 0 | STEERING COLUMN SEAL • Steering Column Hard Rubber Floor Seal Seals air leaks around column at floor. Part No. Description FL151 1934-46 3 and 4-speedeach | 10.00 |
|----|--|-------------------------|
| | BATTERY RELATED• Battery Floor Hole CoversRemovable metal plate in floor, when servicing battery. Made in the USA.Part No.DescriptionFL1601936-38 (4 3/8" x 7 3/4")eachFL1491939-46 (4 3/8" x 10 5/8")each | 19.75 19.75 |
| | • Battery Tray Assembly, Made in the USA Part No. Description FL185 1937-46 With sides and the 2 long carriage boltseach | 65.00 |
| | PARK BRAKE BOOT AND FOAM COLLAR• Park Brake Foam CollarFits between brake lever base and floor plate to stop air leaks, 1934-47. Also larger1948 and newer having vertical hand pull lever.Part No.DescriptionFL1381934-59each | r trucks, 4.75 |
| §. | • Park Brake Boot Boots were not originally used by GM on early trucks, however, this is a nice extra. Part No. Description FL164 1934-59each | 5.90 |
| | FLOORBOARD SECTIONS, WOOD• Floorboard and ToeboardPlywood as original including proper holes, cuts, tapers, and thickness. Made in ouPart No.DescriptionFL1981934-35 Floorboard, 3 speed High cab, square cornerseachFL1991934-36 Toeboard High cabFL1971936 Floorboard, 3 speed Low cab, rounded cornerseachNote: At printing time, we had the pattern for a 3 speed transmission only. You mustthe shift hole if your truck has a 4 speed. | 46.00 46.00 46.00 |
| | • Floorboard and Toeboard Screw Set Part No. Description FL145 1939-46set | 7.95 |



...visit our website for SPECIAL savings!

FLOORBOARD SECTIONS

| | LOORBOARD SECTIONS | |
|----------|--|--|
| | Floorboard and Toeboard Sections - Metal New on the market ! Made in the USA in original gauge metal. Fits just right. Part No. Description FL301 1936-38 3-speed transmission, floorboardeach 12 FL302 1936-38 4-speed transmission, floorboardeach 12 FL303 1939-40 3-speed transmission, floorboardeach 12 FL304 1939-40 4-speed transmission, floorboardeach 12 FL305 1941-46 3-speed transmission, floorboardeach 12 FL306 1941-46 4-speed transmission, 1/2 ton, floorboardeach 12 FL307 1941-46 No holes for master cylinder, battery or shift lever. floorboard (street rod type floor)each 12 | 25.00 25.00 25.00 25.00 25.00 25.00 25.00 25.00 39.95 above |
| | Floorboard Sections - Fiberglass Tough black fiberglass to replace your rusted-out unit. Made in the USA Part No. Description FL153 1941-46 3-speedeach 8 Note: Cut 3" diameter hole for master cylinder floor cover. | 86.50 |
| | Floorboard and Toeboard Screws Secures the metal floor and toeboard to body. Zinc plated steel. Made in USA. Part No. Description FL145 1939-46 (21 Pieces total)set | 7.95 |
| 2 Styles | MISCELLANEOUS FLOOR PARTS • Starter Boot Stops air coming into cab around starter rod. (See help page in back of this book.) Part No. Description FL110 1934-38 1 3/4" Tall (Limited production)each FL117 1939-57 3" Talleach | 19.00 5.50 |
| | Starter Rod Felt Floor Seal Part No. Description FL118 1934-46each | 3.75 |
| | Master Cylinder Floor Hole Cover Part No. Description FPF130 1936 Low cab-46 Rounded all metal plug, as originaleach | 11.50 |
| Centro | Running Board Bolt Kits Includes special flat top step carriage bolts. Part No. Description FL128 1936-55 1/2 and 3/4 ton pickup or larger truckkit FL129 1936-55 1 ton pickupkit | 9.95 10.50 |

| • Running Board to Fender Gaskets Part No. Description FL240 1939-40 1/2, 3/4, 1, and 1-1/2 ton front fenderspair 15.9 FL225 1941-46 1/2, 3/4, 1, 1-1/2, and 2 ton front fenderspair 15.9 | |
|---|----|
| Floor Shift Boots Boots were not originally used by GM on early trucks, however, this is a nice extra. Part No. Description FL165 1934-47 3-speed and 1936-66 4-speed not originaleach 8.5 | 50 |
| Floor Shift Foam Collar Fits between transmission and floor plate. Stops air leaks around 4 and 3-speed floor shifter. Originally used instead of a boot. Part No. Description FL137 1934-65 4-speed and 1934-47 3-speed floor shiftereach 6.9 | |



| (Cancer V | FRONT PARTS | | |
|---------------------------|---|--------------|---|
| Truck Parts | visit our website for SPECIAL savings! | | |
| FPF104 \ FPF108 FPF109 | Front Splash Apron - Metal Part No. Description FPF104 1941-46 Chevrolet, Hand Made! Show Quality. Made in USA! "The Best" FPF109 1941-46 Chevrolet, Hand Made! Show Quality. Made in USA! No bumper brace holes, FPF108 1941-46 Chevrolet, Imports. Fits and looks good, with the 2 holes. Not made in USA! | each | 275.00 245.00 179.50 |
| FP150 FPF106 | Front Splash Apron - Fiberglass - Made in the USA! Fits below grille. Part No. Description FP150 1941-46 Chevrolet FPF105 1941-46 GMC FPF106 1941-46 Chevrolet, No bumper brace holes, | each | 78.50 78.50 78.50 |
| | • Front Splash Apron Support Brackets. Made in USA! Extra support between the front splash apron and lower filler pan. 9 1/2" lo Part No. Description FPF107 1941-46 Chevrolet | U | e GM. 19.50 |
| FP176 | BUMPER BOLTS, NUTS, ETC.• Bumper Bolts - ChevroletPart No.DescriptionFP1761931-36 With large oval head, nut, and washer (polished stainless) 3 1/2" inches highFP1731931-36 Bumper end eye bolts, nuts, and washers (polished stainless)FP1061937 With rounded chrome head as originalFP1071938-46 With oval head as original with nut and washer (polished stainless cap)FP107A1938-46 FP107 sold in a set of 5 | pair each | 21.95 36.50 2.75 6.50 29.50 |
| FP176 FP106 | • Bumper Bolts - GMC Part No. Description FP176 1936-38 With large oval head, nut, and washer (stainless) FP106 1936-46 With rounded chrome head as original | each | 21.95 2.75 |
| | Bumper Bolt Nuts Part No. Description FP210 For use with FP106 bumper bolts FPF211 Marsden style has original slots in sides. For FP106 Note: For the perfectionist:The slotted Marsden nuts came on early trucks | each | .20 3.95 |
| 36 oldchevyt | Bumper Brace Rubber Covers Part No. Description FP228 1941-46 Fits over brace openings in front splash apron below grille rucks.com ORDERS 1-800-862-1913 TECH HELP 2-4pm | | 12.75 252-5857 |
| 36 oldchevyt | | | |



...visit our website for SPECIAL savings!

FIREWALL RELATED ITEMS

| | Note: Betwe | overs erglass reproduction interior cover with nice grain. Includes insulating fir een 1936-46 firewall covers were not originally used. However, these are neat and noise in the cab. (See "cab related" section for total cab insula Description 1936-46 Chevrolet and GMCeach | excellent |
|--|---|--|--------------------------------------|
| and the second sec | • Firewall C | RELATED ITEMS over Retainers hat secure the above cover pads to inner firewall. Description 1936-46each | 1.65 |
| FP101 FP101 FP183 FP129 | • Grommets Part No. FP101 FP171 FP183 FP104 FP129 | 5, Firewall Description 1934-46 4-hole firewall grommet for cableseach 1936-46 Ignition switcheach 1936-59 Speedometer cableeach 1936-59 Starter wire or vacuum hose grommeteach 1936-59 Wiring loomeach | 5.00 5.75 1.75 1.00 3.25 |
| <image/> <section-header><image/><section-header><image/><image/><image/><section-header><section-header></section-header></section-header></section-header></section-header> | November 2 have the out | hevrolet Dur 1934-35 and 1936 Chevrolet Grilles and Inserts are New on the 014! After 75 years, we had them made and they fit just right. Completer ter surrounding ring and center vertical with crank hole opening. The our outer surrounding ring and is good if you do not want a crank hole Description 1934-35 Complete Grille with the surrounding welded on frame and vertical center bar. High polish stainless. Just like GMeach 1934-35 Insert. High polish stainless. Shaped just like GM. If you are adding the original lower crank hole, use FP662 or FP663each 1936 Complete Grille with the surrounding attached support and vertical center bar. High polish stainless. Just like GM. If you are adding the original lower crank hole, use prP662 or FP663each 1936 Insert. High polish stainless. Shaped just like GM. If you are adding the lower crank hole, use part FP662each 1937 Polished stainless steel | ete grilles insert is opening. |



٨

FRONT PARTS

...visit our website for SPECIAL savings!

GRILLE Related Items

| NEW! | Chevrolet Grille Bar Top quality. and approval given by General Motors for authentisity. Stamped Chevro just like original. Chrome plated steel with red script letters. Part No. Description FP241 1939 Grille Bar | let letters Inquire! Inquire! |
|------|--|-------------------------------------|
| NEW! | • Grille Divider Trim We have the three trims that attach to the upper part of the large lower section. Inc pair of curved corners plus the narrow 28" horizontal strips with its 11 twist clips. Mirror stainless as original. Show quality! Available December 2014! Part No. Description FP239 1941-46 Grille trim, Set of all 3 (FP234 and FP234C)set FP234 1941-46 Grille curved cornerspair FP234C 1941-46 Grille center divider trim 28" long with twist clipseach | |
| K | • Grille Center Horizontal Clip Secures the horizontal center strip to the grill. Zinc plated. Included in FP239. Part No. Description TRC113 1941-46 center clipeach | 2.00 |
| | • Grille Bar Clips, COE Part No. Description TRC111 1941-46 Chevrolet, cab over engine grille bar clips. Hand made. Zinc plated. Show quality. About 40 requiredeach | 3.50 |
| | • Grille Shells Fiberglass reproduction of the original outer metal housing. Not the grille in Part No. Description FPG546 1934-35 Chevroleteach FPG547 1936 Chevroleteach | nsert. 314.00 314.00 |
| | Chevrolet | |
| | Everybody wants | |
| | one! | |
| | | |

...visit our website for SPECIAL savings!



Crank Hole Cover - Chevrolet

| | Part No.DescriptionFP6631934Chrome | 38.00 39.50 48.50 49.95 49.95 |
|------|---|---|
| | 1937 Grille Parts Part No. Description FP655 Grille top trim, polished stainless as original. Show quality!each FP249 Center vertical strip, stainlesseach FP660 Crank hole cover, stainlesseach *FP246 Side vertical strips, replacement chrome, non-metalpair *NOTE: These side vertical strips (FP246) are flexible chrome non-metal that look vertical to the original GM. | 275.00 45.00 39.50 7.75 ery close |
| | Grille Center Vertical Strips Part No. Description FP249 1937 Chevrolet, stainlesseach FP650 1938 Chevrolet, stainlesseach FP136 1939 Chevrolet, chromeeach FP137 1940 Chevrolet, chromeeach | 45.00 44.00 56.25 56.25 |
| | 1937-38 GMC Grille Bars Recently produced are exact copies of the vertical grille bars for those rare very popul trucks. The 22 gauge metal is just like General Motors made them over 70 years a paint dull silver as original. You can chrome if you wish. Note: Just the length is d 1937 GMC Grille Bars (Check your measurements against 1938) Part No. Description FP260 Center bar, (20 3/8" tall) requires 1 | ago! You |
| | 1938 GMC Grille Bars (Check your measurments against 1937) Part No. Description FP267 Center bar, 21 7/8" tall (requires 1) | 32.00 23.00 21.00 |
| | • 1937-38 GMC Grille Crank Hole Surround The "rare" die cast part near grille bottom. Show quality. Powder coated in correct silver with black strips. Hand made in USA in very limited quanities. Can be made to Part No. Description FP645 | |
| Molt | • 1937-38 GMC Grille Bar Support Rubber Block The necessary rubber cushion that supports the above vertical bars. Very Important to align and cushion bars! Part No. Description FP264 Cushions the 6 vertical grille barseach | correctly 69.95 |



...visit our website for SPECIAL savings!

| | , Grille, Upper Filler Pan - Fiberglass | |
|------------------------|---|--|
| | Fits between radiator and grille. Helps draw air into radiator. Part No. Description FPG551 1939-40each FPG552 1941-46each | 65.50 65.50 |
| | • Grille Guard Made just like the more popular design of the 1930's and 1940's. Smooth chrom pipe with fasteners that attach to front bumper brackets. 16" inches high. Ope the center gives room if you need to crank your engine. Clamps to bumper brackets Part No. Description FP520 1937-46 | n area in |
| FP117 | • Grille, Lower Filler Pan Fits between grille and lower radiator. Quality fiberglass formed to original dim Part No. Description FP184 1937 Chevrolet, dimensions 13-1/2" x 19-1/2"each FP174 1938 Chevrolet, dimensions 12" x 18"each FP162 1939-40 Chevrolet, dimensions 14" x 21"each FP111 1941-46 Chevrolet, dimensions 15" x 37"each | 62.00 61.00 65.00 75.50 |
| | HOOD RELATED ITEMS• Grille, ValanceLower "chin" that is usually damaged or missing on these older trucks. Quality filPart No. DescriptionFP185 1934-35 Chevrolet | berglass. 110.00 105.65 47.70 |
| | Hood Hinge This center hinge holds the two halves together. Part No. Description *FPH110NC 1934-40 Available Dec. 2014!each *FPH112NC 1941-46 Available Dec. 2014!each | 68.50 72.50 |
| Will NEVER RUST! | • Hood Side Panel Hinge Rods Connects side panel to top panel. Stainless to stop rust. Cut rod to exact length. Part No. Description FPH106 1934-46 Stainlesspair | 19.95 |
| E. | Hood Center Hinge Hold-Down Bracket, Rear Part No. Description FP158 1934-46 Chevrolet and GMC, blackeach FP158S 1934-46 Chevrolet and GMC, polished stainlesseach | 11.75 19.95 |
| | • Hood Bumper Set Part No. Description FP112 1937-46 six piecesset | 4.50 |
| | Hood Lace Fits under front or rear of hood on cowl. Part No. Description FP161 1934-36 (woven fabric) rear cowl and radiator shellset FP115 1937-41 (woven fabric)set FP116 1942-46 (molded rubber)set THELE COMP. OPDERS 1 800 862 1913 TECH HELP2 4mm. 1 816 2 | 28.00 22.50 15.50 |

40 oldchevytrucks.com ORDERS 1-800-862-1913 TECH HELP 2-4pm 1-816-252-5857



| T Com | Hood Lace Retainer Clips Part No. Description FP169CH 1942-55 1st Set of 8 clips and 8 clutch head screws, as originalset FP169PH 1942-55 1st Set of 8 clips and 8 Phillips head screws, replacementset | 12.95 8.50 |
|-------------------------|---|---|
| FP634 FP649 FP643 | Hood Strips, Show Quality Polished stainless with red center. (The horizontal strips on hood sides) Note: Retaining clips for Chevrolet if needed are in TRIM SECTION. Part No. Description FP634 1939-40 Chevrolet only | 84.75 92.50 14.95 45.00 ruck. |
| | Hood Corners Protects cowl when lowering hood. Looks like original. Fits in factory holes in hoo Part No. Description FP229 1934-36 Leatherpair FP211 1937-46 Rubber with mounting plugpair | |
| | • Hood Handles Part No. Description FPH102NC 1939-46 Paintable steeleach FPH102C 1939-46 High polished and chromedeach | 14.75 31.90 |
| FP120 | MISCELLANEOUS FRONT PARTS • License Plate Brackets, Front. For 1/2 and 3/4 Ton Beautiful black exact reproduction. Made in USA! Part No. Description FP170 1934-36 Attaches to right side bumper bolteach FP120 1937-40 (includes securing plate)each FP121 1941-46each | 18.50 28.50 23.50 |
| 0 | • Fender Welt, Black A popular non-original extra. Place between fender and bedside. Part No. Description FP124 1934-55 1st Front weltpair FP192 1937-40 Addition to FP124, fits between fender and grill housingpair FP125 1934-53 Stepside pickups. Rear welt. A popular extrapair | 8.50 7.95 16.90 |
| | • Inner Fender Gaskets, Front Part No. Description FPF103 1941-46 Eight piece setset | 16.95 |
| | Fastener Kit - Headlight Bucket to Fender Consists of 16 "J" clips and correct clutch head screws for one truck. Part No. Description FP166 1941-57kit • Radiator Support Pads | 8.50 |
| | Part No. Description FPF102 1941-46 | 7.00 |



| | HIGH PERFORMANCE SPEED EQUIPMENT For those not wishing to go totally original, we offer several high quality items for m dressup and increased performance. Designed for six cylinder General Motors true | |
|------------|---|--|
| 0 | Beehive Oil Filter For the ultimate in deluxe engine dress-up components. Mint reproduction of a mi popular item. For the final detail. Cools and cleans oil. Attaches to six cylinder intake or firewall. For 1941-62 Chevrolet engines. (Not 1958-62 full flow 261 six cylinder Part No. Description HP112 Flat black ribbed center with polished endseach | manifold |
| | Beehive Oil Filter Mounting Bracket | 200.00 |
| | Used with HP112. Part No. Description HP1121 Firewall mounted bracketeach | 21.50 |
| \bigcirc | Beehive Replacement Oil Filter Element Part No. Description | |
| | MEE130 Extra oil filter for HP112each | 9.95 |
| | Engine Bolt Kits These stainless bolt kits add a nice extra to the appearance of your six cylinder C Includes fasteners for oil pan, fuel pump, manifolds, thermostat housing, distributor, six valve cover, water pump, and timing cover. They are available in slotted and hex as or button head for the custom truck. Bolts are labeled to help in installation. Part No. Description HPE200 216 engine, slotted and hex style as originalset HPE201 1954-55 235 engine, slotted and hex style as originalset HPE202 1955-62 235 engine, slotted and hex style as originalset HPE203 216 engine, button head for a custom lookset HPE204 1954-55 235 engine, button head for a custom lookset HPE205 1955-62 235 engine, button head for a custom lookset HPE205 1955-62 235 engine, button head for a custom lookset HPE205 1955-62 235 engine, button head for a custom lookset HPE205 1955-62 235 engine, button head for a custom lookset HPE205 1955-62 235 engine, button head for a custom lookset | de cover, |
| | Air Filter Assembly, Original Style Created to copy the original 6 5/8" dry element design. Looks very close to the factory Fits the original Rochester and replacement Carter YF, not the early Carter W-1 style. To create an even more authentic look, you might consider ordering the copp element, ME238 in our Mechanical fuel Section. Part No. Description ME904 1950-55 with original black topeach ME907 1950-55 with chrome topeach | cast iron |
| | Air Filter with Dry Element, Chrome For the custom truck using the Carter Y-F, and Rochester carburetor. Flat top desig Part No. Description HP120 6-1/2" diameter, six cylindereach HP123 6-1/2" diameter, six cylinder, top plate only for HP120each HP148 14" diameter, V-8each HP149 14" diameter, chrome with Chevrolet letters, V-8each Note: HP120 does not fit the early cast iron Carter W1 carburator. | yn. 29.50 4.95 51.25 67.75 |



| HIGH PERFORMANCE SPEED EQUIPMENT (continued)• Valve and Push Rod Cover (Chrome Steel)Original shape. Oil filler hole on top. Must use a vented oil cap. (See HP111 below)Part No.DescriptionHP2301937-53 Chevrolet 216 and 235 low pressure valve covereach36.00HP2311954-62 Chevrolet 235 and 261 comboset95.95NOTE: HP231 has chrome covers HP232 and HP233, gaskets and chrome oil cap. |
|---|
| Valve Cover, Offenhouser High Performance Made from the original tooling of the 1950's. High polished aluminum. A famous name in early racing!. With Offenhouser lettering. Fits 216, 235, and 261 Chevrolet. Part No. Description HP237 1937-62 Valve cover only.(235 eng.use HP110 stud kit.)each 242.00 |
| Valve Cover Spacers Moves thermostat housing forward to make room for some cast aluminum valve covers. Part No. Description HP535 1937-62 Chevrolet 6 cylindereach 16.50 |
| Valve Cover Stud Kit Necessary for securing the center hole aftermarket aluminum valve covers (Offenhouser, etc.) to the later 235 Chevrolet engines. Also secures original 216 valve covers to the late model 235. Includes stud, acorn nuts, washers and seals. Part No. Description HP110 1937-62set 16.95 |
| Oil Cap, Chrome Part No. Description HP111 1937-62, Valve cover top fill only! Ventedeach 13.95 |
| Fenton Cast Iron Dual Exhaust Chevrolet And GMC Headers Authority given by the original manufacturer to produce these in demand era performance accessories. These cast iron headers are exact in every detail including "Fenton" lettering. The resulting dual pipes on your early pickup will cause that special six cylinder purr, so often heard in past years. Nothing sounds like Fentons on GM six cylinder engines. Note: For GMC minor adjustments are needed see instructions. (See website for further details.) Part No. Description HP102 1937-62 Chevrolet and GMC, 2" diameter outletset 285.00 |
| Fenton Exhaust Manifold Warming Kit For better engine performance when using Fenton Headers on your Chevrolet and GMC inline six cylinder! Our kits allow hot exhaust from the headers to enter into a cavity created by a threaded plate under the original as well as the Fenton and Offenhouser dual intake manifold. Fuel is quickly warmed as it leaves the carburetor as was designed by General Motors. Professional appearance! NOTE: To see this kit installed, check the High Performance Section of our 1947-55 Research Catalog at www.oldchevytrucks.com. Part No. Description HPM544 1937-53 Chevrolet 216, GMC 228,248,270, and 1939-59 302. Kit 59.50 HPM543 1954-62 Chevrolet 235 and 261 engines. |



HIGH PERFORMANCE

| •Exhaust Manifold We are in the process of producing the cast iron single barrel manifold as used on the Chevrolet six cylinder. Just like GM made them. Even includes the heat riser assembly and spring. All in a bolt-on assembly. No dual exhaust system required. Part No. Description MEE326 1950-53 216 and 235 low pressure engine |
|---|
| •Fenton Manifold with Dual Intake Plus Linkage and Fuel Lines Aluminum Fenton dual intake manifold that is a perfect match for the Fenton Headers HP102. Includes accelerator linkage and stainless steel fuel lines. Part No. Description HP107 For late 235 and 261 Chevrolet engines |
| Offenhouser Manifold with Dual Intake Plus Linkage Cast aluminum Offenhouser unit for attaching two factory or aftermarket single barrel carburetors. Part No. Description HP104 1937-53 For 216 Chevrolet engine |
| <image/> |



| Motor Mount Kit, Side Mount for V-8 Used when placing a 1958 and newer small block Chevrolet V-8 in the 1940-55 1st GM pickup. These engine side mounts can be bolted on or welded to your frame. Includes cushion set, bolts, and instructions. A professional installation that eliminates the under engine round cross member sold in some stores. Part No. Description HP121 1936-55 1stset 134.50 |
|--|
| Transmission Frame Cross Member Our cross members fit well when you place a modern automatic transmission in the older GM trucks. Its 6" drop make a successful fit on 350, 400, 700R4, and Powerglide transmissions. Part No. Description HP1261 1939-59each 65.50 |
| Transmission Mount Pad Part No. Description MET102 For use with HP1261 aboveeach 11.75 |
| Air Conditioning Compressor and Alternator Bracket Secures air conditioning compressor and alternator in the best position. Made in USA! Part No. Description HP129 1955-62, 235 and 261 enginekit 135.00 |
| Alternator Bracket Specially made bracket for properly securing a modern 6 or 12 volt GM alternator when the original generator is replaced. Part No. Description HP130 1937-53 216, 1954-55 1st 235 and 1939-59 GMC engineeach 64.50 HP131 1955 2nd-62 High pressure 235 engine, Made in USA!each 54.50 |
| Chevrolet United and a second se |
| 1939 New Zealand Right Hand Drive truck. Owner and restorer Steve Jones. |



| | HIGH PERFORMANCE SPEED EQUIPMENT (continued) Alternator, Six Volt This modern unit is even equipped with an internal regulator. Its charging capacity is over 70 amps. Can be adapted to all 6 volt vehicles. Rebuilt. No core charge. (Used with HP130 or HP131.) Part No. Description |
|--------------|--|
| | REHP137N 1934-55 1st Chevrolet (negative ground)each84.50REHP137P 1936-55 1st GMC (positive ground)84.50 |
| | Alternator, Twelve Volt Designed to replace the original generator. Has internal voltage regulator and a charging capacity of over 70 amps. Negative ground only. Rebuilt. No core charge. (Used with HP130 or HP131.) Part No. Description REHP136 Negative groundeach 84.50 |
| | • Alternator Pulley This pulley is made for a GM alternator when you use the original wide fan belt on your early six cylinder. Matches width of original 216 Chevrolet Harmonic Balancer. Part No. Description HP530 1937-52 216 Chevroleteach 24.50 |
| | Alternator Flat Fan You will need a "flat" alternator fan to use HP530 above. Most come with this fan design. Otherwise we can provide it. Part No. Description HP531 Alternator flat faneach 12.00 |
| | • DA Plug for Alternators Allows the use of your original ignition switch when using a modern alternator. Prevents the engine from continuing to run after you turn off the switch. A simple plug-in to your alternator. Part No. Description HP240 For 6 or 12 volteach 21.50 |
| | Distributor and Coil, Modified HEI This electronic ignition greatly improves starting and performance. No points to wear out! No gradual change in timing! A late model modern GM distributor has been machined to fit the older inline six. This excellent used GM modified housing includes new HEI coil, rotor, cap, lead wire, vacuum advance, and instructions. Twelve volt 235 engine and 261, not 216. No core charge. This small distributor and round coil look similar to the original six cylinder unit. Does not take away from the original appearance! Made in USA! Part No. Description HPD150 1954-62 Chevrolet (high oil pressure engines)each 255.50 HPD151 1954-62 Chevrolet HEI coil only |
| F | Spark Plug Wire Set for HEI Distributor Set of black wires with insulated caps (six cylinder). Part No. Description ELW542 1937-62 Chevrolet and GMCset 27.95 |
| | • Distributor, Mallory A heavy duty dual point unit specially made for your GM six cylinder engine when you desire high performance. Part No. Description |
| (p - | HP138 12 volt |



| • Coil, High Performance Designed for the higher RPM engine. Excellent with the HP138 Mallory dual point distributor described above. Will not work with our HEI distributor. Part No. Description HP139 12 volteach 64.95 |
|--|
| Disc Brake Conversion Kit Use with your existing straight axle and spindles. A top quality American made bolt-on assembly. Includes caliper mounting brackets, attaching hardware to spindle, bearing adapters which use modern tapered roller bearings, and instructions for using <u>your</u> late model calipers, five lug rotors, pads, seals, and bearings. You obtain more common parts locally or use HP1411 or HP1412. Part No. Description HP1401 1929-40 1/2 ton |
| Disc Brake Kit, Complete Front - 5 Lug Pattern Everything you need to equip your existing straight axle front end with modern brakes. Includes the above HP1401 or HP1402 kit plus bearings, seals, rotors, rebuilt calipers, brake pads, etc. Saves your time and money from gathering modern parts locally! Not to be used with original master cylinder. Part No. Description HP1411 1929-40 1/2 ton |
| • Disc Brake Kit, Complete Front - 6 Lug Pattern This 6 lug disc brake kit contains all you will need to put modern discs on your stock 1/2 ton spindles, and uses your stock hub. Includes GM rotors, calipers, brackets, hoses, and brake pads, etc. HP508 and HP509 are options for this disc brake kit. Part No. Description HP500 1941-54 1/2 ton, frontkit 459.50 |
| Wheel Bearing Upgrade, Front For those that prefer to eliminate the original front ball bearings, we have the conversion. Changes the original balls to modern roller type. Includes inner and outer bearings with races plus grease seals. Works with original 1/2 ton drums as well as HP500. Part No. Description HP508 1941-59kit 119.00 |
| Wheel Spacer Kit Works with HP500. Part No. Description HP509 1941-54 1/2 ton 3/16" wheel spacers. (Some late model wheels rub the caliper when you add modern disc brakes.) |
| |



| HIGH PERFORMANCE SPEED EQUIPMENT (continued)• Ring and Pinion For Differential - 1/2 TonFinally, a rear end ratio is available that allows your 1/2 ton pickup to cruise better at highwayspeeds. These new sets change the 4.11 ratio on the 1940-53 closed drive line to 3.55. Yourtrucks personality is now completely changed! Nothing is visible outside. Engine RPM isreduced almost 20%.Part No.DescriptionHP1631940-543.55 ratio |
|--|
| • Differential Bearing, Bushing, and Seal Kit 1/2 Ton For use with HP163 Ring and Pinion Set above when you require all wearing parts replaced. Kit includes such items as pinion and carrier bearings, pinion and wheel seals, gaskets, torque tube bushing, etc. Individual components are listed in Mechanical Section. Part No. Description HP165 1940-50 1/2 tonkit 395.00 |
| Differential Chrome Cover This 10 bolt cover includes gasket and drain plug. For a little extra "flash" the cover and plug have been polished and chrome plated. They will be quickly noticed by the following traffic!. Part No. Description HP245 1937-62 1/2 Tonkit 54.95 |
| Axle to Leaf Spring Attaching Kit Allows you to replace your original axle housing with modern differential that has the more popular 3 inch axle tubes. Includes U-bolts, lower plates, saddles, etc. Welding of saddles to axle housing required. Part No. Description HPD179 1934-54 1/2 ton onlykit 89.95 |
| • Proportioning Valve Necessary when using disc brake master cylinder in combination with rear drum brakes. Part No. Description HP169 Brake fluid valve |
| • Proportioning Valve Mounting Bracket Designed to attach the proportioning valve (HP169) to master cylinder area. Part No. Description HPB170 |
| Shock Absorber Conversion Kit For those wishing to add modern tube shock absorbers to their 1949 and older 1/2 ton pickup with original lever action shocks. We now stock a complete kit which includes upper and lower forged steel shock mounts, front and rear, plus 4 gas shocks. Because the kit was designed for 1947-49 1/2 ton, you will need to drill holes in your frame rail for the upper shock mounts. Sorry, we don't have a template for the 1946 and older truck. Part No. Description HP590 1936-49 1/2 ton (also 1950-54 replacement)kit 285.50 |

...visit our website for SPECIAL savings!



HIGH PERFORMANCE SPEED EQUIPMENT (continued)

Independent Front Suspension Mounting Kit, Pacer

The American Motor's Pacer (about 1975-82) has a front suspension that bolts in and has parts (A-arms, springs, tie rods, sway bar, steering, shocks, etc.) contained in a single unit. (The later years even have disc brakes.) It is heavy duty and ideal for this application. (We now have an adapter kit for attaching this Pacer unit to your truck.) Installation is bolt-on to the truck's front cross-member after our brackets are welded to your Pacer front end. Tread width is 61-1/2" and works as is. This is a good fit and well worth doing if you want a softer ride and modern updated steering.

Part No. Description

HP127 1947-55 1st (with modifications will work on 1940-46)set 145.00

Mustang II to Chevrolet Disc Brake Conversion Kit

A popular front suspension for the custom truck is the rack and pinion assembly from the 1974-78 Mustang II. It attaches very nicely to the 1959 and older GM 1/2 ton frame. We offer an excellent brake conversion kit which allows you to use larger 11 inch diameter GM car rotors, calipers and discs, while keeping the Ford Mustang spindles. Provides 65% more braking capability over the 9 inch Mustang II rotor. (The front wheel 4-3/4" bolt circle pattern will now match the rear if you use most GM car five-bolt rear drums.)

Note:User must supply stock Ford upper caliper cradle mounting bolts on all Mustang kits.Part No.Description


HP171 Conversion Kit 1/2 ton kit 150.00

Mustang II to Chevrolet Disc Brake Conversion Kit, Complete

Includes the above HP171, plus the necessary rotors, calipers, brake pads, seals, bearings, etc. Saves you time and money from gathering modern parts locally!

Note:User must supply stock Ford upper caliper cradle mounting bolts on all Mustang kits.Part No.Description

HP172 Conversion Kit 1/2 ton kit 395.00







KNOBS

...visit our website for SPECIAL savings!

We carry a full line of excellent reproduction dash knobs that will perfectly replace your cracked and broken originals.

KB101 CHOKE, THROTTLE, AND HEADLIGHT KNOBS Choke Knobs Part No. Description 1934-39 Black with white letterseach KB101 9.80 KB102 1940-46 Rose taneach 9.80 **KB102 KB131** Throttle Knobs Part No. Description KB131 1934-39 Black with white letterseach 9.80 **KB133** 1940-46 Rose taneach 9.80 **KB133 KB132** Headlight Knobs Part No. Description KB132 1934-39 Black with white letterseach 9.80 KB134 1940-46 Rose taneach 9.80 **KB**134 **CHOKE AND THROTTLE CABLES** We have an excellent selection of top quality cables, complete with housing, wire, base and proper year knobs. For the perfectionist! Choke Cable With Knob Part No. Description KB135 1934-39 Complete with black knob and white letteringeach 35.50 1940-46 Complete with rose tan knob and letter "C"......each KB136 35.50 Throttle Cable With Knob Part No. Description KB148 1934-39 Complete with black knob and white letteringeach 35.50 KB120 1940-46 Complete with rose tan knob and letter "T"each 35.50 MISCELLANEOUS KNOBS AND HANDLES Crank Knob With Pin, Side Window Part No. Description **KB118** 1939 Also for windshield crank handle. Black......each 9.80 KB103 1940-46 Also for windshield crank handle. Rose taneach 9.80 Cowl Vent Knob, Non-Metal Part No. Description KB190 1942-46 Top cowl vent knob. Medium browneach 8.95


KNOBS

...visit our website for SPECIAL savings!



MISCELLANEOUS KNOBS AND HANDLES (continued)

| | • Gear Shif Part No. KB128 KB114 | t Knobs Description 1929-47 3-speed floor shift. Black (non-threaded)each 1936-66 4-speed floor shift. Black (threaded)each | 8.50 8.50 |
|----|---|--|----------------|
| | • Ash Tray Part No. KB110 | Handle Description 1940-46 Original rose tan with attaching clipseach | 9.95 |
| 50 | | k Knobs, Just like original. ne T-handle for inside of left door. Description 1934-40 3/16" Square holeeach 1941-46 1/4" Square holeeach | 11.50 11.50 |



It's a definite assurance to you and your family that you can get skilled, reliable Chevrolet service, at reasonable cost, whenever and wherever you may travel!

ORDERS 1-800-862-1913 TECH HELP 2-4pm 1-816-252-5857 oldchevytrucks.com 51

| | LIGHTING | | | |
|-------------|---|---|---|--|
| Truck Parts | visit our website for SPECIAL savings! | | | |
| | HEADLIGHTS• Headlight Assemblies, With Black BucketsStainless rings. Very close in appearance to the originals. 12 voltPart No. DescriptionLGH2101937-40 with small parklight on bucket | pair | 299.00 | |
| | adjustable mounting stud.Part No.DescriptionLGH1991934-40 with Sealed beams, no parklightsLGH2001934-40 with Sealed beams, with parklights in bezel | pair pair | al, but not rrect 1/2" 230.00 260.00 265.00 | |
| | eye amber glass lens. Includes special adjustable stand for attaching to fr Replace 12 volt bulb if you have a 6 volt system. Show quality! Part No. Description | ont bumpe | ith 6" cat- er braces. 245.00 | |
| | Headlight Rings or Doors Part No. Description LG100 1937-40 Chrome LG101 1941-46 Chrome | pair each | 59.50 24.95 | |
| | LGH600R 1934-36 Chevrolet and 1936 GMC, right LGH601L 1937 Chevrolet and 1937-40 GMC, left | each each | 49.00 49.00 42.50 42.50 | |
| | LG570 1938 Chevrolet | pair | 3.50 3.50 3.50 | |
| 00 | Headlight Bar Pads, Fender and Radiator Shell Part No. Description LG297 1934-36 Chevrolet and 1936 GMC, set of 4 | set | 13.00 | |
| | • Headlight Bucket to Fender Gaskets Not originally used but a nice addition to stop metal to metal contact. Part No. Description LGH460 1941-46 | pair | 16.50 | |
| 0 | • Headlight Rim Rubber Seal Wire reinforced. Fits inside headlight bezel or ring. Part No. Description LG161 1941-56 | pair | 9.50 | |
| | Headlight Reflectors Made to reflect the light from the bulb. Exactly fits the edge of the factory | / bucket. | | |
| | Part No.DescriptionLGL1081937-39 As original.LGL1091937-39 Correct for modern H-4 Halogen bulb. | pair pair | 84.50 74.75 | |
| | | visit our website for SPECIAL savings! HEADLIGHTS HEADLIGHTS Headlight Assemblies, With Black Buckets Stainless rings. Very close in appearance to the originals. 12 volt Park to Description LGH210 Headlight Assemblies, Stainless Beautiful polished 12 volt headlights to nicely replace original style. Close exact. Excellent for the street rod enthusiast! Has original 8 1/2" diame adjustable mounting stud. Park No. Description LGH200 LGH201 Park No. Description LGH201 LGH201 Park No. Description LGH201 <td colsp<="" th=""><th>wisit our website for SPECIAL savings! HEADLIGHTS Neadlight Assemblies, With Black Buckets Stainless rings, Very close in appearance to the originals. 12 volt Park No. Description LCH210 11937-40 with small parklight on bucket</th></td> | <th>wisit our website for SPECIAL savings! HEADLIGHTS Neadlight Assemblies, With Black Buckets Stainless rings, Very close in appearance to the originals. 12 volt Park No. Description LCH210 11937-40 with small parklight on bucket</th> | wisit our website for SPECIAL savings! HEADLIGHTS Neadlight Assemblies, With Black Buckets Stainless rings, Very close in appearance to the originals. 12 volt Park No. Description LCH210 11937-40 with small parklight on bucket |



| | HEADLIGHTS (continued) | |
|----|--|-----------------------------------|
| | • Headlight Rim Rubber Seal Retaining Clips Part No. Description LG203 1941-55 1st (per truck)set | 4.90 |
| | Headlight Sealed Beam Retainer Ring Part No. Description LG104 1941-57 Stainless steeleach | 8.75 |
| | • Headlight Adjusting Nut And Screw Part No. Description LGH303 1941-57 Set of 4set | 17.95 |
| | • Headlight Adjusting Spring Part No. Description LGH473 1941-46each | 3.90 |
| | Headlight Wiring Loom Grommets Part No. Description LG204 1934-36 Fits in the side of grille housingpair LG106 1937-55 1st Fits in inner fenderpair | 4.75 2.75 |
| | • Headlight Wiring Loom Black fabric loom to protect wiring that extends from light bucket to inner fender block. Exact as original. Part No. Description LG112 Headlight wiring loomfoot | terminal 1.55 |
| | • Headlight Sealed Beam Socket Headlight plug and wires that attach to seal beam bulbs with 3 prongs. Part No. Description LG293 Headlight sealed beam socketeach | 2.50 |
| | PARKLIGHTS Parklight Assemblies For the person that likes a few "extras" but wants to stay with GM accessories. stock the very attractive park light assemblies that were placed on cars at the C dealership in 1937-39. These authentic appearing lights not only are correct for also fit the fender contour of all 1934-39 GM trucks! Replace their 12 volt bulbs if y a 6 volt system. Includes dual filament sockets so you can easily have both park signals. Colored photo on catalog cover. Part No. Description LGP211 1934-39 | Chevrolet cars but /ou have |
| | • Parklight Housing, Metal Part No. Description LGP414 1942-46each | 29.50 |
| QQ | • Parklight Lens Bezel, Stainless Steel. Made in USA! Part No. Description LGL401 1940each | 34.50 |
| | | |

| LGL404 1940 Round frosted plastic copy, looks exact!each 24 LGL400 1941 Frosted plastic copy, looks exact, limited productioneach 24 LG108 1942-46 Frosted glass, exact as originaleach 13 • Parklight Lens Gaskets Part No. Description LG304 1940 Chevrolet and GMC (round) | 4.50 24.50 24.00 3.75 4.00 4.00 5.50 6.90 |
|--|--|
| 1940 PARKLIGHTS (continued) • Parklight Lens, Chevrolet and GMC Part No. Description LGL402 1934-39 GM accessory lens for LGP211 | 24.50 24.00 13.75 4.00 4.00 5.50 6.90 |
| PARKLIGHTS (continued) • Parklight Lens, Chevrolet and GMC Part No. Description LGL402 1934-39 GM accessory lens for LGP211 | 24.50 24.00 13.75 4.00 4.00 5.50 6.90 |
| Parklight Lens Gaskets Part No. Description LG304 1940 Chevrolet and GMC (round) | 4.00 5.50 6.90 |
| LG207 1941 Chevrolet and GMC 4" long | |
| 1940 LGP210 1941 Chevrolet and GMC LGP210 pair 10. LG210 1942-46 Chevrolet and GMC. Lens housing to headlight 10. | 11.30 |
| LG154R 1940-53 Right, with red glass lens only. No license lenseach 23. LG154LC 1940-53 Left, chrome with red glass lens | rome e non have ce. 37.50 23.00 23.00 |
| LG154RC1940-53Right, chrome with red glass lens only. No license lens28.LG152L1940-53Left, with red plastic lens and license lens23.LG152R1940-53Right, with red plastic lens only. | 28.50 28.50 23.00 23.00 |
| LG155L 1940-53 Left, with red glass lens with blue dot and | 28.50 |
| LG155R 1940-53 Right, with red glass lens, blue dot. | 28.50 |
| LG195L 1940-53 Left, with red plastic lens, blue dot, | 29.95 |
| LG195R 1940-53 Right, with red plastic lens, blue dot. | 29.95 |
| • Taillight Conduit Retainer On 1934-39 taillights there is a small retainer that secures the metal conduit for protect wires. If you need it, we have it! Hand made in the USA! Conduit #LGL106 Part No. Description | cting |



| | • Taillight Bulb Changeover The 1940-53 taillights produced during the past twenty years are not designed to hold the original large 21 candle stoplight bulb! We have created a bracket for inside your taillight that eliminates th three candle power bulb and allows the large original 21cp bulb. With this changeove stoplight will be seen easier and at a greater distance. Get the most out of your style taillights and lessen accident potential. (Not included with LG152, LG154, or I Part No. Description LG290 1940-53 | ne small ver, your original |
|-----------------|---|--|
| LG129P LG132 | STEPSIDE TAILLIGHT ITEMS• Lenses, Pickups, Panel trucks, Suburbans, and Big TrucksPart No.DescriptionLG1291934-46 GMC pickup, Suburban and Canopy Express with tailgate. Glass red round lens 4" diameterLG2491934-39 Red oval glass with Chevrolet bowtieLG1321940-53 Red plastic (a quality copy of LG1331)LG1341940-53 Red glass.LG1341940-53 Red glass, with blue dotLG1961940-53 Red plastic, with blue dot | 24.50 15.50 5.50 5.75 10.50 10.50 |
| LG250 | Taillight Lens Gaskets Part No. Description LG250 1934-39 Chevrolet only, ovaleach LG135 1940-53 Chevrolet and GMCeach | 2.95 1.25 |
| | • Taillight License Lens and Gasket Part No. Description LG137 1940-53 Lens, cleareach LG138 1940-53 Gasketeach | 6.80 2.10 |
| LG144 | Taillight Brackets with Original Style Stamped Lettering These attach to the rear stake pocket. Powder coated black. Made in USA! Part No. Description LGB230L 1934-36 left, with license bracket | |
| | • Taillight Brackets, Custom For those that want a taillight bracket that is very different. The factory light ren the correct position. A definite eye-catcher at any show. Brushed stainless with i attaching screws, taillight chrome acorn nuts and gaskets. A beautiful extra for that truck! Looks great with chrome taillights LG154LC or LG154RC.(Not included!) Part No. Description LGL204L 1940-53, lefteach LGL204R 1940-53, right | ncluded |



| LG156 & LG320 | Taillight Bezels or Doors Part No. Description LG252 1934-39 Black, oval. Chevrolet onlyeach LG156 1940-53 Chrome, rectangulareach LG320 1940-53 Stainless, rectangular, will never rusteach | 12.50 9.00 14.00 |
|-----------------|---|---------------------------|
| LG160 LG1100 | Taillight Wiring Loom or Conduit Protects wiring which extends from taillight bucket. Part No. Description **LGL106 1934-39 Taillight conduit 5/16" galvanized steel,18" long each LG160 1940-53 Black fabric as original, Sold per footfoot *LGL100 1940-55 Polished stainless steel 18" long 1/2 diametereach *Part LGL100 is an excellent dress-up item for the older taillights but is not correct on LG158 (1934-39.) and **Part LGL106 will require taillight retainer LGL107. | 12.00 1.25 4.25 |
| 00 | • Taillight Wiring Loom Grommets Fits in truck frame rail hole near taillight to protect wiring. Part No. Description LG1061 1941-72pair | 2.75 |
| | Bed Roll Custom Lights For the custom non-original stepside pickup. Fits in the bed roll and is a great add the original taillights. A pair of single filament units are extra stop and turn signal Your wiring runs forward through bed roll, down a stake pocket and connects to light harness. An included rubber o ring keeps light secure in bed roll. Complete withousing, sockets, wiring, and instructions. A great extra. Part No. Description SMC120 1940-72 Stepside 1 3/4" diameter rollpair | l lights. the tail |
| | Bed Side Hole Cap, 1-3/4" Diameter Roll For the finishing touch on your modified truck. A rubber O-ring band surrounds the of the metal cap and holds it in place. Just press in and the job is done. Part No. Description SMC100 1940-66 Smooth finishpair SMC101 1940-66 With a Bowtie cut in the smooth surface | outside 39.95 49.95 |
| LG158 | PANEL TRUCK AND SUBURBAN TAILLIGHT ITEMS • Taillight Complete Part No. Description LG158 1934-39 Oval with red glass lens LG154L 1940-46 Rectanglar with red glass lens and license lens | 67.50 23.00 |
| LG249 | Taillight Lens and Bezels, Chevrolet Panel and Suburban Part No. Description LG249 1934-39 Panel and Suburban with double doors, lenseach LG1331 1940-46 Panel and Suburban with double doors, lenseach LG156 1940-46 Panel and Suburban with double doors, chrome bezeleach | 15.50 5.75 9.00 |



| | Taillight Lens, Chevrolet and GMC Suburban with Tailgate (Center Mount) Part No. Description LG129 1934-46 Suburban with tailgate and Canopy Express. Glass red round lens 4" diameter, Limited Quanitiesead | ch 24.50 |
|---------------------|---|----------------------|
| LGL622 LGL623 | Taillight Stand, Panel and Suburban, Double Door (Limited Production) Part No. Description LGL622 1937-39. Made in the USA!eac LGL623 1940-46. Made in the USA!eac | |
| | LIGHT BULBS, SIX VOLTProper 6 volt bulbs to replace originals.• Stop LightPart No.DescriptionLG17221 candle power, as originalead | sh 1.90 |
| P | Park and Taillights Part No. Description LG173 3 candle power, cleareac LGB299 6 candle power, single filament, ambereac | ch 1.50 ch 3.50 |
| | Turn Signal Bulbs Special double filament for use with add-on directional signals. Eliminates the separate park light assembly. Also fits original taillights. Part No. Description LG175 3 and 21 candle power, cleareac LGB298 3 and 21 candle power, ambereac | ch 2.25 |
| | • High Beam Indicator, Ignition Switch and Glovebox Light Part No. Description LG179 1 candle powereach | 1.35 |
| | • Dash Bulbs Part No. Description LG174 2 candle powereach | 1.50 |
| LG184 and LGB120 | Headlight Bulbs Part No. Description LG186 1929-34 As original. 32cp low beam; 32cp high beameach LGB119 1929-34 12 volt. 32cp low beam; 32cp high beameach LG176 1935-39 As original. 32cp low beam; 32cp high beameach LG187 1929-34 Much brighter than original. 32cp low beam; 50cp high beameach LG184 1940-55 1st Sealed beam headlight bulb. Excellent replacement 6 volteach LGB120 1940-57 Seal beam 12 volteach | 5.30 8.00 7.75 |




Headlight Halogen Replacement Light Assembly This new high-tech headlight assembly looks very close to the original seal beam, however deep inside is a commom halogen bulb. An easy replacement that even connects to your original headlight socket. 12 volt only. Part No. Description LGB161 All seal beam trucks.....each 19.95 LED LIGHTING Most all exterior lights for 1940-55 GM trucks are now available 12 volt LED and Halogen. We have them! Headlight Bulb Part No. Description **LGB164** LGB160 1940-72 Halogen sealed beam, one piece.....each 21.95 Taillight Lens Part No. Description 1940-53 Red lens and clear license lens, left.....each LGB164 35.50 LGB165 1940-53 Red lens, righteach 31.50 Taillight, Complete Part No. Description LGB167 1940-53 Red lens and clear license lens, black housing, left.....each 49.95 LGB169 1940-53 Red lens and clear license lens, chrome housing, lefteach 49.95 1940-53 Red lens, black housing, righteach 39.95 LGB166 LGB168 1940-53 Red lens, chrome housing, righteach 43.95

...visit our website for SPECIAL savings!



LGB168



ITERATURE

...visit our website for SPECIAL savings!



SHOP MANUALS

Exact reprints of the original factory shop manuals in full size. A must if you are restoring or just driving your truck. One of our best selling items.

| 25.50 |
|-------|
| 25.50 |
| 25.50 |
| 25.50 |
| 25.50 |
| 25.50 |
| 25.50 |
| 25.50 |
| |

• GMC Part LI194

| : No. | Description | |
|-------|-------------|-------|
| 4 | 1936-38each | 39.50 |

ACCESSORY LISTINGS

These are a great help to identify NOS accessory parts for your year and model at swap meets. These numbers are not listed in most other books and cover all passenger cars and trucks models. Chevrolet only, but similar to GMC.

| Part No. | Description |
|----------|-------------|
| LI518 | 1937 |
| LI519 | 1938 |
| 11501 | 1020 |

| LI518 | 1937 | each | 2.50 |
|-------|------|------|------|
| LI519 | 1938 | each | 2.50 |
| LI501 | 1939 | each | 2.50 |
| LI502 | 1940 | each | 2.50 |
| LI503 | 1941 | each | 2.50 |
| LI517 | 1942 | each | 2.50 |
| LI508 | 1946 | each | 2.50 |



OWNER'S MANUALS

Exactly as original. Explains operations, controls, maintenance, tire pressure, weights, load capacities, etc. Every truck had one of these in the glovebox when new. An item to always have with your truck.

Chevrolet

| Description |
|-------------|
|-------------|

| Part No. | Description | |
|----------|-------------|------|
| LI434 | 1934each | 9.00 |
| LI435 | 1936each | 9.00 |
| LI436 | 1937each | 9.00 |
| LI437 | 1938each | 9.00 |
| LI438 | 1939each | 9.00 |
| LI439 | 1940each | 9.00 |
| LI440 | 1941each | 9.00 |
| LI441 | 1942each | 9.00 |
| LI442 | 1946each | 9.00 |



RETAIL SALESMEN'S

GENUINE CHEVROLET ACCESSORIES

PRICE LIST

1940



the 1934 CHEVROLET

TRUCKS

CHEVROLET TRUCKS FOR 1946

GM Restoration Parts

LITERATURE

...visit our website for SPECIAL savings!

OWNER'S MANUALS (continued)

GMC Part No. Description

| rait NO. | Description | |
|----------|-------------|------|
| LI413 | 1941each | 9.00 |
| LI414 | 1942each | 9.00 |
| LI415 | 1944-46each | 9.00 |

SALES BROCHURES

Exact reprint of dealer's advertising foldout. Mailed to potential customers during those years. **Part No. Description**

| Part No. | Description | | |
|----------|-------------|------|-------|
| _IB34 | 1934 | each | 12.95 |
| _IB36 | 1936 | each | 13.95 |
| _IB37 | 1937 | each | 10.95 |
| _IB38 | 1938 | each | 12.95 |
| _IB39 | 1939 | each | 12.95 |
| _IB40 | 1940 | each | 10.95 |
| _IB41 | 1941 | each | 17.95 |
| _IB42 | 1942 | each | 9.95 |
| _IB46 | 1946 | each | 10.95 |
| _IB46P | 1946 Panel | each | 10.95 |
| | | | |

SALESMAN'S TRUCK DATA BOOKS

• 1937

L

L

A reprint of the annual book assigned to Chevrolet truck sales people. Just the size for the salesman's large coat pocket. Gives pictures, options, and detailed technical data. Great for 1937-38 truck owners. 205 pages.

| 1941 Chevrolet | for 1937-38 Part No. LI189 | truck owners. 205 pages. Description 1937-38 Chevroleteach | 34.00 |
|---|---|--|------------|
| TRUCK DATA BOOK | options, and | eprint of the book assigned to Chevrolet truck sales people. Gives d detailed technical data. An exact copy for the 1941 Chevrolet truck. book. Great for 1940-46 truck owners. 295 pages. Description 1941 Chevroleteach | |
| Master Parts Catalog Master Parts Catalog Master Parts M Restoration Parts M Restoration | This large re of Chevrole etc, of the p | I | al prices, |
| 111 CILLER AN AND IL | GMC Illus Excellent br 200 pages. | | n trucks. |
| <u>GM</u> Restoration Parts | Part No. LI193 | Description 1936-38 GMCeach | 36.90 |

LITERATURE





| Bed Restoration Manual for | | |
|---|---|--|
| for the other of the other other of the other othe | MANUALS, MISCELLANEOUS (continued) Bed Assembly Pamphlet Manual giving details on assembling a GM factory stepside pickup bed from the gr Detail descriptions, trivia, and sketches for the perfectionist. Part No. Description LIP123 GM Factory Stepsideeach | ound up. 3.95 |
| | • Paint Sheets Lists the names and years of the various colors which were available from 1936 No chips. Part No. Description | to 1966. |
| | LI124 1936-66 Chevroleteach LI142 1938-66 GMCeach | .15 .15 |
| | Pin Striping Blueprint An exact large copy of a Chevrolet engineering blueprint from 1937. Shows proper and sizes of pin stripes on hood and body. For the perfectionist. Also appropriate Part No. Description LI190 1937-38 Chevroleteach | |
| Intervention The server and the server and the server the server t | Pin Striping Sheet Gives pin striping details on trucks between 1939-55 1st. Sketches and technica the perfectionist. Included in PT603 pin stripe kits. Part No. Description LI158 Pin Striping Sheeteach | l data for 1.25 |
| RearAyle OVERHAUL GM Restoration Parts | Rear Axle Overhaul Manual 1/2 Ton A General Motors reprint detailing the rebuilding of a closed driveshaft differential a Part No. Description LI160 1941-54 1/2 Toneach | |
| No data tangga na kang na kang Na kang na kang | Mechanic's Study Guide Booklet Available in the mid 1940's to Chevrolet mechanics. These 69 pages helped in p for the GM shop test. Hundreds of specialized questions with answers. Part No. Description LI161 Chevrolet | oreparing 6.50 |
| <text><section-header></section-header></text> | How To Restore Your Truck Probably the "best" restoration book on the restoration of early Chevrolet and GMC Don't let the non-original paint colors on the cover fool you. Author, Tom Browner of our leading experts on GM restoration. He has a great ability to perfectly explored the specialized chapters cover such important topics such as front end overhaul, correct restoration, wiring, transmission and driveline overhaul, bed restoration, chrome sheet metal repair, etc. Even if you have another person restore your GM pickup, you this knowledge to better communicate with your builder! Part No. Description LI581 1934-1972 GM 60 Content of the set of t | II, is one press his . Twenty ct interior e plating, |

| Carter Carter Truck Parts | LITERATUREvisit our website for SPECIAL savings! |
|---|--|
| | MANUALS, MISCELLANEOUS (continued) |
| The official 12-Volt Concernation and the official states of the off | "The Official 12 Volt Conversion Guide" A step by step, 20 page guide to everything you need to know about changing a 6 volt electrical system to 12 volts. Part No. Description LIP612each 10.00 |
| CHEVRC'SET CASTING FORGING IDENTIFIC NUMBER SEQUENCE LAUR 1929-1942 | Casting Number Guide A Chevrolet booklet which allows you to identify cast iron mechanical parts by their permanent built-in numbers. 12 pages. Part No. Description Li187 1929-42each 3.00 |
| CHEVEOLT BOOK DIVISION | Chevrolet Newspaper A full size newspaper featuring the 1941 Chevrolet truck. White paper stock and black ink. Given out by Chevrolet dealerships in 1941 to show the retail customers pictures and data on this new model. Very informative!. Shipped in protective tube. Part No. Description LI145 Chevroleteach 9.50 |
| | Booklet of GM Truck Illustrations We have available a collection of professional line illustrations of General Motors Trucks, between 1929-1972 by artist Bryant J. Stewart. The booklet includes thirteen pages of individual line drawings in print form on heavy paper and ring bound. It is a great addition for the GM Truck enthusiast. Bryant's works are shown on various pages throughout this catalog. Part No. Description LI531 Pen and ink drawingseach 27.50 |
| | • Service Bulletins We now stock "exact" copies of the original monthly Chevrolet Service Bulletins that were issued to all dealers. These pamphlets discuss problem areas on new trucks and cars that may need attention by the dealership. Very informative! These are priced much less than most rare shop-worn originals. Sold in calender years only. (Remember, the last months of each year often feature many of the next year's vehicles.) Due to World War II, the 1942-45 bulletins are short years and are sold together. Part No. Description LI546 1934each 16.00 LI547 1935each 16.00 LI548 1936each 16.00 LI550 1938each 16.00 LI551 1939each 16.00 LI551 1939each 16.00 LI552 1940each 16.00 LI553 1941each 16.00 LI554 1942-45each 16.00 LI555 1946 |

LITERATURE



| How To PAINT YOUR CAP ON A RUBER With We not the Paint of the Constant Capital Constant Cap | MANUALS, MISCELLANEOUS (continued) Chevrolet and GMC - How To Paint Your Car Author Pat Ganahl unveils dozens of secrets that will help anyone paint their own car. From simple jobs to full-on, door jambs and everything paint jobs. Ganahl covers everything you need to know to get a great looking coat of paint on your car. Part No. Description Ll202 Ll202 |
|--|---|
| Idente de três Anazer Anizarie To bater - Han Hall, fors au Caparent Indente au Proposition - Steppen Robert Jane Holikarene Paid Product Marce Car Stanten por Paid Care | |
| | Rebuilding The Small Block Chevy One of the best books on rebuilding the 265, 283, 327, and 350 small block V-8. Includes 650 photos to make your rebuilding a success. Shows performance upgrades, engine removal and installation, how to avoid costly mistakes, tips from master mechanics, selecting the correct parts, and getting quality machine work. A must if you will be restoring a small block Chevy. The detailed 150 pages will simplify your job and make communication with your mechanic much easier. Part No. Description LI574 East 24.95 |
| Checup Internet & Constant La Terret Enternet and and and Enternet and and and | Casting Number Guide, Six Cylinder Finally, we have found a listing of the GM casting numbers for six cylinders from 1929-89. This 126 page, pocket-size booklet lists the numbers on blocks, heads, intakes, exhausts, and water pumps. No more guessing at swap meets or salvage yards! Positively identify the six cylinder and parts. A must for the perfectionist. Part No. Description L1181 1929-89each 15.00 |
| AUTOMOTIVE | • Automotive Wiring and Electrical Systems This book solves the mysteries of automotive electrics and electronic systems. The basics of electrical principles, including voltage, amperage, resistance, and Ohm's Law, are revealed in clear and concise detail, so the enthusiast understands what these mean in the construction and repair of automotive electrical circuits. All the tools and the proper equipment required for automotive electrical tasks are covered. 8 1/2 x 11", 144 Pages, 380 color photos. Part No. Description LI575 |
| Cettomic Bitti Constantion CHEVROLET Speed Maruna Speed Maruna | Chevrolet and GMC Speed Manual A reprint of Bill Fisher's "California Bill" original edition of the 1954 speed manual. Details how the GM inline six was built for performance in the 1950's. Covers Chevrolet 216 and 235 plus GMC 228, 248, 270, and 302 engines. This is how they did it 40 years ago! Part No. Description LI200each 15.95 |
| "The Official Cruide to Modern Cacoline & OU for Antique Vehisles" | Modern Gasoline & Oil Official Guide In this 60 page book author and early vehicle expert Randy Rundle explains how the changes to modern gasoline and engine oil have affected early vehicles, and what you need to do to protect your truck or car from these changes. A must have book for all pre-1980 vehicle owners. Part No. Description LI584 For pre-1980 Vehicleseach 13.95 |



...visit our website for SPECIAL savings!

When you are in need of mechanical parts for your 1934-46 Chevrolet/ GMC think of us. We are one of the country's leaders in providing parts that keep your "special truck" on the road. This mechanical section is the largest section in our catalog. From engine to differential we can help you.

| Units of the stress of the stress | • Master Cy | linders | |
|-----------------------------------|--------------------|--|------------------|
| | Part No. | manufactured. No core charge. | |
| | ME1422 | Description 1936-46 1/2 ton, 3 speed trucks. (1" bore) Mounts to truck vertically | |
| • ME1422 | | plugged threaded hole for a stop light switcheach | 149.00 |
| | ME164 | 1938-47 Early Chevrolet and most GMC's. 3/4, 1, 1-1/2, and 2 ton | 143.00 |
| | | (1-1/4" bore) Mounts to truck horizontally. | 145.00 |
| | | | 110.00 |
| ME164 | Master Cy | /linder Repair Kits | |
| 8 | Part No. | Description | |
| 63 | ME169 | 1936-50 1/2 ton (1" bore)kit | 24.75 |
| | ME319 | 1937-52 3/4 ton, | |
| K | | 1938-52 1 ton, | |
| S (A) | | 1936-59 1-1/2 ton, and | |
| | | 1947-59 2 ton (1-1/4" bore) kit | 35.50 |
| | • Mastor Cy | linder Filler Caps and Boot | |
| | Part No. | Description | |
| | ME474 | 1937-46 1-5/8" thread diametereach | 7.75 |
| | ME178 | 1947-59 1-1/4" thread diametereach | 9.50 |
| | ME103 | 1936-59 Rubber booteach | 4.95 |
| | | | |
| | - | Power Brake Unit, Rebuilt | |
| | | uild most hydrovacs for the 1 and 1 1/2 ton 1946 and older trucks frame n | |
| | - | only. (Please keep your brackets and fittings.) Totally cleaned, reb | ouilt, and |
| | • | used on larger GM trucks (frame mounted) | |
| | Part No. | Description | 205.00 |
| | REME121 REME122 | Overall length 15" incheseach Overall length 13" incheseach | 325.00 325.00 |
| | REME122 | Overall length 10" incheseach | 325.00 |
| | ME122 | Core charge for REME121 and REME122 | 525.00 |
| | | hydrovac cores onlycore | 270.00 |
| | | | 210.00 |
| | | POWER BRAKING as simple as a b c a Control Valve, hydraulically operated from the matter cylinder concerted from the matter concerted from the matter | |
| | | C Vacuum Power Cylinder connected to the Intake Manifold | |



| | 19.75 19.75 |
|---|----------------------------------|
| ME131 1937-45 3/4 ton with 14 inch brakes, and 1946-52 3/4 ton all (1-3/8" diameter) left or righteach 4 MEW326 1936-50 1 1/2 and 2 ton, (1-1/2" diameter) left or righteach 8 | 19.50 19.50 39.95 79.95 |
| ME335 1936-50 1/2 ton, 1936-43 3/4 ton with 11" brakes rear (1-3/16" bore)kit 1 ME338 1937-45 3/4 ton with 14" brakes, 1946-52 3/4 and 1 ton rear, and 1946-52 1 ton front (1-3/8" bore)kit 1 | 8.95 8.95 5.00 5.00 |
| | 2.50 4.95 |
| ME1431 2" x 12" 1946-52 3/4 ton rear and 1946-52 1 ton front, Must have core! set 8 ME513 2" x 14" 1946-52 1 ton rear and 1946-52 1 1/2 ton front , Must have core! | asure |

| Cartler | MECHANICAL | |
|--|--|---------------------|
| Truck Parts | visit our website for SPECIAL savings! | |
| | BRAKE PARTS (continued) • Brake Shoe, High Efficiency We have recently found a supplier of bonded brake shoe linings for 1936-50 1/2 t much higher "coefficient of friction". Rated FF. Used on large modern trucks, racing fork lifts, etc with better stopping ability. Best on the front axle where more braking is Part No. Description ME138FF 1936-50 1/2 Tonset ME299 Core charge for ME138FFcore | vehicles, |
| XIT X | • Brake Hardware Kit This kit replaces all return spring, adjusting hole plug, Brake shoe retaining cone sp "J" hook, brake shoe pin retaining warped washers small and large. Part No. Description MEB171 1936-50 1/2 tonkit | oring with 59.50 |
| and the second s | Brake Hose - Front and Rear Trucks require two front and one rear hose. Part No. Description ME136 1936-46 Alleach | 17.50 |
| | • Brake Hose Securing Clip, Zinc Plated Part No. Description MEB100 All yearseach | .95 |
| Front | • Brake Lines, Correct 1/4" Diameter | |
| | Formed and flared with fittings. Currently only 1/2 ton applications.Part No.DescriptionMEE2151936 Chevrolet and GMC 1/2 ton short bed, OE steel, 6 piece setsetMEE2131936 Chevrolet and GMC 1/2 ton short bed, | 170.00 |
| ~ | MEE214 stainless, 6 piece set | |
| | MEE216 OE steel, 7 piece setset MEE216 1937-40 Chevrolet and GMC 1/2 ton short bed, stainless, 7 piece setset | 160.00 185.00 |
| Rear | MEE2261941-46Chevrolet and GMC 1/2 ton short bed, OE steel, 7 piece setsetMEE2251941-46Chevrolet and GMC 1/2 ton short bed, | 160.00 |
| | stainless, 7 piece setset | 185.00 |
| | Brake Division Blocks We now stock the more in demand brass blocks used on your early GM truck brake These are usually found where metal brake lines changed diameters or connecte wheel cylinder. Brake Line Division Blocks Attaches to right rear axle housing where rubber brake hose meets two metal line Part No. Description MEE249 1936-50 All and 1951-65 3/4 thru 2 toneach | ed to rear |
| MEE246 | • Rear Wheel Cylinder Block Fits between rear wheel cylinder and axle brake line. Two per truck. Use your orig securing hollow bolt (or MEE244) that transfers brake fluid from line to wheel cylin Part No. Description | ginal |
| O | MEE246 1936-50 All and 1951-55 3/4 thru 2 ton 1960-63 3/4 and 1 toneach MEE244 1936-1950 Block Attaching Bolt and copper washers, Reareach rucks com ORDERS 1-800-862-1913 TECH HELP 2-4pm 1-816-2 | 18.00 4.95 |

66 oldchevytrucks.com ORDERS 1-800-862-1913 TECH HELP 2-4pm 1-816-252-5857



| | | (continued) e Return Springs 'Hucks" type brakes. Description | | |
|----------------|---|---|-------|------------------------|
| | ME146 ME148 MEB147 | 1936-50 1/2 ton front or rear and 1937-52 3/4 ton front (9/16"x 6") zinc plated 1936-52 front and rear (5/8"x 7 9/16") 1936-52 front and rear (5/8"x 7") | each | 2.95 11.50 15.00 |
| | | e Pin Retaining Warped Washers | | |
| \bigcirc | Part No. MEB324 MEB325 | Description 1936-50 Small 1/2" dia 1936-50 Large 15/16" dia. | | 1.75 1.95 |
| | • Brake Sho Part No. ME340 | e Retaining Cone Springs Description 1936-48 With retaining "J" hooks (per wheel) | set | 5.00 |
| MEB146 | Fits in small Part No. | ustment Hole Plugs rectangular holes in backing plate. Description | | 4 50 |
| ME145 | MEB146 ME145 | Metal snap in type, exact as GM made them Rubber push-in type | | 1.50 .50 |
| , e | • Park Brake Part No. ME286 MEB287 MEB225 | Description 1937-46 1/2 ton short bed (metal wrapped as original) 1937-46 1/2 ton short bed (vinyl cover replacement) | | 80.00 62.50 |
| | MEB285 MEB284 | 1937-45 3/4 ton (6 bolt wheels) 11" brakes (metal wrapped as original) 1937-45 3/4 ton (6 bolt wheels) 14" brakes | each | 64.50 |
| \sim | MEB286 | (metal wrapped as original) 1946 3/4 ton (8 bolt wheels) (metal wrapped as original) | | 64.50 64.50 |
| | • Park Brake Part No. MEB288 | e Cable Pulley Description 1934-46 (3" diameter with bolt) | each | 7.95 |
| | • Park Brake Part No. ME159 | e Cable Boot Description 1936-59 | pair | 3.75 |
| Color Color | • Park Brake Part No. ME161 | e Cable to Backing Plate Felt Gaskets Description 1937-55 1st | pair | 4.75 |
| | • Park Brake Part No. ME168 | e Cable Clip Description 1936-50 1/2 ton and 1947-52 3/4, and 1 ton. Fits on rear of cable | each | 7.95 |
| Jø_ | • Park Brake Part No. ME436 | e Lever Squeeze Handle Spring Description 1929-59 All models with vertical hand lever | each | 4.95 |
| DERS 1-800-862 | .1913 TECH | HELP 2-4pm 1-816-252-5857 oldchevvtruck | s.com | 67 |



...visit our website for SPECIAL savings! BRAKE PARTS (continued) Brake Drums Part No. Description **MEB125** 1936-50 Front 1/2 ton and 1936-45 3/4 ton (includes 6 studs) each 119.95 1936-50 Rear 1/2 ton, 1937-45 3/4 ton (without studs 6 studs) .. each 95.00 **MEB130 MEB126** 1946-52 Rear 3/4 ton (8 lug wheels)each 149.00 Wheel Bearings with Race - Front Description Part No. ME171 39.75 1929-59 1/2 ton outer.....each 1936-52 3/4, 1, and 1-1/2 ton inner.....each **ME390** 125.00 1936-52 3/4, 1, and 1-1/2 ton outereach ME391 51.80 **ME170** 1941-59 1/2 ton inner.....each 59.50 **MEB992** 1946-Mid 49 2 ton inner (1 9/16" inside diameter).....each 145.00 Wheel Bearings with Race - Rear Part No. Description **ME172** 1933-62 1/2 ton and 1936-39 3/4 ton outer.....each 55.50 **MEB994** 1936-57 1-1/2 ton outer, single speed axle.....each 62.00 1936-57 1-1/2 ton inner, single speed axleeach **MEB995** 82.00 ME392 1946-72 3/4 and 1 ton outer.....each 47.75 1946-72 3/4 and 1 ton inner.....each **ME435** 47.50 Spindle Castellated Nut Threads on spindle and secures wheel bearings. Allows use of required cotter pin. Part No. Description 1941-72 1/2 ton 3/4" x 20 threadseach ME504 2.95 Wheel Seals - Front Part No. Description **ME147** 1929-40 1/2 ton.....each 22.50 1935-59 3/4, 1, and 1-1/2 ton.....each **ME309** 17.95 1941-59 1/2 ton.....each **ME343** 15.95 1940-Early 49 2 ton.....each **ME798** 18.50 • Wheel Seals - Rear Part No. Description **ME149** 1933-62 1/2 ton and 1933-45 3/4 and 1 ton, (o.d. 2 3/4")each 27.75 1946-72 3/4 and 1 ton, (o.d. 3 15/16").....each ME304 10.75 ME677 1936-59 1-1/2 ton and 1936-53 2 ton,each 29.50



| | CLUTCH AND TRANSMISSION • Clutch Disc - New Replacement No core charge. Part No. Description MEE256 1938-53 1/2 ton, 9" normally with 3-speedseach MEE257 1938-53 1/2 ton, 10 3/4" normally with 4-speedseach | 59.00 69.00 |
|--------------|--|----------------------------------|
| | • Clutch Disc - Rebuilt General Motors Original Plus core charge. Part No. Description ME104 1938-53 1/2 ton, 9" normally with 3-speedseach ME405 1938-53 1/2, 3/4, 1, 1-1/2, and 2 ton, 10-3/4" normally with 4-speeds (for 9 bolt pressure plate)each ME106 Core charge for ME104core MEC366 Core charge ME405core | 49.50 69.50 20.00 65.00 |
| | Clutch Pressure Plates - Rebuilt Diaphragm type. Plus core charge. Part No. Description ME109 1938-53 1/2 ton, 9" normally with 3-speedseach ME407 1938-53 1/2, 3/4, 1, 1-1/2, and 2 ton, 10-3/4" normally with 4-speeds (9 bolts holding it to flywheel)each ME111 Core charge for ME109core MEC365 Core charge for ME407core | 94.50 89.00 25.00 65.00 |
| | Clutch Release Bearing with Housing For diaphragm pressure plate. Part No. Description ME113 1938-72 Throwout bearing for 6 cylinder. (1-7/8" long)each | 33.80 |
| 0 | Clutch Alignment Tool Part No. Description MEE242 10 splineeach | 6.95 |
| | • Clutch Pedal Pull-Back Spring Part No. Description ME112 1932-40each | 6.95 |
| | • Clutch Release Fork Ball Threads into bellhousing as original. Part No. Description ME518 1938-59 Six cylinder, 7/16" x 20" male threadeach | 12.50 |
| \mathbf{r} | Clutch Release Fork Ball Retaining Spring Clip Part No. Description ME458 1938-72 Fits in clutch release forkeach | 3.95 |
| | | |



| | CLUTCH AND TRANSMISSION (continued)• Clutch Pedal Floorboard BumperJust like GM made them. Your two fasteners secures perfectly to the holes in your toPart No.DescriptionME7611937-46Floor board bushingseach | beboard. 8.75 |
|------|--|-------------------------|
| | • Clutch Pilot Shaft Bushings and Bearings Presses into back of crankshaft. Part No. Description ME479 1940-72 Chevrolet, bushing, six cylinder and V-8each ME717 1931-39 Chevrolet and 1939-59 GMC, bearingeach | 4.75 41.50 |
| | • Clutch and Brake Pedal Shaft Bushings Part No. Description ME114 1929-46pair | 13.50 |
| | • Transmission Overhaul Gasket Set Part No. Description ME118 1938-54 3-speedset MEE121 1939-47 4-speedset | 15.50 20.00 |
| | Transmission Shift Repair Insert and Compression Spring Removes wear from original tower for a tighter shift. Brass. Part No. Description MET136 1937-47 3-speed floor shifteach | 19.95 |
| NEW! | • 4 Speed Lever Reverse Spring Fits by the shift knob and allows transmission to be put in reverse by driver's finge Part No. Description MET137 1934-46 4-speedeach | er. 18.95 |
| | Transmission Bearings Part No. Description ME303 1932-36 3-speed, front input shaft bearingeach ME301 1938-67 3-speed, front main input shaft bearingeach ME302 1937-54 3-speed, rear main shaft bearingeach | 39.55 52.50 47.50 |
| | • Transmission Countershaft, 7-1/8" Long Part No. Description MET108 1937-47 used only with bushingseach MET100 1948-59 used only with needle bearingseach | 35.00 46.75 |
| | • Transmission Flywheel Cover, Fiberglass Part No. Description MEE418 1937-59 6 cylindereach | 42.95 |
| | • Transmission Flywheel Ring Gear Part No. Description MEE494 1935-36 6 volt, 133 Teetheach MEE495 1937-54 6 volt, 139 Teetheach MEE496 1955-69 12 volt, 168 Teetheach | 75.00 44.95 29.00 |

...visit our website for SPECIAL savings!



| 0000000 | Transmission Needle Bearings, 3-Speed Part No. Description ME729 1940-54 Between cluster gear and countershaft, set ME741 1937-62 Between input shaft and front of main shaftset | 12.75 11.75 |
|---------|--|--------------------------------|
| | • Transmission Main Shaft Pilot Bearing Fit between front drive gear shaft and main shaft inside transmission. Part No. Description MET109 1931-47 4 speedeach | 24.50 |
| | • Transmission Small Parts Kit Includes needle bearings, thrust washers, snap rings, etc. Part No. Description MET150 1940-54 3-speed onlykit | 43.75 |
| | • Transmission Front Bearing Retainer Part No. Description MET110 1946-47 4 Speed (casting #591605)each MET111 1938-46 4 Speed (casting #591327)each | 45.50 45.50 |
| | COOLING SYSTEM• RadiatorNow available! A complete new radiator, not re-cored. For the original six cylinder Cpickup. Correct 3 tube row brass construction as was provided by GM for proper cPart No.DescriptionMER8101941-46 1/2 and 3/4 ton 3 coreeach | hevrolet cooling. 525.00 |
| | Radiator Support Core Mount Pads Part No. Description ME731 1940-46 Chevrolet and GMC (fits at sides)pair | 1.70 |
| ME196 | Radiator Caps Part No. Description MEE100 1934-36 Radiator cap Seahorse mascot, Chevroleteach ME270 1937-46 Non-pressure typeeach ME196 1937-46 4 pound rating (for pressure system only)each | 179.00 9.50 10.95 |
| | Radiator Hose Clamps Original flat type very close to those used by GM. Part No. Description ME197 1937-55 1st 216 engine, uppereach ME1981 1937-53 216 engine, lowereach | 2.50 4.50 |
| | Radiator Hose New black reinforced rubber to perfectly fit your truck. Part No. Description ME2811 1934-36 Straight upper hoseeach ME2812 1937-46 Straight upper hoseeach ME465 1937-46 One metal angle with pair of straight rubber hoses plus four clamps. Lower hoseset | 8.95 8.95 35.00 |
| ··· | • Radiator Overflow Tank Part No. Description MER815 1937-1955 GM Accessory. Attaches to firewalleach | 125.00 |
| | • Thermostat Part No. Description MEE490 1937-66 180 degreeeach -1913 TECH HELP 2-4pm 1-816-252-5857 oldchevytrucks.com | 8.95 |

 ORDERS
 1-800-862-1913
 TECH HELP 2-4pm
 1-816-252-5857
 oldchevytrucks.com
 71

| | Jan 🐡 | | |
|----|-------------|--|----------------------------------|
| C | Truck Parts | MECHANICALvisit our website for SPECIAL savings! | |
| | | Radiator Petcock Part No. Description ME7401 With brass 1/8" pipe threadeach ME740 With brass 1/4" pipe threadeach | 5.00 4.75 |
| | | Temperature Gauge Reduction Bushing For reducing size of hole in head when placing a 1955 and newer 235 engine in a 1900 older truck. Accepts mechanical heat tube from dash gauge. Part No. Description ME275 1955 and newer engine. Chevrolet onlyeach | 954 and 6.50 |
| | | Water Pumps - New No core charge. Part No. Description ME280 1941-52 Chevrolet with 5/8" groove pulleyeach | 120.00 |
| - | | Water Pump with Short Shaft Used when installing a 1955-62 235 engine in a 1937-55 Chevrolet truck. Elimination need to move the radiator forward. Includes proper narrow pulley with 3/8" groover a thousand sold! They work great.) Part No. Description REME205 1937-55 1st Chevrolet (no core charge) 4" diametereach If you prefer the pulley to be 7 1/4" diameter, to slow fan RPM as GM used, we h complete assembly. Recommended especially for the low ratio differential on larg with the later 235 installed. Part No. Description MEE391 | e. (Over 130.00 have the |
| - | | Water Pump Adapter Plate When placing a 1955-62Chevrolet in-line six cylinder in a 1954 and older truck s not want a modified short shaft low position water pump. If you prefer the high posit water pump in the stock location, this adapter plate is for you. Note: Requires drilling two 5/16" diameter holes in front engine block 3/4" deep a tap new threads. Part No. Description MEE390 Adapter plateeach | tion 216 |
| - | | Water Pump Graphite Packing Stops leaks around shaft of these early pumps. Part No. Description ME830 1926-36 Chevroletset | 6.00 |
| - | | • Fan - Correct 15" Overall Length Part No. Description MEE243 Fits 216 Engine. This unit also required on REME205 short shaft water pumpeach | 29.00 |
| 72 | | Fan Belts Part No. Description ME208 1937-52 Chevrolet. For 5/8" groove pulleyeach ME241 1939-59 GMC. For 3/8" groove pulleyeach ME240 1939-59 GMC. For 5/8" groove pulleyeach ME875 1937-55 Chevrolet. For short shaft water pump REME205each WERS.com ORDERS 1-800-862-1913 TECH HELP 2-4pm 1-816-25 | 14.95 19.75 22.75 15.50 |

72 oldchevytrucks.com ORDERS 1-800-862-1913 TECH HELP 2-4pm 1-816-252-5857



| | Carrier B | IAFT AND DIFFERENTIAL PARTS earings and Cushion | | |
|--|--|--|---------|-----------------|
| | Part No. | Description | a a a b | 47.50 |
| | ME397B ME397R | 1940-561/2 ton, inner axle carrier bearing1940-561/2 ton, inner axle carrier bearing race | | 47.50 19.50 |
| | MEB272 | 1946-72 3/4 and 1 ton, inner axle carrier bearing race | | 13.50 |
| | meder e | and race | each | 57.00 |
| | ME399 | 1946-53 3/4 ton, drive shaft carrier bearing | each | 39.50 |
| | ME467 | 1941-53 3/4 ton, drive shaft carrier bearing | | |
| | | rubber cushion | each | 11.50 |
| | • Pinion Se Part No. | eal for Differential Housing Description | | |
| | ME728 | 1941-45 3/4, 1, and 1-1/2 ton | | 13.00 |
| | ME427 | 1946-65 3/4, 1, and 1-1/2 ton | each | 18.95 |
| | | earing and Race | | |
| | Part No. | Description | aaab | 70 50 |
| | MEP394 ME395 | 1930-39 1/2 ton, front pinion bearing (double roller) 1940-54 1/2 ton, front pinion (double roller) | | 79.50 125.00 |
| | ME396 | 1936-54 1/2 ton, rear pinion | | 59.50 |
| | MEP397 | 1946-72 3/4 and 1 ton, front pinion assembly consists | ouon | 00.00 |
| | | of a pair of bearings and matching race | set | 225.00 |
| Ο | Special cop These were Part No. | al Housing Cover Bolt Washers oper coated crush washers used under bolt heads that secu e used by GM to prevent leakage of differential grease. Description | · | · |
| | MEE550 | 1/2 ton (copper coated) | each | 1.25 |
| | Differenti Part No. | al Housing Cover Gaskets Description | | |
| | ME292 | 1933-62 1/2 ton (For 10 bolt covers) | each | 8.50 |
| and the second sec | ME549 | 1946-72 3/4 and 1 ton | each | 10.50 |
| | | | | |



| | C C | DRIVE SHAFT AND DIFFERENTIAL PARTS (continued) • Universal Joint Repair Kit Connects the front and rear yolk on closed drive shaft systems. Part No. Description ME453 1940-54 1/2 ton only, 3 and 4-speed | 43.50 |
|---|---------------------------|--|-----------------------------------|
| | | • Universal Joint Lock Clip Replaces the bolt head retaining "bend over" clip between the 2 yolks. Part No. Description ME690 1940-54 1/2 ton only, 3 and 4-speed (included in ME453)each | 2.95 |
| | C. LINDING | • Universal Joint Lock Clip Bolt Part No. Description MES104 1940-54 1/2 ton (hardend steel) Made in USA!each | 3.20 |
| | | Universal Joint Housing and Bell Gasket Sets Part No. Description ME124 1935-54 1/2 ton, short bedset ME820 1937-54 GMC only. 1/2 ton, long bedset | 17.50 34.50 |
| | * ME125 ME127 ME127 | | embly 1960's 83.50 53.00 |
| | | • Drive Shaft Torque Tube Seal Only Fits in end of short tube extension beside front drive shaft bushing. Part No. Description ME126 1940-50 1/2 ton (included in ME125)each ME468 1937-54 3/4 and 1 toneach | 15.50 14.95 |
| - | | • Drive Shaft Extension, GMC Only Finally an exact heat treated replacement of the approximate 8 inch drive shaft used GMC long bed 1/2 ton. Limited production. Hand made in USA! Part No. Description ME470 1937-54 GMC 1/2 ton long bedeach 2 | on the 295.00 |
| | | • Drive Shaft Extension Bearing Used with ME470. Part No. Description ME470B 1937-54 GMC 1/2 ton long bedeach | 54.95 |

ENGINE ELECTRICAL

I.



| REME7431937 6 volteachREME4251938-55 1st 6 volt. With foot switch on topeach | 195.00 195.00 175.00 175.00 75.00 50.00 not use |
|--|---|
| Starter Drive Part No. Description ME763 1938-55 1st For 6 volt startereach | 25.00 |
| • Starter Drive Spring Part No. Description ME911 1934-37each | 18.95 |
| Starter Pedal Return Spring and Clip Part No. Description ME401 1938-59 six cylindereach | 6.95 |
| REME4497 1940-52 6 volt. 7" with 5/8" groove pulleyeach | 160.00 125.00 125.00 35.00 65.00 |
| | 125.00 115.00 30.00 |
| Distributor Vacuum Advance Quality zinc plated surface. Note: Will also fit 1937-38 Chevy. Part No. Description ME253 1939-62 Chevrolet and 1939-59 Inline six cylindereach | 39.95 |



...visit our website for SPECIAL savings!

ENGINE ELECTRICAL (continued)

| | Distributor Cap Part No. Description ME293 1933-53 Chevrolet 216 engine and 1939-59 GMC (2" tall) | each 17.50 |) |
|-----|--|--|--|
| | | | |
| | Distributor Rotor Part No. Description ME381 1933-53 Chevrolet and 1939-59 GMC | each 7.50 |) |
| No. | | | |
| | Part No. Description | |) |
| | Part No Description | | ; |
| | | Part No. Description ME452 1937-40 Chevrolet and 1939-59 GMM ME451 1941-48 Chevrolet, 10mm size Part No. Description ME293 1933-53 Chevrolet 216 engine and 1939-59 GMC (2" tall) ME293 1933-53 Chevrolet 216 engine and 1939-59 GMC (2" tall) ME293 1933-53 Chevrolet and 1939-59 GMC (2" tall) ME384 1933-53 Chevrolet and 1939-59 GMM ME385 ME384 1933-53 Chevrolet and 1939-59 GMM ME385 ME385 1954-62 Chevrolet and 1939-59 GMM ME385 ME381 1933-53 Chevrolet and 1939-59 GMM ME381 ME381 1933-53 Chevrolet and 1939-59 GMM ME381 ME381 1933-53 Chevrolet and 1939-59 GMC ME387 ME381 1933-53 Chevrolet and 1939-59 GMC ME387 ME381 1933-59 GMC ME387 GMM ME387 ME387 1933-62 Chevrolet Messare ME389 ME389 1939-59 GMC Messare GMM ME386 ME389 1939- | Part No. Description ME452 1937-40 ME451 1941-48 COMM Part No. Description ME451 1941-48 Common ME293 1933-53 Common ME384 1933-53 Common ME385 1954-62 Common ME381 1933-53 Common ME381 1933-53 Common ME381 1933-53 Common ME381 1933-53 Common ME381 1933-54 Common ME381 1933-59 Common ME381 1933-59 ME381 |



| | ENGINE COMPONENTS (continued) Motor Mount Shield The sheet metal cover that protects the front rubber mount from oil. An item that is usually missing. Part No. Description ME533 1932-55 1st Chevrolet and 1939-59 GMC six cylinderseach | 10.75 |
|-------------|---|----------------------------------|
| Measure K | • Motor Mount - Front For six cylinder engines, fits in your original steel housing. Part No. Description ME216 1932-55 1st and 1939-55 GMCeach | 11.50 |
| ME217 ME218 | Motor Mounts - Rear (per side) For six cylinder engines. Part No. Description ME217 1937-47 (3": wide)each ME218 1948-53 1/2 ton only, 2" wideeach | 22.00 19.95 |
| | Valve Cover Stud Top Seals Part No. Description ME214 1934-53 Chevrolet 216 engine and 1939-59 GMC | 2.75 |
| | Valve Cover Acorn Nuts For securing cover to head. Non-polished stainless steel. Looks original! Part No. Description ME213 1934-53 Chevrolet 216 engine and 1939-59 GMC | 5.00 |
| | Engine Gasket Sets (6 Cylinder) American made quality gaskets. Overhaul gasket sets. Part No. Description ME475 1935-36 Chevrolet 207 engineset ME210C1 1937-53 Chevrolet 216 engine and 1941-49 Chevrolet 235 low pressure engineset ME721 1938 GMC 223 (Pontiac engine), 1/2 ton onlyset ME210G1 1939-59 GMC 228, 236, 248, and 270 engineset | 99.95 167.50 |
| | Valve Job SetsPart No.DescriptionME211C11937-53Chevrolet 216 engine and 1941-49Chevrolet 235 enginesetME211G11939-59GMC 228, 236, 248, and 270 engineset | 57.50 67.95 |
| | Side Cover Sets Part No. Description ME365 1935-36 Chevrolet 207 engine | 19.25 15.50 15.50 15.50 |



| | Timing Cov | ONENTS (continued) ver Sets skets and crankshaft seal! Description | |
|-----------------|---------------------------|---|----------------|
| | ME734 | 1937-53 Chevrolet 216 engine and 1941-62 Chevrolet 235 engineset | 16.95 |
| | ME7341 | 1939-59 GMC 228, 236, 248, and 270 engineset | 18.95 |
| | Oil Pan Set | | |
| | Part No. ME771 | Description 1934-36 Chevrolet 207 engineset | 15.75 |
| | ME116C | 1937-39 Chevrolet 216 engineset | 14.95 |
| | ME116C1 | 1940-53 Chevrolet 216 engine and | 14.95 |
| | ME116G1 | 1941-55 1st Chevrolet 235 engineset 1939-59 GMC 228, 236, 248, and 270 engineset | 14.95 |
| | Valve Cove | | |
| | Part No. ME772 | Description 1935-36 Chevrolet 207 engineset | 13.75 |
| | ME212C1 | 1937-53 Chevrolet 216 engine and | |
| | ME212G1 | 1941-53 Chevrolet 235 engineset 1939-59 GMC 228, 236, 248, and 270 engineset | 12.50 14.50 |
| | MEZ IZG I | 1939-39 GMC 220, 230, 240, and 270 engine | 14.50 |
| | | Between Head and Manifolds) | |
| | Part No. ME3673 | | 15.00 |
| Q Q | ME255C1 | 1937-53 Chevrolet 216 engine and | |
| | ME255G1 | 1941-49 Chevrolet 235 engineset 1939-59 GMC 228, 236, 248, and 270 engine, | 14.95 |
| | ML20001 | except 1950-54 GMC 270 engineset | 15.95 |
| | Engine Inta | aka Pinas | |
| | Fits betwee | n head and manifold. (set of 3) | |
| | Part No. ME236 | Description 1934-53 Chevrolet 207 and 216 engine, | |
| | IVIE230 | 1941-49 Chevrolet 235 engine, and | |
| | ME007 | 1939-59 GMC engineset | 7.50 |
| | ME237 | 1950-62 Chevrolet 235 and 1954-59 GMC 302 engineset | 7.50 |
| | Manifold / | | |
| 229 | Part No. | Between Intake and Exhaust) Description | |
| (La constructor | ME367 | 1934-53 Chevrolet 216 engine, 1941-49 Chevrolet 235 engine, | |
| \sim | | 1939-59 GMC 228 and 248 engine, 1942-46 GMC 236 engine, and 1939-59 GMC 270 engineeach | 4.50 |
| | | | 4.00 |
| | | To Manifold Gasket | |
| | Part No. ME446 | Description 1934-36 Chevrolet 207 engine, | |
| 0 | | 1937-53 Chevrolet 216 engine, | |
| | | 1939-59 GMC 228, 236, 248, and small port 270 engineeach | 7.50 |
| | | | · - |
| | | | |



| | ENGINE COMPONENTS (continued) Thermostat Part No. Description MEE490 1937-66 180 Degree temperature (inline six cylinder)each 8 | 8.95 |
|--|--|--------------|
| | 0 0 | 2.00 1.95 |
| | Crankshaft Rear SealsPart No.DescriptionME6831940-53 Chevrolet 216 engine, 1941-62 Chevrolet 235 engine, and | |
| | ME6834 1940-53 Chevrolet 261 engine, original rope typeset 1940-53 Chevrolet 216 engine, 1941-62 Chevrolet 235 engine, and | 9.65 |
| | 1954-62 Chevrolet 261 engine, Hi-tech ropeset 24 | 4.00 4.00 |
| | • Valve Stem Oil Seals Oil burning in your Chevrolet engine is often due to deteriorated valve stem seals. The seals are inexpensive and not difficult to install. Set includes umbrella and O-ring. Part No. Description ME5521 1941-72 Six cylinder, 216,235 & 250 engine (set of 12)set | nese 7.95 |
| | Rocker Arm Shaft-Chevrolet | |
| | Part No.DescriptionME2411937-39 216 engine, two per engine (when available)pairME2421940-53 216 engine, 1941-62 235 engine, and | 0.00 9.75 |
| | Push Rods Solid lifter type for truck engines. | |
| O | Part No.DescriptionME2431940-53ME24411954-62Chevrolet 235and 261engine and | 5.50 4.95 |
| and a state of the | Lifters Mechanical. Part No. Description ME507 1940-53 Chevrolet 216 engine, 1941-55 Chevrolet 235 engine, 1939-55 GMC 228, 248 and 270 engineseach 2 ⁻¹ | 1.95 |



| | Camshaft | e | |
|--|--|--|-----------|
| ann | | s with mechanical lifters. | |
| A CONTRACT OF | Part No. | Description | |
| | ME510 | 1937-53 Chevrolet 216 engineeach | 149.00 |
| Ø | | Thrust Plates | |
| | | n camshaft and gear. | |
| (()) | Part No. | Description | |
| | ME727 | 1937-62 Chevrolet six cylindereach | 13.60 |
| ×. | ME990 | 1939-59 GMC six cylindereach | 15.95 |
| | ENGINE CO | OMPONENTS (continued) | |
| | Camshaft | | |
| | | rox. 2" I.D. journals. | |
| international in | Part No. | Description | |
| | ME658 | 1937-53 Chevrolet 216 engine, | |
| | | 1941-54 Chevrolet 235 engine, | |
| tanian danaran araa ah | | 1954 Chevrolet 261 engine, | |
| | | 1939-59 GMC 228 and 248 engine, | |
| | | 1939-62 GMC 270 engine, and | |
| | | 1952-59 GMC 302 engineset | 34.50 |
| - MAR | • Valves - Ir | | |
| | Part No. | Description | |
| | ME246 | 1941-53 Chevrolet 216 engine and | 47 50 |
| | ME247 | 1941-49 Chevrolet 235 engineeach | 17.50 |
| | | 1939-51 GMC 228 and 248 engine (1/2 dome pistons)each | 21.00 |
| and the second sec | • Valves - E | | |
| | Part No. | Description | 47 75 |
| | MEE125 | 1941-49 Chevrolet 216 and 235. (30°)each | 17.75 |
| | ME249 | 1939-51 GMC 228 and 248 engine (1/2 dome pistons)each | 19.50 |
| | | ts – Exhaust, Hardened | |
| | | n you have a concern of wearing down the original valve seats due to | o lack of |
| | | ern gasoline. | |
| | Part No. | Description | 4.00 |
| | MEE126 | 1937-53 Chevrolet 216each | 4.00 |
| | Valve Gui Part No. | | |
| | ME524 | Description 1941-62 Chevrolet 216 and 235 engine, intakeeach | 4.00 |
| | ME525 | 1941-62 Chevrolet 216 and 235 engine, exhausteach | 4.00 |
| | MEE124 | 1939-59 GMC six cylinder, intake and exhaust | 4.00 |
| | | specify engine (special order)each | 5.00 |
| Camshaft Gear | • Timing Ge | ears - Camshaft | |
| ssource K | Part No. | Description | |
| i alla | ME439F | 1937-62 Chevrolet and | |
| | - | 1939-59 GMC. Fiber, for quieter operationeach | 42.50 |
| Source and | ME439A | 1937-62 Chevrolet and | |
| Timing marks 20 | | 1939-59 GMC. Aluminum, as original on truckseach | 46.50 |
| nk Gear 7 ¹ | | | |
| | 1 | | |



| Camshaft Gear | | | |
|---------------|--|--|---|
| | ENGINE COMPONENTS (continued) • Timing Gears - Crankshaft Part No. Description ME512 1937-39 Chevrolet and 1939-59 GMC | | 72.50 |
| Crank Gear 7 | ME440 1940-62 Chevrolet | each | 25.00 |
| | Piston Aluminum, and Ring Sets, Six Cylinder We are the source for Chevrolet six cylinder pistons from 1937 thro in stock and some will be ordered for you. All recently manufactured p not cast iron. As pistons always require new rings, we provide these in matched s web site for the exact part number on piston and ring sets not listed o Part No. Description MEE613 STD 1937-40 Chevrolet 216 piston and rings MEE614 .010 1937-40 Chevrolet 216 piston and rings MEE615 .020 1937-40 Chevrolet 216 piston and rings MEE616 .030 1937-40 Chevrolet 216 piston and rings MEE617 .040 1937-40 Chevrolet 216 piston and rings MEE618 STD 1941-53 Chevrolet 216 piston and rings MEE619 .010 1941-53 Chevrolet 216 piston and rings MEE620 .020 1941-53 Chevrolet 216 piston and rings MEE621 .030 1941-53 Chevrolet 216 piston and rings MEE622 .040 1941-53 Chevrolet 216 piston and rings MEE623 STD 1954-62 Chevrolet 235 piston and rings MEE625 .020 1954-62 Chevrolet 235 piston and rings MEE626 .030 1954-62 Chevrolet 235 piston and rings MEE627 .040 1954-62 Chevrolet 235 piston and rings MEE628 STD 1959-51GMC, special order only ME4848 STD 1939-51GMC, special order only ME4848 STD 1939-51GMC, special order only | bistons are all sets below. C on this page. set | uminum, heck our 320.90 320.90 320.90 320.90 320.90 259.95 259.95 259.95 259.95 259.95 259.95 259.95 259.95 259.95 259.95 259.95 259.95 259.95 259.95 259.95 259.95 259.95 |
| | ME4840 Oversize 1939-51 GMC, special order only (specify siz Piston Rings Sets Only Ring groove for the Chevrolet 216 and 235 low pressure engine dimensions as follows: 12 x compression rings 1/8", and 6 x oil rings 3 the part number below to order aluminum replacements 1941-53 Part No. Description ME3680S STD 1937-53 Chevrolet 216, cast iron pistons ME36802 .020 1937-53 Chevrolet 216, cast iron pistons ME36803 .030 1937-53 Chevrolet 216, cast iron pistons ME36804 .040 1937-53 Chevrolet 216, cast iron pistons ME36806 .060 1937-53 Chevrolet 216, cast iron pistons ME36807 .020 1941-62 Chevrolet 216, cast iron pistons ME36807 .020 1941-62 Chevrolet 235, aluminum pistons ME36703 .030 1941-62 Chevrolet 235, aluminum pistons ME36704 .040 1941-62 Chevrolet 235, aluminum pistons ME36706 .060 1941-62 Chevrolet 235, aluminum pistons ME36706 .060 1941-62 Chevrolet 235, aluminum pistons ME36708 STD 1941-62 Chevrolet 235, aluminum pistons ME36708 .060 1941-62 Chevrolet 235, aluminum pistons ME36709 .060 1941-62 Chevrolet 235, aluminum pistons ME3690 STD 1939-51 GMC special order only ME3690 Oversize 1939-51 GMC special order only (specify size ME3690 Oversize 1939-51 GMC special order only ME3690 Oversize 1939-51 GMC special o | are the usu 3/16". Add an 3 216 engine set set set set set set set set set set set set set set set set set | A after 65.50 65.50 65.50 65.50 65.50 65.50 65.50 65.50 65.50 65.50 65.50 65.50 |



...visit our website for SPECIAL savings!

NGINE COMPONENTS (continued)

| ► I | ENGINE COMPO | NENTS (continued) | |
|-------|--------------|---|-----------|
| | • Engine Cra | ankshaft Main Bearing Inserts | |
| | Part No. | Description | |
| | NOME305S | STD 1937-39 New Old Stock Chevrolet 216 engine | |
| | | (when available)set | 195 00 |
| | NOME305U | Undersize 1937-39 New Old Stock Chevrolet 216 engine | 100100 |
| | NOMECCO | (when available)set | 195.00 |
| | | STD 1940-47 New Old Stock Chevrolet 216 engine | 155.00 |
| | NOIVIL4200 | | 195.00 |
| | | (when available)set | 195.00 |
| | NOME4200 | Undersize 1940-47 New Old Stock Chevrolet 216 engine | 105.00 |
| | | (when available) | |
| | ME516S | STD 1939-62 GMC six (Special order only!)set | 250.00 |
| | ME516U | Undersize 1939-62 GMC six (Special order only, | |
| | | specify size!)set | 250.00 |
| | | nu stin u Dad Ina st Dasnin us | |
| | - | nnecting Rod Insert Bearings | |
| | | REME371 (216 engine) machined insert type rod. | |
| | Part No. | Description | |
| | ME372S | STD 1937-53 216 engine and | |
| | | 1941-53 235 engine, Chevroletset | 197.50 |
| | ME372U1 | .010 1937-53 216 engine and | |
| | | 1941-53 235 engine, Chevroletset | 197.50 |
| | ME372U2 | .020 1937-53 216 engine and | |
| | | 1941-53 235 engine, Chevroletset | 197.50 |
| | ME372U3 | .030 1937-53 216 engine and | |
| | | 1941-53 235 engine, Chevroletset | 197.50 |
| | ME517S | STD 1939-59 GMC (Special order only!)set | |
| | ME517U | Undersize 1939-59 GMC (Special order only, | |
| | | specify size!)set | 250.00 |
| | | | |
| | • Engine Co | nnecting Rod - Babbit Type | |
| | Rebuilt with | new poured babbit material. We must have your rod forging numbe | rs. Plus |
| | core charge. | Exchange only. | |
| | Part No. | Description | |
| | REME307S | STD 1937-47 Chevrolet 216 engine and | |
| | | 1941-47 Chevrolet 235 engineset | 450.00 |
| Cart- | REME307U | Undersize 1937-47 Chevrolet 216 engine and | |
| | | 1941-47 Chevrolet 235 engineset | 450.00 |
| | ME308 | Core charge if connecting rods are ever available, per set. | 100.00 |
| | ME000 | All nuts and bolts must be sent in with corescore | 90.00 |
| | | | |
| | • Engine Co | nnecting Rod - Insert Type | |
| ASA. | - | nachined to accept insert bearings ME372. Your rods are no longer the | original |
| | | Exchange only. | e onginai |
| | Part No. | Description | |
| | REME3711 | • | 150 00 |
| | | 1937-47 Chevrolet 216 engineset | 450.00 |
| | ME308 | Core charge for connecting rods, per set. | 00.00 |
| | | All nuts and bolts must be sent in with corescore | 90.00 |
| | _ | | |



| ENGINE COMPONENTS (continued) • Plastigage For accurately measuring the clearance of babbit main and rod bearings in the 216 er Necessary when setting bearing clearances. Use at the workbench or in the truck. Clearange .001 to .003. Part No. Description ME661 12 Stripsset | |
|--|------------------|
| Oil Pumps - New Part No. Description ME250 1941-53 Chevrolet 216 engine and 1941-53 Chevrolet low pressure 235 engineeach | 199.50 |
| • Oil Pump Repair Kit Part No. Description ME2911 1939-59 GMC 228, 248, 270, and 302 engineeach | 69.50 |
| • Oil Line Tube Consists of copper line and soldered brass fittings necessary for installation. O pressured oil from pump through engine to rocker arms. Part No. Description MEO199 1937-53 Chevrolet 216 engineeach | Carries 29.00 |
| Oil Pan Drain Plug, Original Part No. Description MEO208 1938-72each | 2.95 |
| • Oil Pan Plug Repair When your oil pan drain threads are damaged and leaking, don't replace or remove th This patented winged drain plug saves time and money. No special tools. Part No. Description MEO207 1938-72each | ne pan. 18.95 |
| • Engine Block Freeze Plug Kit Part No. Description MEE254 1937-62 Chevrolet 216, 235, and 261 enginekit | 14.95 |
| • Camshaft Freeze Plug We just found a supplier for the rear engine camshaft freeze plug! Its sides are short oil drain-back hole is not covered. Part No. Description MEE331 1929-36 207 engineeach | so the 9.00 |
| • Oil Line Brass Fittings On left side where dash gauge out line attaches to block. Part No. Description MEO197 1937-62 Original dash gauge, oil line to blockeach MEO198 1941-62 T-Fitting. Connects above line fitting and accessory oil filter lineeach | 3.50 6.75 |

| (| Jim () Arter Truck Parts | MECHANICAL visit our website for SPECIAL savings! |
|---|--------------------------------|---|
| A | | visit our website for SPECIAL suvings! |
| | | Engines - Used Short Block We supply used short blocks for the 216 and 235 1937-62. These are one of the "greats" of past Chevrolet engines. (Does not include head.). Ready for rebuilding. All new component for rebuilding are available in this section. Part No. Description USED 1937-39, 1940-47, 1948-53 216 engine, Inquire! |
| | | •Used Head Checked for cracks! Needs valves, guides, etc. Call on Availability! Part No. Description Used Chevrolet 216 (Specify year)each Inquire Used Chevrolet 235 (Specify year)each Inquire |
| | | EXHAUST PARTS •Exhaust Manifold We are in the process of producing the cast iron single barrel manifold as used on the hig oil pressure 235 Chevrolet six cylinder 1954-62 engine. Just like GM made them. Even includes the heat riser assembly and spring. All is a bolt-on assembly. No dual exhaust system required. Part No. Description MEE326 1950-53 216 and 235 low pressure engine, Avail. Dec. 2014each 235.00 |
| | | • Exhaust Pipe Gaskets We stock the following gaskets (between manifold and exhaust pipe). Specify your style. Part No. Description ME526 2" donut gasket |
| | | Exhaust Manifold Stud And Special Brass Nut |
| | | Holds exhaust pipe to cast iron manifold. Part No. Description MEE344 1938-72 Holds pipe to manifoldeach 3.00 |
| | | • Exhaust Manifold Filler Paint Hi-temp silver paste fills rust pit holes. Gives a new appearance. Part No. Description MEE324 1936-72 (3 oz jar)each 15.0 |
| | | • Heat Riser Spring Fits beside six cylinder exhaust manifold. This is a special bi-metalic spring that expand with engine heat. Part No. Description ME188 1937-65each 17.7 |
| | | • Tailpipe Heat Shield Part No. Description BP147 1934-46 Chevrolet and GMC. Protects bed wood from tailpipe heateach 7.9 |
| | | • Tailpipe Hanger Part No. Description ME234 All years (universal type)each 6.0 ME540 1941-55 1st Formed with flat steel, as originaleach 8.5 |
| | | |



| | Muffler We had these round heavy duty aluminized units reproduced so you could have the the factory dimensions. 25" long overall,20" body, 5" diameter,2" inlet,1 3/4" outlet. back the original sound. Part No. Description ME232 1934-62 Chevrolet and GMC. | |
|--|--|----------------------------------|
| | Muffler Clamps Part No. Description ME528 All years. Rear 1-7/8" outlet, fits on ME232 mufflereach ME529 All years. Front 2" inlet, fits on ME232 mufflereach | 2.25 2.50 |
| | Muffler Hanger Assembly Original band type for ME232 above. Includes hardware. Part No. Description ME233 Chevrolet and GMCeach | 14.95 |
| | FRONT END AND STEERING PARTS • Kingpins with Bushings Part No. Description ME523 1934-39 1/2 ton, and 1937-39 3/4, and 1 ton. STD | |
| | Drag Link, Complete with Internal Hardware. Part No. Description MES400 1937-46 1/2, 3/4, 1, and 1-1/2 ton each | 66.70 |
| ()) (| • Drag Link Repair Kit Rebuilds original style ends. Included in MES400. Part No. Description ME180DL 1929-52 1/2, 3/4, 1, and 1-1/2 ton. Both endsset | 34.95 |
| | Tie Rod Part No. ME437 Description 1937-55 (Approximately 43 1/4 " Long)each | 45.00 |
| INE348 | Tie Rod Ends Note: The modern 1/2 ton tie rod end assemblies were introduced in the 1960's to r the original multi-piece system. They attach to the tie rod as one piece unit. Helps steering easier. Part No. Description ME347L 1934-59 Left, 1/2 ton, left, modern type * | 39.95 39.95 43.95 43.95 |

| \mathbb{C} | ancer . | MECHANICAL | |
|--------------|---------------------|--|--------------------------|
| | Truck Parts | visit our website for SPECIAL savings! | |
| | | FRONT END AND STEERING PARTS (continued) | |
| | | Tie Rod End Repair Kit Rebuilds the original style multi-piece ends. Part No. Description | |
| | | ME180TR 1929-59 1/2, 3/4, and 1 ton. Both endskit | 34.95 |
| | \mathcal{A} | • Tie Rod and Drag Link Replacement Balls Hardened steel. Replace egg shape worn balls which makes proper steering adj impossible. (1/2 ton unless stated.) Part No. Description | |
| | | ME274 1934-46 Non-threaded as original (set of 4)set ME274T 1934-46 Like ME274 except threaded for | |
| 2 | | easy installationset ME265N 1934-59 For tie rods only. Non-threaded as | 48.50 |
| | | ME265T 0riginal straight shaftpair ME265T 1934-59 For tie rods only. Like ME265N except threaded | 28.00 |
| | | for easy installation straight shaftpair | 28.75 |
| | | ME691N 1934-46 For drag link only. Non-threaded as originalpair ME691T 1934-46 For drag link only. Like ME691N except threaded | 23.75 |
| | Mr. NE66A | for easy installationpair ME664 1946-59 3/4 ton. For tie rods only. Threaded ends and | 26.75 |
| _ | F . | tapered shaft for easy installationpair | 59.50 |
| | | Steering Sector Seal and Two Bushings Helps tighten steering. Included in rebuilt units. Part No. Description ME297 1937-46set | 24.95 |
| | MES124 | Steering Gear Box Gaskets. Part No. Description | |
| | | MES123 1937-40pair | |
| | MES123 | MES124 1941-46pair | 5.50 |
| M | IES148 | Steering Box Repair Parts 1941-46 Makes your truck steer like New! Part No. Description MES148 Steering Box Worm Gear assembly and shaft 49 5/16" long . each MES141 Steering Box Worm Gear bearing and race | 235.00 34.50 75.00 |
| - | | FUEL SYSTEM | |
| | ME221 | See CAB RELATED PARTS for Gas Filler Neck Grommets. • Fuel Pumps 1937-62 Chevrolet and 1939-59 GMC. Part No. Description | |
| é | | ME221 "Metal Top" type. Excellent replacementeach ME737 "Glass Top" type, as originaleach | 59.95 64.95 |
| | | ME222 "Double Action" metal top type. Designed to also | 04.90 |
| | ME737 Service ME222 | act as a vacuum booster to help stop "slow down" of wiper motoreach | 110.00 |
| | | | |
| 86 | oldchevyt | rucks.com ORDERS 1-800-862-1913 TECH HELP 2-4pm 1-816- | 252-5857 |



| | Fuel Systems (continued) • Fuel Pump Rebuilding Kit For reconditioning the original GM single action "glass top" units. Part No. Description ME228 1937-62set 48.75 |
|--------|--|
| | Fuel Pump Inlet Brass Fitting Part No. Description MEE608 1934-62 allows fuel line to attach to fuel pumpeach 4.95 |
| | Fuel Pump Diaphragm The main part normally needed to repair this basic early GM fuel pump. Part No. Description ME837 1934-36 Chevroleteach 14.90 |
| 5 | • Fuel and Vacuum Advance Lines These are used to connect the 2 differant lines that run from the carburetor to the vacuum advance and fuel pump. Just like GM made them! Clips sold below. Part No. Description MEE192 1937-40 Chevrolet, OE steelpair 56.95 MEE193 1937-40 Chevrolet, stainlesspair 61.95 |
| | • Fuel Line From fuel pump to original carburetor. 100% authentic in appearance, application, and fit! These are formed to fit with original Carter W-1 carburetors. Part No. Description MEE200 1941-49 Chevrolet, OE steeleach 24.50 MEE201 1941-49 Chevrolet, stainlesseach 32.50 |
| | • Clip for Fuel Pump & Vacuum Advance Lines Part No. Description MEE195 1937-62 Set of threeset 6.50 |
| MEE195 | Carburetor - Rebuilt Plus core charge. Includes base gasket. (Check on availability!) Part No. Description REME838 1932-36 Chevrolet (Carter W-1)each 225.00 REME538 1937-40 Chevrolet (Carter W-1)each 225.00 REME223 1941-48 Chevrolet (Carter W-1)each 215.00 REME519 1937-53 Chevrolet (Carter Y-F) For the 216 engine. A popular after market unit during those yearseach 215.00 ME267 Core charge for Chevrolet unitscore 50.00 REME7621 1939-46 GMC (Zenith) With smooth upper top, we must have coreeach 225.00 REME762 1947-59 GMC (Zenith) With ridge on top to hold air filter, we must have core |
| | Carburetor Repair Kits Please remember many of the GM carburetors are interchangeable. During the last 50 years the exact unit was not always used as a replacement. For example, the GMC Zenith carbs were often replaced with units from Chevrolet 216 engines. Therefore, it is very important to check your carburetor before ordering a repair kit. Hint: The W-1 carb's are cast iron. The others are die cast. Sorry, we can't take back kits once they have been opened. Part No. Description ME2821 1932-40 (Carter W-1) |

| | Jin 📀 | MECHANICAL | |
|---|-------------|---|----------------------------------|
| | Truck Parts | visit our website for SPECIAL savings! | |
| | | FUEL SYSTEM (continued) • Carburetor Repair Kits (continued) Part No. Description ME473 1937-62 Chevrolet and GMC (Carter Y-F) | 44.95 59.00 49.00 56.50 |
| _ | Ø | Carburetor Insulator Plates Slows heat transfer from intake manifold to carburetor. Exact as original. 1-1/2" th 2-1/2" center to center. Part No. Description ME273 1934-53 Chevrolet 216, 1941-49 Chevrolet 235 low pressure, 1939-59 GMC 228, 236, 248, and 1941-62 GMC small port 270, six cylinder engine | nroat, 9.95 |
| | | Carburetor Gas Filter An authentic GM option which helps in removing dirt particles and water before enter carburetor. Almost identical to original including metal top, glass bowl, and interrest taches to side of carburetor. Part No. Description ME668 Carburetor gas filtereach | |
| | | Carburetor Gas Filter Element Part No. Description ME669 Replacement element for ME668 aboveeach | 7.50 |
| - | | Carburetor Inlet Brass Fitting Part No. Description MEE608 1934-62 allows fuel line to attach to carburetoreach | 4.95 |
| - | | Accelerator Swing Bracket Bolt, Made in USA!. Part No. Description MEE296 1937-49 Threads into left side of engine blockeach | 19.50 |
| | | Accelerator Linkage Return Spring Lower Clip Secures to an oil pan bolt and attaches to the lower end of the vertical linkag spring. Made in USA! Part No. Description MEE295 1941-53each | e return 4.00 |
| | | Accelerator Linkage Return Springs, Vertical Part No. Description ME402 1937-40each ME459 1941-53. Made in USA!each | 4.00 7.50 |
| | | Throttle Cable Brass Wire Stop Attaches to end of cable beside carburetor. Part No. Description ME403 1937-59 Fits beside carburetoreach | 1.75 |



| FUEL SYSTEM (continued) • Air Filter Assembly, Original Style Created to copy the original 6 5/8" diameter dry element design. Looks very close to the factory original. Fits the Rochester, Zenith, and Careplacements, not the early Carter W-1 cast iron style. To create an even more autok, you might consider the copper mesh element, ME238 below. Part No. Description ME904 1950-55 with original black top ME907 1950-55 with chrome top | rter YF ithentic 64.50 72.50 |
|---|---|
| Air Filter Element-Oil Wetted Type, Not Oil-Bath Design When using the original standard metal mesh GM air filter on top of carburetor. Part No. Description ME424 1936-40 7" diameter copper mesh. Exact originaleach ME238 1941-55 6" diameter copper mesh. Exact originaleach ME2381 1941-55 6" hi-tech style paper. ME238 replacementeach Note: Show quality ME424 and ME238 is the oil-wetted type originally used. Req light coating of oil to be effective. | 28.50 31.50 16.95 uires a |
| • Air Filter Retainer Wing Nut Fits the smaller #10 fine thread stud on earlier air filters. Part No. Description ME231 1936-46each | .95 |
| | 275.00 350.00 |
| • Gas Filler Spout A metal spout that extends through bed side and attaches to tank MEG146 above gas cap ME496. Part No. Description MEG132 1934-36each | e. Uses 22.95 |
| • Gas Tank Straps Part No. Description MEG103 1934-36 Secures tank under rear of bedset MEG104 1939-46 Secures tank under seatset | 32.00 49.50 |
| • Gas Tank Installation Pads Protects under seat tank from straps. Part No. Description MEG123 1939-46set | 11.95 |
| Gas Tank Sending Unit and Float, Stainless steel to resist rust. 6 or 12 volt. 0-30 ohm as original. Part No. Description MEG124 1934-46 under the seat tankeach MEG110 1934-59 Adjustable for all models with under bed tankseach | 44.95 35.00 |
| | Air Filter Assembly, Original Style Created to copy the original 6 5/8" diameter dry element design. Looks very close to the factory original. Fits the Rochester, Zenith, and Ca replacements, not the early Carter W-1 cast iron style. To create an even more au look, you unght consider the copper mesh element, ME238 below. Part No. Description ME904 1950-55 with original black topeach ME907 1950-55 with original black topeach ME907 1950-55 with original black topeach ME424 1936-40 7" diameter copper mesh. Exact originaleach ME424 1936-40 7" diameter copper mesh. Exact originaleach ME238 1941-55 6" diameter copper mesh. Exact originaleach Mote: Show quality ME424 and ME238 is the oil-wetted type originally used. Req light coating of oil to be effective. Air Filter Retainer Wing Nut Fits the smaller #10 fine thread stud on earlier air filters. Part No. Description ME231 1936-46 |



| | FUEL SYSTEM (continued) • Gas Tank Floats Part No. Description ME718 1934-46 Coated cork as original | 6.25 |
|---------|--|------------------------------------|
| | Gas Tank Shut-Off Valve Threads into tank and connects to horizontal rubber flex line MEG128. Brass as ori Part No. Description MEG137 1937-46each | iginal. 15.75 |
| | Gas Tank Sender Gasket Fits on top of tank. Included in MEG124. Part No. Description ME490 1936-66 Improved cork and rubber blendeach | 1.95 |
| | • Gas Tank Flex Hose Fits between tank shut-off valve and metal line. Part No. Description MEG145 1934-36 includes shut off valveeach MEG128 1937-46each | 36.50 26.50 |
| | Gas Cap - Part No. Description ME496 1938-71 Non-locking Typeeach MEE103 1938-71 Chrome locking Type, 2 keys without Bowtieeach ME497 1938-66 Chrome, 2 keys. With Chevrolet Bowtieeach Note: See "Cab Related Parts" section for gas filler neck grommet, filler hose, clamps, a | 9.95 23.95 37.95 and etc. |
| | HEATING SYSTEM Heater Core, Recirculator We now have the correct diameter round heater core for the original GM firewall m unit. Solder on the tanks from your heater if you have a bad core. Made in USA! Part No. Description MEH244 1941-46 round O.D. 8 1/4" x I.D. 2 7/8"each | ounted 289.95 |
| | Heater Valve for Recirculator Heater Fits in water pump outlet as original when using a recirculator heater. Turn valve to re water flow into heater core. For 5/8" diameter hose. Part No. Description ME364 For recirculator heaterseach | egulate 46.75 |
| and the | Heater Hose Water Shut Off Valve Fits in heater hose. Not original, but works excellent. Can be connected to operate cable from inside cab. Part No. Description ME792 All yearseach | e with a 47.95 |
| | Heater Hose Connectors Connects 5/8" heater hose to water pump and/or thermostat housing. Part No. Description MEH153 2 3/4" lengtheach MEH154 1 1/2" lengtheach | 8.50 7.50 |



| HEATER SYSTEM (continued) |
|---|
| Heater Hose Part No. Description ME769 5/8" Specify lengthfoot 1.75 |
| • Heater Hose Clamp Part No. Description ME204 Original flat type as used by GMeach 1.75 |
| Heater Duct Tubing Connects heater to defroster duct under dash. Cut length to fit. Part No. Description ME283 1936-46 (1-1/2" diameter)set 26.95 |
| MISCELLANEOUS MECHANICAL • Crankshaft Pulley Sleeve Metal sleeve fits over original crankshaft. Eliminates unwanted worn groove on crankshaft created by timing cover seal which may cause oil leaks. Pulley must be removed to install. Part No. Description ME256 1937-72 Chevrolet six cylinder and 1939-59 GMC six cylinder |
| Hub Cap Wheel Clips Secures original hub caps to factory wheels. Made with spring steel as original. Nicely replaces rusted and broken clips. Made in USA! Part No. Description ME150 1936-60 1/2 toneach 1.95 |



| \mathbf{v} | MISCELLANEOUS MECHANICAL (continued) | | |
|--------------|---|---|-------------------------------------|
| | • Oil Cap Part No. ME271 | Description 1937-48 Chevrolet and most GMC's. Fits on top of side breather pipeeach | 3.00 |
| | • Oil Filter (Disposable Part No. ME289 ME756 ME373 | Cartridges cartridge inside canister type filter assembly. Not late model spin on ty Description 1937-62 Chevrolet 4-1/8" diameter (cloth wrap as orignal)each 1937-62 Chevrolet 4-1/8" diameter (metal wrap replacment).each 1939-59 GMC 3-5/8" diametereach | pe. 29.50 29.50 23.95 |
| Ű | For optional | Lines with Fittings, (Chevrolet six cylinder only) external type oil filter assembly that attaches to intake manifold. Chevre ne. Oil resistant rubber. Description 14" Lowereach 18" Uppereach Both upper and lowereach | olet 216 16.95 18.95 35.75 |
| | equal or be | Assembly haven't found the original style. We now stock an attractive remote filte tter than GM. Attaches to firewall or inner fender (not to intake manifol ines to the factory pre-drilled holes in your block. With instructions. Description 1941-62 216, 235 and 261 Chevrolet six cylinderpair | er that is d). You 73.50 |
| | • Speedom Exact as ori Part No. ME485 ME2721C ME812 | eter Cables with Metal Wrap Housing ginal. Description 1934-36 Chevrolet and 1936-46 GMC with square end connect at speedometer end - 65"each 1937-46 Chevrolet - 65"each 1939-59 Cab Over Engine body - 108"each | 46.50 39.50 46.50 |
| | • Speedom Excellent re Part No. ME2274 ME811 | eter Cables with Black Vinyl Housing placement. Description 1937-46 Some 4 speeds approx: - 65" longeach 1939-59 Cab Over Engine body - 108"each | 26.50 42.50 |
| | • Speedom Part No. FP183 | eter Cable Firewall Grommet Description 1936-59each | 1.75 |
| | | | |



| | MISCELLANEOUS MECHANICAL (continued) • Wheel Studs Part No. Description MEW200 1936-50 1/2 ton, front ME344 1946-70 3/4 ton, front, 2wd, 1-3/4" long ME1552 1936-62 1/2 ton, rear | each | 2.30 3.75 2.75 |
|----|--|--|--|
| | • Lug Nuts For attaching wheels. Part No. Description ME141 1934-72 1/2 ton and 1934-45 3/4 ton, 7/16" x 20 threads ME345 1946-72 3/4 ton and 1934-72 1 ton, 1/2" x 20 threads | | .95 1.95 |
| | Lug Nut Covers Chrome acorn nut covers. A nice non-original dressup item. Part No. Description MS341 All years 1/2 ton MS344 3/4 and 1 ton | | .85 .95 |
| | SUSPENSION PARTS • Leaf Springs As original. Not re-arched, but freshly machine provide the correct 1 3/4" wide. Made in USA! Part No. Description MES106 1934-55 Center leaf spring bolt with nut MES117 1934-36 1/2 ton, front MES131 1937-38 1/2 ton, front MES111 1939-46 1/2 and 3/4 ton, front MES101 Late 1936-40 MES112 1941-46 MOTE: Request pricing and availability of leaf springs not shown about | each each each each each each | 3.00 189.00 199.00 199.00 235.00 235.00 |
| | • Spring Shackles, Made in USA! Part No. Description ME183 1934-46 1/2 and 3/4 ton, front MES200 1934-46 1, 1 1/2, And 2 ton, front (2" spring) ME186 1934-46 1/2 ton, rear | each | 46.00 50.50 37.95 |
| 00 | Spring Shackle Rubber Grease Seals Part No. Description ME187 Replaces original round cork type (included in ME183 and ME186) | each | .95 |



| | | Spring U-I Holds leaf s | ON PARTS (continued) Bolts, Made in USA! pring to axle. Includes proper attaching nuts. Two per spring re | equired | |
|---|-----------|---|--|--|-------------------------|
| | | Part No. ME276 MES300 | Description 1940-54 1/2 ton, front 1934-46 1/2 ton, rear | | 10.00 16.00 |
| | | • Spring Bo Part No. ME260 | It and Bushings, Made in USA! Description 1934-55 1st 1/2 ton front & rear, 3/4 ton front | | |
| | | ME805 | 1-3/4" spring 1941-55 1st 1 and 1-1/2 ton, 2" spring | | 27.50 24.50 |
| | | | ns and Bushings, Rear Springs one truck. Made in USA! Description | | |
| | | ME432 ME433 | 1937-55 1st 3/4 and 1 ton, for 2" rear springs 1937-62 1-1/2 ton, for 2-1/2" rear springs | | 59.95 59.95 |
| | | Original leve shaft resurfa | sorbers - Single Action Lever Type r action type. Units are totally rebuilt to operate like new, including icing, modern seals, fluid, etc. Equal to new in quality and long modern telescoping style 5 to 1. Plus core charge. 30 day turna Description 1934-46 Left front and 1947-49 Right front, 1/2 and 3/4 ton 1934-46 Right front and 1947-49 Left front, 1/2 and 3/4 ton 1934-49 Left, rear 1934-49 Right, rear Core charge for "Single Action" shock absorbers | each each each each each each | |
| | | | Sorber Link - For Single Action Shocks ith both bushings, pins, and brass sleeves. (For one shock.) Description 1930-39 Front and 1933-36 Rear (8" long) 1940-46 Front (6 3/4" long) 1930-32 Rear and 1937-49 Rear (9 1/4" long) | set | 27.80 26.50 27.80 |
| | SSM | | sorber Link Rubber Bushings, Pins, and Sleeves ME263, ME410, and ME411. Set of 2. Single action type only! Description 1930-49. | | 12.75 |
| _ | | • Shock Abs Part No. MES110 | sorber Link Upper Bushings - For Double Action Shocks Description 1937-49 | each | 13.75 |
| | aldehaurt | | 0 000EDS 1 000 0(2 1012 TECH HELD 2 4mm 1 | 016 2 | 57 5057 |

Truck Parts

...visit our website for SPECIAL savings!

| | | PARTS (continued) sorber Link Lower Bushings - For Double Action Description 1937-49 Front or rear. (metal cups over rubber)pair | 24.75 |
|------------------|--|--|----------------|
| | | sorber Fluid placement when adding fluid to the original 1949 and older lever actio | n shock |
| | Part No. ME672 | Description 32 ounce containereach | 8.95 |
| | • Grease Fi Part No. | Description | |
| | ME190 | Straight fittingeach | .55 |
| HH . 7 | ME191 | Angled fittingeach | .65 |
| | ME192 | Steering kit for tie rods and kingpins | 4.80 |
| | ME193 | 1940-59 Spring kit for 4 springskit | 7.40 |
| ME758 ME757 | • Axle Bum Part No. ME758 ME757 | pers, Rubber Description 1940-55 1st Front, fits on axle above spring, squareeach 1929-46 1/2 ton, rear, fits on axle above spring, roundeach | 10.95 15.95 |
| | | For hard farm service for all-round duty | |
| | | World's thriftiest high-powered trucks | |
| | | Buy one be convinced! | |
| | | A Construction of the construction of a constructin construction of a c | |
| | | CHEVROLET TRUCKS | |
| | | FOR EXCOMPTION. | |
| ODDEDS 1 900 973 | 1012 TECH | THELD 2 4mm 1 016 252 5057 oldehevytrucks com | 95 |

 ORDERS
 1-800-862-1913
 TECH HELP 2-4pm
 1-816-252-5857
 oldchevytrucks.com
 95



MIRROR PARTS

| | Mirroro D | | |
|--------|----------------|--|------------|
| | • Mirrors, F | ar with those not going original. Attaches to door edge. Complete wi | h bracket |
| | | ng screws. Fits all years and models. | IT DIACKEL |
| | Part No. | Description | |
| | MI101 | Left, short curved chrome arm | |
| | WITCH | with 4" stainless headeach | 19.95 |
| | MI102 | Right, short curved chrome arm | 10.00 |
| | 1011102 | with 4" stainless headeach | 19.95 |
| () | MI148L | Left, 6" straight chrome arm with 4" stainless headeach | |
| | MI148R | Right, 6" straight chrome arm with 4" stainless headeach | |
| | - | attractive era option with an LED turn signal (flashing arrow) in the m | |
| | | urn signal is not on it looks just like the original. Attaches to door edge. | |
| | | t and attaching screw. Fits most all years of trucks and cars. This left | |
| | | ome or stainless armed mirror has 4 inch head | |
| | MI601 | LED Left, short curved chrome arm | |
| | | with 4" stainless headeach | 27.95 |
| | MI602 | LED Right, short curved chrome arm | |
| | | with 4" stainless headeach | 27.95 |
| | | | |
| | • Mirrors, (| Dutside | |
| | Part No. | Description | |
| | MI103 | Black 5" roundeach | 9.65 |
| | MI125 | Chrome 5" roundeach | 10.95 |
| | MI104 | Black rectangular type to replace MI103. | |
| | | Gives slightly more viewing area (5 1/2" x 7 1/2")each | 13.95 |
| | MI149 | Stainless rectangular type to replace MI125. | |
| | | Gives slightly more viewing area (5 1/2" x 7 1/2")each | 16.95 |
| 0 | | | |
| | | ms, Outside | |
| | | oor hinge as original. In primer. | |
| | Part No. | Description | 20 50 |
| | MI302 | 1934-36 High cab, left or right. Hand made in USA,!each | |
| | MI127 | | |
| | MI128 MI106 | 1936-38 Low cab, righteach | |
| | MI106 MI107 | 1939-46 Lefteach | |
| MI107 | IVIT 107 | 1939-46 Righteach | 25.95 |
| P | • Mirror Ar | m Extension | |
| | - | a that allows you to add a 6" mirror arm extension. In seconds one bolt | connects |
| | | on to your original shorter arm. A hook holds it in place. The existing m | |
| | | the end of this extension. It even swings back toward the cab if yo | |
| | | age door opening. There are the same diameter of the original arm so the | |
| | | its right or left. Hand made in the USA! | ley maton |
| | Part No. | Description | |
| | MI304 | 1937-55each | 17.75 |
| | | | |
| \sim | Door Hin | ge Pins for Mirror Arms | |
| | Part No. | Description | |
| | DP112 | 1934-38 2-5/8" long. Also used on 1939-46 hinges | |
| | | without mirror armeach | 2.50 |
| | DP135 | 1939-46 3" long. Use with mirror armeach | |
| | | - | |
| _ | | | |



...visit our website for SPECIAL savings!





General Motors Trucks



| | Door Lubr | ication Stickers | | |
|---|--------------|---|----------|-------|
| | | Blue, yellow, and white, as original. Attaches to door post. | | |
| | Part No. | Description | | |
| AUTHORIZED GM Restoration LUBRICATION GM Parts | MS101 | Lube sticker | each | .60 |
| SERVICED AT MILES | | | | 2.75 |
| CHASSIS LUGE. TRANS. | MS501 | Lube stickers (set of 5) | sei | 2.75 |
| | • "Decal Or | ly" From Above Advertising Sales and Service Signs | | |
| | | lows, your own signs, etc. Approximately 11 1/2" diameter. | | |
| LUBRICANTS RECOMMENDED BY YOUR DEALER out Pastonation | Part No. | Description | | |
| BY YOUR DEALER GM Restoration Parts | DE101 | Chevrolet | each | 9.75 |
| GM Restoration Parts | DE101 | GMC | | 8.95 |
| SUPER | DETOZ | 0.000 | Cuon | 0.00 |
| CHEVROLET | Chevrolet | and GMC "Miniature Service Sign" Decals | | |
| VER VICE | | dows, your own signs, etc. A miniature of DE101 and DE10 | 2 above. | |
| | Part No. | Description | | |
| GM Restoration Parts | DE103 | Weatherproof vinyl, approximately 3" diameter. | | |
| | DEIGO | One of each on a single sheet | set | 2.75 |
| | | | | |
| | Clutch Heat | ad Drivers | | |
| | | high quality drivers to complete your Chevrolet tool collection. | A "must" | when |
| sell l | | s unique bolt head. | | |
| | Part No. | Description | | |
| | i dit itoi | 5/32" Not available separately se | t only | |
| | MS111 | 1/4" | | 3.50 |
| | | ailable separately se | | 5.50 |
| | MS313 | Full set of three, with clear plastic pouch | • | 16.95 |
| | 1010310 | | 501 | 10.95 |
| | • Inner Tube | | | |
| | Part No. | Description | | |
| | MS204 | For original 16 inch tires | each | 16.50 |
| | MOLOI | | | 10.00 |
| | | | | |
| | | | | |
| | | A | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | 1 | | | |
| | | | | |
| | | | | |
| | | | | |
| | | the second se | | |
| | | | | |
| | | | | |



...visit our website for SPECIAL savings!

WHEELS AND HUB CAPS

Our new wheels are very close to originals. They fit well with drum or disc brakes. Designed for tubeless radial or bias belted tires. We stock both original 6 lug pattern as well as 5 X 4 3/4"pattern for popular Chevy car wheels. The following hub caps are slightly modified inside to fit this wheel center, however the changes are not visible when installed.

| MST150 | • Wheels, Bare Steel Smooth finish. Ready for priming and paint. Used with MST155, MST159 or MST163 hub cap listed below. Part No. Description MST150 1934-59 15" x 5" wide, 6 holeeach 89.50 MST166 1934-59 15" x 6" wide, 5 hole x 4 3/4"each 89.50 |
|-------------------------|--|
| | • Wheels, Chrome High polished mirror finish. Use with MST155, MST158, or MST163 hub cap listed below. Part No. Description MST149 1934-59 15" x 5", 6 holeeach 115.00 MST167 1934-59 15" x 6" wide, 5 hole x 4 3/4"each 115.00 |
| MST155 AND MST163 | Hub Caps - Chrome Plated Designed to fit "only" the above new wheels: Part No. Description MST158 1936-59 With Chevrolet red/blue stampings as 1941-46each 38.75 MST155 1936-59 8" Without logo |
| | • Stainless Steel Wheel Ring As used on deluxe pickups. Top quality! Looks great in combination with a chrome hub cap. 1 3/4" wide. Part No. Description TR146 15"each 26.00 |



| MST270NC | Spare Tire Mounting Parts, Side Mount Part No. Description MST269 1934-36 Side mount cowl and fender rubber grommeteach 19.50 MST270NC 1934-36 Side mount tire clamp. Paint as originaleach 40.00 |
|----------|--|
| | Spare Tire Hook Holds up factory tire rack by attaching into rear cross sill. Includes special long retaining nut. (Included in spare tire under bed assembly.) Part No. Description MS107 1937-50 1/2 and 3/4 toneach 14.50 |
| | • Spare Tire Hook Locking Nut This special long brass nut fits MS107, however, it has a groove for use with your factory spare tire lock. Hand made in the USA! Part No. Description MS275 1937-50 1/2 and 3/4 toneach 18.75 |
| | Factory Tool Bag An exact copy of the original canvas tool bag placed in new GM trucks during the 1940s and 1950s. Made with proper olive color material and snaps. Inside are cardboard sheets with scale artist's drawings of each tool. You will know which tools to look for at swap meets, second-hand stores, garage sales, etc. Made in the USA. Part No. Description MS151 Factory tool bag |
| () | Key Blank, General Motors Style Part No. Description MS120 Authentic key for ignition, doors and glovebox. Ready to be cuteach 1.95 |
| | Blue Dots An after-market option. Very popular during prior years. Cut glass with chrome over brass ring. The best quality made! Easy to install in all plastic taillight lenses. Part No. Description MS225 Blue dot lenspair 8.95 |
| | Reflector License Plate Fasteners An inexpensive extra accessory to go with that older truck. Adds the final detail to an otherwise plain area. Quality reflective jewels with aluminum back, long bolt, and nut. Part No. Description MS157 Red plastic lens |



| Old Checy Trucks | bottom. Logo state Part No. Desc | our important notes. Edges are bordered and hates: "Old Chevy Trucks". ription t 50 sheets (7" x 7-1/4") | | ronts at 3.50 |
|---|---|--|--|----------------------------------|
| Detsor Remy M Restoration Parts | two threaded drive Part No. Desc MS128 Black | g oval etched plate used on the generator, starter, an rivets. Made in the USA. ription a etching on aluminum. Correct for 1941-59 putor and 1941-55 generator and starter | | ncludes 7.50 |
| | design. Eight faster Part No. Desc | ur tags (distributor, starter, and generator) just lik | | n spline 3.95 |
| HARVERT BE BY DEFENDENCE DUPERSTICES BY DEFENDENCE DUPERSTICES BY MEDICAL BY MEDICAL BY MEDICAL BY MEDICAL BY MEDICAL BY MARVERSTICES | vehicle manufactur spot provided.) Mac Part No. Desc *TR403 1936- *TR404 1939- *TR104 1939- TR105 1942- | detail on your restored GM Truck! Black on s rer, gross weight, horsepower, etc. (You stamp y | vour serial nun each each each each | 39.50 17.90 17.90 17.90 |
| MST432 MST434 | We challenge you embroidered with twill. One size fits a blue bill or tan with miscellaneous sect Chevrolet Part No. Des MST430 Blac MST432 Tan MST431 Tan | 5, HEAVYWEIGHTS u to find a better quality heavy weight base official GM registered logos and come in low p all with adjustable rear band. Available in either bl n black bill. For great colored view of these attr tion of our website 1934-46 catalog at www.jimca scription ck (Bowtie\Chevy Trucks) with blue bill (Bowtie\Chevy Trucks) with black bill (Bowtie\Chevy Trucks) ck with Bowtie and flames on bill | rofile brushec lack, tan with r active caps, c a rtertruckpart each each each | d cotton medium click the |
| | MST459 Hat | s cription Jim Carter Logo on Black Hat w/USA Flag side/website | each | 12.95 |
| | Part No.DesMST460LrgMST461X-L | t Logo w/All trucks on back. scription White rg White Lrg White | each | 14.95 14.95 16.95 |




| MST436 | BASEBALL GMC Part No. MST435 MST436 | CAPS, HEAVYWEIGHTS (continued) Description Black (GMC Trucks)each Tan with black bill (GMC Trucks)each | 14.95 14.95 |
|--|---|---|--|
| FRONT BACK | 100% pre-sh trucks on the 1955-56, 196 double sideo 1934-46 cata Part No. MST423 MST424 | Heartland" is one of the most popular Chevrolet truck T-shirts. Thi forunk cotton shirt is just right for those that like the full range front and back. This shirt features such great trucks as 1941-46, 57-68, 1969-70, 1971-72, and late 1990's. For a great view of this I shirt check the "miscellaneous" section of our website alog at www.oldchevytrucks.com. Description Large | of Chevy 1947-53, attractive 17.95 17.95 |
| PLEASE DON'T TOUCH ME. I'M NOT THAT KIND OF A TRUCK! | MST425 • Don't Touc 7" x 11" cards Part No. MS995 | XX Large each h Me Sign board window sign at car show's to help keep fingerprints off your tr Description Please Don't Touch Me, I'm Not That Kind of Truck!each | uck. |
| | • Vise Pads Non-metal pa polished surfa Part No. MS715 | ads have internal magnets that attaches to vise jaws. Protects ch aces. Description | |
| and a second sec | sheet metal. | torations, these unusual fasteners can be a great help. Weld both ea The inside square nuts are held in place and accept an attaching be diameters with these thread sizes: Description 5/16" X 18each 1/4" X 20each 3/8" X 24each | |
| | When you wa | Open Supports ant your hood securely held in the open position. Originally on GM on Chevrolet. Installs quickly on wishbone rod where it attaches to fi Description 1939-46pair | rewall. |

And they are every bit as outstanding in performance ... endurance... and operating economy as they are in price

Always, demand follows quality and value!... Again in 1934, the demand for Chevrolet products has made Chevrolet the world's largest builder of trucks as well as of passenger cars. And now, thanks to economies resulting from volume production, Chevrolet offers still greater values—the highest quality Chevrolet Trucks ever built and the lowest-priced trucks you can buy! Truck buyers who want to save money will find that these are not only the world's lowest-priced trucks, but that they are also very economical to operate and maintain. They are big—rugged—dependable trucks. They are powered by six-cylinder valve-in-head engines which use very little gas and oil. And they are extremely long-lived ... built to do their job faithfully over a long period of years. Buy a Chevrolet Truck and you buy fine, dependable, economical haulage service—at the world's lowest price!

CHEVROLET MOTOR COMPANY, DETROIT, MICHIGAN Compare Chevrolet's low delivered prices and easy G. M. A. C. terms. A General Motors Value





| | | | |) |
|---|--|--|--|------------------|
| | C | | | |
| | | Bumpere | | |
| | | Bumpers Part No. | Description | |
| | | MS197 | 1934-36 Chevrolet only, front. Chromeeach | 355.00 |
| | | MS226 | 1934-36 Chevrolet and GMC, rear. Chromeeach | 355.00 |
| | | MS199 | 1937 Chevrolet only, front or rear. Chromeeach | 375.00 |
| | | MS200 | 1938-39 Chevrolet only, front or rear. Chrome | |
| | | | with correct center horizontal indentationeach | 375.00 |
| | | MSB213 | 1940 Chevrolet front or rear. Chrome with 2 horizontal grooves, | 075.00 |
| | | MOOOT | as originaleach | 375.00 |
| | | MS237 | 1941-46 Chevrolet only, front or rear Chromeeach | 325.00 |
| | | NOTE: We h | have used 1937-45 Chevrolet front bumpers 1 1/2 ton you chrome or \$50.00 each. Call for availability. | paint . |
| | | | | |
| | | | races and Brackets | |
| | | | s formed as original. | |
| | | Part No. MSB106 | Description 1934-36 1/2 ton, front. For reproduction bumpers only!pair | 145.00 |
| | | MSB108 | 1937 1/2, 3/4, and 1 ton, frontpair | 149.00 |
| | | MSB203 | 1938-39 1/2 and 3/4 ton, front | 160.00 |
| | 960 | MSB207 | 1940 1/2 and 3/4 ton, frontpair | 145.00 |
| | | MSB206 | 1941-46 1/2, and 3/4, frontpair | 125.00 |
| | 6 | MS202 | 1934-36 Inner bumper brace without frame | |
| | | | extensions, rear (5' 9" long)each | 145.00 |
| | | MSB107 | 1934-36 rear extensions (use with MS202). Set of 4set | 79.00 |
| | | MSB199 | 1937 1/2 ton, rear. Set of 6 items | 160.00 |
| | 1/ | MSB204 MSB208 | 1938-39 1/2 ton, rear. Set of 6 itemsset 1940 1/2 ton, rear. Set of 6 itemsset | 160.00 175.00 |
| | | MS184 | 1940 1/2 ton, rear. Set of 6 items | 129.00 |
| | | | | |
| | | | BOLTS, NUTS, ETC. | |
| | FP176 | • Bumper Bo Part No. | olts - Chevrolet Description | |
| | | FP176 | 1931-36 With large oval head, nut, and washer | |
| | | 11 170 | (polished stainless) 3 1/2" inches higheach | 21.95 |
| | | FP173 | 1931-36 Bumper end eye bolts, nuts, and | |
| | | | washers (polished stainless)pair | 36.50 |
| | | FP106 | 1937 With rounded chrome head as originaleach | 2.75 |
| F | P107 🏾 🖳 🗌 | FP107 | 1938-46 With oval head as original (polished stainless)each | 6.50 |
| | <u> </u> | FP107A | 1938-46 Sold in a set of 5set | 29.50 |
| | FP176 | Bumper Be | olts - GMC | |
| | | Part No. | Description | |
| C | | FP176 | 1936-38 With large oval head, nut, and washer (stainless)each | 21.95 |
| | FP106 | FP106 | 1936-46 With rounded chrome head as originaleach | 2.75 |
| | | • Bumper Be | olt Nuts | |
| | | Part No. | Description | |
| | | FP210 | For use with FP106 bumper boltseach | .20 |
| | | FPF211 | Marsden style has original slots in sides. For FP106each | 3.95 |
| | | Note: For th | ne perfectionist:The slotted Marsden nuts came on early trucks. | |
| | FPF211 | | | |
| | | | | |
| | | | | |



| 90 | Bumper Brace Rubber Covers Part No. Description FP228 1941-46 Fits over br apron below grill | race openings in front splash | 12.75 |
|----|---|---|---|
| | to make the best molds. This pro and braces like the GM units. If yo be your choice for the perfect res separate the men from the boys! T Part No. Description MSR223 1941-46 1/2 ton le | 1941-46 1/2 Ton al 1/2 ton running boards that were the necessar oduct looks just like the originals. They bolt to your ou don't have New Old Stock GM metal boards, our storation. These black fiberglass 1941-46 running They are also excellent with step plates MS215 or N fteach ghteach | r fenders rs should g boards //S215G. |
| | correct in dimensions. Excellent or MS215G. Part No. Description MS222 1934-36 1/2 ton. L MS223 1937-38 1/2 ton. L MS224 1941-46 1/2 ton. L without ridges MSR226 1941-46 3/4 ton or (Slight modification MSR225 1941-46 1/2 ton. L 2" wider than stock Note: For the non-original 1940- | ecial truck. Made from new old stock patterns so for use with the aluminum decorative step plates eft and right. Includes proper diamond tread. pair eft and right. Ribbed like originalpair eft and right. Smooth top surface | 390.25 499.00 468.00 635.00 413.50 rs from a |
| | securing units. Cut these 30" un Part No. Description | ded on running board reinforcement between the t | wo brace 11.00 |



| | | | each | braces. 9.00 9.00 |
|---|--|---|--------------------------|----------------------------------|
| GM Restoration GM Restoration Parts | MS215 Chevrolet with blu MS215G GMC with attracti | e kick 5" x 8 3/4" ue Bow-tie emblem 5-1/4" x 1 ive early style letter design 5" 6 except non-polished 5" x 10 | l1"pair x 10 5/8"pair | 58.95 55.95 44.50 29.00 |
| | MS220 | MS215 | MS215G & MSR2 | 22 |
| | MISCELLANEOUS PARTS | • | | |
| e | | er cover designed for protect | se. Not designed for lo | |
| NEW! | •Vintage Flashlight Now available for the first time s column and the chrome flashlig like the original! Requires 2 D-o Part No. Description MS720 Flashlight and class | ht snaps to the rubber edge cl | amp. A popular item m | - |
| Υ , | CAND ROMAN | | | |



...visit our website for SPECIAL savings!

Auto Dolly

MS651

Move your special car or truck easily accross a floor. Free up space in garage or storage buildings. These heavy duty dollies are U.S. made and rated at 6000 lbs. Low profile 1/4" powder

coated steel plate. Polyurethane ball bearing won't mar floors and can turn 360° circle. Packed in sets of four each. These are not light weights!

Description Part No.

| | set of 4 (8" wide x 16" long)set | 149.00 |
|-------|-----------------------------------|--------|
| MS711 | set of 4 (12" wide x 16" long)set | 159.00 |

Counter or Bar Stool

We provide seven "GM" counter or bar stools. Great for your shop or rec. room. Their colorful 14" cushions swivel on chrome legs 30" high.

| Part No. | Description | |
|----------|----------------------------------|-------|
| Fart NO. | Description | |
| MS650 | GMC General Motors Truckseach | 99.95 |
| MS651 | Super Serviceeach | 99.95 |
| MS652 | We Use Genuine Partseach | 99.95 |
| MS653 | Chevrolet Racingeach | 99.95 |
| MS654 | Red Bowtie on all Black Seateach | 99.95 |
| MS655 | Ok Used Carseach | 99.95 |
| MS656 | Chevrolet GM Genuine Partseach | 99.95 |



GOT TO SEE THESE!

NEW!





MS650 Below!



oldchevytrucks.com 107 ORDERS 1-800-862-1913 TECH HELP 2-4pm 1-816-252-5857



PAINT

| visit our | website | for SPECIAL savings! |
|-----------|---------|----------------------|
|-----------|---------|----------------------|

PAINT, EXTERIOR

To date, most of our customers have found no supplier for the proper colors for vintage GM trucks. The only choice was to have paint mixed close to the original. We can now correct that problem. We have obtained a source for the more popular exterior colors for Chevrolet and GMC 1936 and up. 1/2 and 3/4 ton pickups usually require 1-1/2 gallons for good paint coverage. These are mixed in fresh acrylic enamel.

Note: Sorry, no paint shipped out of the 48 Continental United States.

| -AF | • Paint She Lists the na Part No. LI124 | eets ames and years of the various colors which were available from 1936 to Description 1936-66 Chevroleteach | o 1966. .15 |
|-------|--|--|--|
| | LI124 | 1938-66 GMCeach | .15 |
| PAINT | | Iors - Chevrolet Description 1936-42 Apple Green (not the pin stripe color) | 56.50 169.50 56.50 169.50 56.50 169.50 56.50 169.50 59.80 179.50 56.50 169.50 |
| | • Basic Co Part No. PT801Q PT801G PT802Q PT802G PT803Q PT803G PT806Q PT806G | , i i i i i i i i i i i i i i i i i i i | 56.50 169.50 56.50 169.50 56.50 169.50 56.50 169.50 |
| | • Red and Part No. PT405Q PT405G PT407Q PT407G | Maroons - ChevroletDescription1936-52Swifts Red1936-52Swifts Red1936-72Omaha Orange1936-72Omaha Orange1936-72Omaha Orange1936-72Omaha Orange | 59.80 179.50 59.80 179.50 |

108 oldchevytrucks.com ORDERS 1-800-862-1913 TECH HELP 2-4pm 1-816-252-5857

PAINT

...visit our website for SPECIAL savings!



| PAINT | PAINT, EXTERIOR (continued) • Red and Maroons - GMC Part No. Description PT804Q 1938-52 Pimpernel Scarlet | 59.80 179.50 59.80 |
|-------|---|---|
| | PT805G 1938-53 Permanent Redgallon | 179.50 |
| | Kildare Green During 1939-46, Brewster green was the standard color on Chevrolet trucks. The colors were non extra cost options. We now have the harmonizing green color to placed on the cab and hood belt moulding of the Brewster Green trucks. An apple stripe PT603AG was placed on the center of the belt line as a final touch. Part No. Description PT602 Kildare green | hat was |
| | Pin Striping Tape for Cabs A final detail for the perfectionist. Furnished in the original width and most of the colors. Location and technical instructions included for 1939-46. (Example: Scarl was used over Boatswain Blue. Black was used over Medium Cream. Argent Silve was used over Swifts Red and Black.) Part No. Description PT603AG Apple Greenkit PT603LG Light Greenkit PT603SC Scarletkit | et stripe |
| | PT603WH Whitekit | 13.00 |
| | • Striping Tape When you want to paint or spray your own cab stripe and not use the above colore Once applied, the tape center can be pulled away to expose the paintable stripe See LITERATURE SECTION for pin striping sheet, LI158. Part No. Description PT217 15 Yards per roll | |
| NEW | PAINT, INTERIOR 1936-38 Chevrolet Interior Powder Coating Now available after 75 years! So much research and experimenting to get the 193 wrinkle interior appearance right. The color, the wrinkle, the texture of our powder will separate the men from the boys in any truck gathering. It is applied by a powder company in most medium sized towns. A 5 pound bag is enough for all removable parts such as door panels, upper window panels, dash, rear panel around window, will wiper plate and panel, etc. Good News! All the panels requiring this color are attached to the cab with small Therefore, this powder coating can even be used on the metal of a fair conditioned reab. Part No. Description | coating coating interior ndshield screws. |



Т

PAINT

...visit our website for SPECIAL savings!

| INTERIOR PAINT | • 1936-38 C | ERIOR (continued) hevrolet and GMC Special "Wrinkle" Finish on these early trucks. Description Brown (Show quality, see above section) | 149.50 38.50 10.20 |
|-------------------|---|---|------------------------------|
| | • Interior Pa For cab, do required. Part No. | aint ors, dash, seat frame, etc. Formulated to exact color. Two quarts Description | normally |
| | PT105 PT106 | 1939 Chevrolet, gray brown enamel quart 1940-46 Chevrolet, special beige color "Hammered" type, as original. Gives that unique cloud or | 55.50 |
| ENGINE PAINT | PT106ES | "fish eye" appearance. Instructions included quart 1940-46 Chevrolet, special beige color "Hammered" type, as original. Gives that unique cloud or "fish eye" appearance. | 58.95 |
| | PT133 | Instructions included. 11oz spray caneach 1941-46 GMC, silver brown enamel with slight metallicquart | 14.95 62.50 |
| | • Steering V Part No. PT136 | Wheel and Column Paint Description 1946 Brown (1941-45 were black)pint | 39.50 |
| | | | |
| MANIFOLD PAINT | | h-temperature engine enamel available anywhere. Exact factory colo that "final touch". Fast drying. Description 1929-62 Chevrolet six cylinder, greyquart 1939-48 GMC six cylinder, olivequart | rs to give 45.95 45.95 |
| | The best hig your engine Part No. PT115 PT117 • Transmis Gives the a Part No. | h-temperature engine enamel available anywhere. Exact factory colo that "final touch". Fast drying. Description 1929-62 Chevrolet six cylinder, grey quart 1939-48 GMC six cylinder, olive quart | 45.95 |

PAINT



| | | • Exhaust Manifold Filler Hi temp paste fills rust pit holes. Part No. Description MEE324 1936-52 | each 1 | 5.00 |
|------------------|---------------------------------------|--|---|--------------|
| | | Engine Accessory Paint Black. For generator, starter, distributor, frame Part No. Description PT119 Black paint | | 9.50 |
| | | PAINT, BUMPER AND GRILLE | | |
| FOR T PERFECT | HE ST! | Turret Grey During World War II when chrome was not average the proper enamel color as used on Chernel Strips during most of 1943-45. Part No. Description PT100 1943-45. | evrolet grilles,hub caps, bumpers, and l | |
| Ş | A A A A A A A A A A A A A A A A A A A | • Paint Sprayer, Portable Can be used to spray over 1,001 products. W own sprayer for quality paints. Particularly goo up jobs. Sprays 12 to 16 ounces of liquid. Part No. Description | od in spraying paints or doing smaller to | ouch- |
| | | PT125 Extra power unit | | 9.95 7.95 |
| | | PT126 Extra product container, glass | each | 2.00 |
| | | | | |



We Got Parts!



PAINT

...visit our website for SPECIAL savings!

| | Most everyone has heard about POR-15. We were so impressed with what this product can do for you in your restoration, we became a dealer! Whether you are painting the frame on a body-off restoration or just protecting your battery tray from acid chemicals, this "one time" application will do the job. Even great on farm machinery and underwater marine items. It's proven reputation is unequalled!! | | | | |
|---|---|--|--|--|--|
| | | • Metal Ready Provides the best adhesion on any metal surface including aluminum and polished surfaces. It gently etches the metal and gives an ideal surface for coatings such as POR-15 after thoroughly degreasing, "Metal Ready" will neutralize rust and etch any clean bare metal. (This is not needed for the POR-15 coating below if the surface is grease free.) Part No. Description | | | |
| | | POR15DMRQTquart 21.95 | | | |
| - | | • POR-15 Coating This is what its all about !! Chemically combines with rust as you paint. No need to remove rust first. Great on truck and car parts such as frames, suspension, floor pans, corroded battery trays, and even engines. This is not just paint. It is so tough you will be surprised how little the chassis is effected by rocks on gravel roads. Part No. Description POR15DPSG Semi gloss black | | | |
| - | | • Fuel Tank Sealer This high-tech sealer is formulated to not only stop pin hole leaks but resists all fuels including those with higher alcohol content. Stops rust corrosion, and leaks permanently. Chemically bonds to the inside tank metal surface. Seals up to a 25 gallon tank. Part No. Description POR15DQFTSquart 46.95 | | | |
| - | | • Marine-Clean Cleans and degreases in one application without leaving residues, noxious fumes or flammable solvents. Part No. Description POR15DQMCquart 13.00 | | | |
| - | | • POR-15 Solvent Specially formulated for easy cleanup or thinning of POR-15 Rust Preventive Paint. Part No. Description POR15QSLVquart 18.50 | | | |
| | | | | | |

112 oldchevytrucks.com ORDERS 1-800-862-1913 TECH HELP 2-4pm 1-816-252-5857

RADIO

...visit our website for SPECIAL savings!



RESTORED RADIOS

Radio - Rebuilt AM

| | Includes sp designed to Silvertone, | ebuilt AM er dash 60 year old radios have been disassembled and rebu eaker. Secures to lower edge of dash to the left of steering attach under the dash at the left of the steering column. Bra GM, Airline, Etc. as above average 1939 to 1946 cores are rebuildable cores, please inquire on availability. Made in US Description 1939-46 6 volt radio | column. T inds will be available. SA | hey are Philco, |
|---------|---|---|---|---------------------|
| | bullet shape | | m caps. Ni y! | |
| · | On some ap This is usua suppressors Try one or a | ise Suppressors oplications annoying radio noise is picked up and heard thro ally due to original style copper spark plug wires. It can be e s. They originally were attached to three places on your truck's Il three to eliminate noise. Place on battery terminal of voltage and armature side of generator Description Radio suppressor | eliminated s electrical e regulator | with our system. |
| Aller . | • Voltage R Part No. EL135 | educer, Radio Description Drops 12 to 6 volts. Necessary if you have converted to a 12 volt system and use a 6 volt radio | each | 19.95 |
| | | | J | |

oldchevytrucks.com 113 ORDERS 1-800-862-1913 TECH HELP 2-4pm 1-816-252-5857

| Carrier Carrier Truck Parts | SHEET METAL | |
|-----------------------------------|--|--|
| | visit our website for SPECIAL savings! CAB REPAIR PANELS Save much body time attempting to make these unusual panels. Made in USA! | |
| SM456 | Cowl Panel, Lower Front- Made in the USA. Original gauge metal! Hand formed. 6" high. Part No. Description SM462L 1934-36 Left, one panel | 250.00 250.00 98.00 98.00 85.00 85.00 |
| | • Cab Corners - Lower Finally a professionally made panel with tooling that correctly replaces the rear co the pickup cab. These are so often rusted beyond repair. Saves many hours of bo time. Correct metal thickness and about 10" high. Part No. Description SM468 1936-46 | rners of dy shop 74.50 |
| | Cab Belt Corners - Upper These patch panels fit curve on the corners of the cab. These four inch high meta are hand made and use the same gauge metal as the originals. They include th horizontal rib or belt that is so often rusted beyond repair. Extend from edge of door to of back of cab where the horizontal panel SM459 begins. Part No. Description SM458L 1939-46 | lower |
| | Cab Horizontal Patch Panel Rear This 4 inch high horizontal metal panel is two feet long and is straight. This rib or belt rusted beyond repair. This connects to the two corner patch panels above. (SM458 Part No. Description SM459 1939-46 Center (Approx: 4" high x 24" long)each | 8L/R.) |
| | Door Patch Panels These hand rolled and formed panels nicely replace your rusted out door skins. I the three right angle edges to bend over your door frame. The shorter panel will re spotted rust on the door bottom edge if all else is good. Professional installation recom to insure a perfect final appearance! Welding these short panels is difficult for an a Made in USA! Part No. Description SMD146L 1936-38 left, approx:6" high | pair the mended |
| | Door Patch Panels (continued) Slightly curved replacement panel, you fit to door. Part No. Description SM308L 1936-38 Left, approx:26" high | 98.00 98.00 98.00 98.00 |

...visit our website for SPECIAL savings!




| 1 | • Door Bottoms Will perfectly fit your original doors. These hand made pieces | 0 | |
|-----------------------------|--|-------------------|------------------|
| | include the proper bends and curved edges. Original gauge metal. Made i Part No. Description SMD149L 1936-38 Left | | 85.00 |
| | SMD149E 1930-38 Left | each | 85.00 |
| | SMD150L 1939-46 Left | | 85.00 |
| | SMD150R 1939-46 Right | | 85.00 |
| | • Floorboard and Toeboard Sections - Metal New on the market ! Made in the USA in original gauge metal. Fits just rigl Part No. Description | | |
| | FL301 1936-38 3-speed transmission, floorboard | | 125.00 |
| | FL302 1936-38 4-speed transmission, floorboard | . each | 125.00 |
| | FL303 1939-40 3-speed transmission, floorboard | | 125.00 |
| | FL304 1939-40 4-speed transmission, floorboard | | 125.00 |
| | FL305 1941-46 3-speed transmission, floorboard | | 125.00 |
| | FL306 1941-46 4-speed transmission, 1/2 ton, floorboard | . each | 125.00 |
| | FL307 1941-46 No holes for master cylinder, battery or shift lever. | | 405.00 |
| | floorboard (street rod type floor) | . each | 125.00 |
| | FL308 1941-46 Toeboard | . each | 69.95 |
| | Rocker Panels, Fit on cab below door. | | |
| | Part No. Description | h | 70.00 |
| | SMR458 1936-38 Left, fiberglass | | 70.00 |
| | SMR459 1936-38 Right, fiberglass | | 70.00 |
| | SMR468 1939-46 Left, fiberglass | | 75.00 |
| | SMR469 1939-46 Right, fiberglass SMR464 1939-46 Left, Metal, new tooling | | 75.00 125.00 |
| | SMR464 1939-46 Left, Metal, new tooling SMR465 1939-46 Right, Metal, new tooling | . each | 125.00 |
| | | . each | 125.00 |
| | •Panel Truck Tool Box Lid Made in our own wood shop! Is an exact copy of an original found in a nice years ago. Covers the in-floor tool box which is under the passenger seat. hardware. Note: See our website tech article "1941 Chevy Panel Truck Int Part No. Description | You pro erior" | ovide the |
| | FL196 1939-46 Tool box lid | each | 25.50 |
| | BED SHEET METAL • Front Bed Panels Now, for the first time since discontinued by General Motors. 16 gauge, bene etc., as original. Bolts into place as original. Price includes the mounting ro nuts, and washers for securing the panel to the bed sides and flat surface. N Part No. Description | od and t | he bolts, |
| | SM113 1934-39 Chevrolet, 1934-38 GMC, 15 x 45 3/4" SM114 1940-46 Chevrolet, 1939-46 GMC, 15 x 48 1/2" Note: 1939-46 GMC uses a metal bed floor (not wood). | each each | 117.00 117.00 |
| Chermolet | • Tailgates Formed steel, with ends. Ready for final sanding and painting. These qua made to original specifications. In primer. Made in USA! Part No. Description | lity tailg | ates are |
| GMC M Restoration Parts | SM117 1934-39 Chevrolet, non lettered. Also fits GMC | | 205.00 |
| | SM241 1939 Chevrolet, includes rolling script as original | each | 250.00 |
| ONG | SM207 1940 Chevrolet, with rolling script as original | each | 265.00 |

ORDERS 1-800-862-1913 TECH HELP 2-4pm 1-816-252-5857 oldchevytrucks.com 115

| Carter Carter Truck Part | SHEET METAL visit our website for SPECIAL savings! BED SHEET METAL (continued) |
|--------------------------------|--|
| | • Tailgates (continue) Part No. Description SM172 1941-46 Chevrolet, non lettered. Will also fit GMCeach 175.00 SM166 1940 Chevrolet or GMC, non lettered. Custom tailgate (not original)each 205.00 Note: If you want the Chevrolet script on your 1934-38, use the 1939 tailgate (SM241). Note: 1939-46 GMC uses a metal bed floor (not wood). |
| | Note: SM207 has the correct large lower roll and requires SM175 , SMT196.• Tailgate Ends Part No.Description SM226SM2261941-53 (included in SM321 and SM172)pair28.00 |
| | Tailgate Hinges and Adaptor, Stepside Part No. Description SM151 1934-39 (Also fits SM166.)each 16.95 SMT196 1940 Adaptorpair 52.00 SM175 1941-53each 11.00 Note: If you don't have the original hinge, we have the special hinge adaptor for large roll on the 1940 SM207 only. Use with SM175 with SMT196. |
| 1 Son | Hidden Tailgate Latches, Stepside For use in custom applications for replacing the old tailgate chains. This is a unique "locking" system that keeps them in open postion when the gate is down. Zinc plated. These work great with the tailgate arms below. Part No. Description SM608 1941-72 |
| | Tailgate Support Arms, Stepside When you want to eliminate the original tailgate chains! Hidden when gate is closed. Excellent for the custom stepbed truck for something a little different! Zinc plated. Assembly includes upper and lower pivots, links, and instillation hardware. Part No. Description SM610 1941-53 Chevrolet / GMC |
| | Tailgate Chain Hook Protectors Protect your newly painted tailgate from chips. This is always a problem where the chain enters the tailgate. The small clear vinyl covers are almost invisible! Part No. Description SM245 1932-53pair 1.25 |
| | • Tailgate Chains Part No. Description SM229 1932-53 Remove eyebolts if used on 1932-40, zinc platedpair 33.90 SMT300 1932-53 Stepside, polished stainless steelpair 49.50 |
| | Tailgate Chain Cover Protect the paint on your bed with these original type tubular covers. Includes water drain hole. Part No. Description SM246 1932-72 Stepside - blackpair 4.75 SM2461 1932-72 Stepside - clearpair 7.95 |







| Chevrolet Long Bed for Stepside Pickups - 1/2 and 3/4 Ton Part No. Description SM233L 1937-39 Lefteach SM233R 1937-39 Righteach SM211L 1941-46 Left completeeach SM211R 1941-46 Right completeeach | 449.75 435.00 |
|--|---|
| GMC Long Bed for Stepside Pickups, 1/2 and 3/4 Ton These 16 gauge sides are slightly longer than Chevrolet in the 1937-38. They like they came originaly. Includes welded on stake pockets and punched steel ar Holes included for fender and front bed panel instillation. Chain bracket rivited welded to the rear stake pocket. Part No. Description SMB390 1937-39 long 1/2 & 3/4 ton, lefteach SMB391 1937-39 long 1/2 & 3/4 ton, righteach SM211L 1941-53 long 1/2 & 3/4 ton, lefteach | gle strips. and spot 415.00 415.00 435.00 |
| Stake Pockets Contour and metal gauge as original. Weld to bed sides. Made in the USA. Part No. Description SM161F 1934-39 Front, right or lefteach SM161RR 1934-39 Left reareach SM160F 1940-53 Front, right or lefteach SM162LR 1940 Left reareach SM160LR 1941-53 Left reareach SM160RR 1941-53 Right reareach SM160RR 1941-53 Right rear | 44.50 44.50 48.50 56.95 56.95 48.50 |
| • Tailgate Chain Brackets Attaches to bed side to hold tailgate chain. Part No. Description SMB300 1934-40pai | 28.95 |
| • Bed Side Hole Cap, 1-3/4" Diameter Roll For the finishing touch on your modified truck. A rubber O-ring band surrounds t of the metal cap and holds it in place. Just press in and the job is done. Part No. Description SMC100 1940-66 Smooth finishpai SMC101 1940-66 With a Bowtie cut in the smooth surface | 39.95 |



...visit our website for SPECIAL savings!



•Bed Roll Custom Lights

For the custom non-original stepside pickup. Fits in the bed roll and is a great addition to the original taillights. A pair of single filament units are extra stop or turn signal lights. Your wiring runs forward through bed roll, down a stake pocket and connects to the tail light harness. An included rubber O ring keeps this light secure in bed roll. Complete with lens, housing, sockets, wiring, and instructions. A great extra.

Part No. Description

SMC120 1940-66 Stepside 1 5/8" diameter roll......pair 81.50

FENDERS, Fiberglass

We offer fiberglass fenders, which we feel are the best available. Molds for these fenders have been formed from "New Old Stock" GM fenders. These fiberglass units are the state-of-the-art and will be an excellent replacement for those almost extinct good metal originals.

| TI | • Front Part No. SM259L SM259R SM260L SM260R SM261L SM261R SM262L SM262R SM263L SM263R | Description 1934-35 Left, 1/2 ton | 410.00 410.00 410.00 429.00 429.00 434.00 434.00 450.00 |
|----|---|--|--|
| | Part No. SM264L SM264R FP658 | Over-Engine) Front Fenders and Grille Panel, FiberglassDescription1941-46 Left fender1941-46 Right fender1941-46 Fiberglass grille panel with barscach | 590.00 |
| | • Front Inne Part No. SMF3436L SMF3436R SMF3738L SMF3738R SMF4146L SMF4146R | r Fender, Molded Fiberglass Description 1934-36 Lefteach 1937-38 Lefteach 1937-38 Righteach 1941-46 Lefteach 1941-46 Righteach | 168.00 168.00 168.00 229.50 229.50 |



...visit our website for SPECIAL savings!

| | | FENDERS, • Rear | , Fiberglass (continued) | |
|-------|------|---|---|--|
| | | 46. These 1 trucks. For t | Description 1934-36 Left, 1/2 ton Panel, Suburban, and Pickupeach 1934-36 Right, 1/2 ton Panel, Suburban, and Pickupeach 1937-38 Left, 1/2 and 3/4 toneach 1937-38 Right, 1/2 and 3/4 ton Panel and Suburbaneach 1939-46 Left, 1/2 and 3/4 ton Panel and Suburbaneach 1939-46 Right, 1/2 and 3/4 ton Panel and Suburbaneach 1939 Left, 1/2 and 3/4 ton Panel and Suburbaneach 1939 Right, 1/2 and 3/4 toneach 1940-46 Left, 1/2 and 3/4 toneach 1940-46 Right, 1/2 and 3/4 toneach 1940-46 Right, 1/2 and 3/4 toneach 1939 units are also excellent when using wide tires on the more custom hose using this wider fender on the 1940-46, we also have the appropria rds (MSR225). See the MISCELLANEOUS section under Running B | 1940-46 ate wider |
| | | can put unsig Deflect road form and adl stars. Guara | otectors paint stars! Yes, sharp gravel points hitting under your fenders at hig ghtly stars on the top painted surface. Protect your fiberglass and metal gravel using specially developed "knobby" designed, flexible, black pa here to the underside of your fenders. Great insurance protection again nteed not to separate when applied properly. Each kit contains two 1/4 thesive, and instructions. Description Fender protectors | fenders. nels that nst paint |
| MS | B101 | • Fender Bra Part No. | aces Description | |
| | | MSB101 MSB100 | 1937-38 Rear fenderpair 1940-41 Rear fender. Original style brace for lower | 45.00 24.75 |
| MS | S109 | MS109 | rear of fendereach 1940-46 Rear fender. Fits under top crown of fender. Original on 1942-46, but excellent support on all 1940-46 pickup rear fenderseach | 29.50 |
| | | | NEOUS Il or Housing opies made from originals. Stainless correct grilles, See Front Parts S Description 1934-35each 1936each | Section! 314.00 314.00 |
| SM525 | TL | top and option | glass hoods for the non-original street rod enthusiast. We provide a o onal sides. You furnish firewall mounted hood hinges which allow the later model vehicles. (Hood tops must ship truckline.) Description 1937 Top, one pieceeach 1937 Sides, with original style louverspair 1937 Sides, no louvers, smoothpair | ne piece hood top 499.00 270.00 242.00 |

120 oldchevytrucks.com ORDERS 1-800-862-1913 TECH HELP 2-4pm 1-816-252-5857



| | Part No. Description SM542 SM544 | erglass (continued) 1938 Top, one pieceeach 1938 Sides, no louvers, smoothpair Ee Edge, Panel, Suburban (Below double doors.) | 479.00 257.00 |
|--|---|--|---|
| | The upper edg Part No. | ge of this panel welds against body. Correct horozonital ribs. Description 1939-46 1 3/4" widepair | 89.50 |
| TL093 TL082 TL224 TL224 TL1083 TL1083 TL1083 TL1083 TL1083 TL1083 TL1083 TL1083 TL1083 TL1083 | •Sheet Meta These Spotw They make b the underlyin panel can be spotweld cutt a regular han out spotwelds restoring you Part No. TL093 TL094 TL224 TL096 TL082 TI1083 TL214 TL750 This Sheet M half the time joint even thr need to remo from one side | 1 | s. ving f. The the sed in o drill arage 49.95 32.04 18.50 cutters, 54.95 atters, 49.59 34.95 17.28 6.95 hade in erfect ns. No ned |
| | | | |



SPEEDOMETER AND GAUGE

| | Gauge Refacing Kits Finally, a proper refacing kit for those otherwise good dash gauges. Many hours and much talent put into this project. If your gauges wor you can make them look like new with this kit. Custom waterless, stick-on decals perfec cover those weathered gauges. Exact, as original. Kit includes detailed instructions, pl decals to do all instruments, speedometer and odometer. Part No. Description SP107 1934-35 Chevrolet, black. For 90 mph gaugeset 10.5 | tly us |
|---------------|---|---|
| SP106 | SP102 1936-39 Chevrolet, cream. For 100 mph gaugeset 12.7 SP106 1936-39 GMC, dark cream. For 80 mph gaugeset 12.7 SP101 1940-46 Chevrolet, brown. For 100 mph gaugeset 12.7 SP101 1940-46 GMC, dark cream. For 80 mph gaugeset 12.7 SP174 1940-46 GMC, dark cream. For 80 mph gaugeset 12.7 | 75 75 75 |
| | Speedometer - New Yes, we just had these produced! Look just like over 65 years ago. No core charge. Part No. Description SP179 1940-46 Chevroleteach 195.0 | 00 |
| ENEWS | Odemeter - New Correct black 10th wheel with white numbers. The other five wheels are white with bla numbers. The gear on end has the correct straight teeth, not tapered. Part No. Description SP180 1937-1939 and 1947-1954each 34.7 SP109 1934-1935 and 1955-1959 Decal onlyset 9.9 Note: SP109 is Set 7 rows of white on black numbers and 7 row of black on white number | 75 95 |
| 1936-39 | Speedometers - Rebuilt Professionally rebuilt AC Delco units. Not reproductions. Include new odometer, needland face decal, as appropriate. Other items rebuilt or replaced. Show quality. We supporting units, non-repairable imports. Part No. Description RESP168 *1934-35 Chevrolet (attaches to square end type cable)each 210.0 RESP169 *1936 Chevrolet (attaches to square end type cable)each 210.0 RESP184 1937-39 Chevroleteach 210.0 RESP170 *1936-39 GMC (attaches to square end type cable)each 210.0 RESP171 1940-46 Chevroleteach 210.0 RESP173 1940-46 GMC RESP174 *1940-46 GMC Big truck (attaches to square type cable)each 210.0 RESP174 *1940-46 GMC Big truck (attaches to square type cable)each 210.0 RESP174 *1940-46 GMC Big truck (attaches to square type cable)each 210.0 RESP174 *1940-46 GMC Big truck (attaches to square type cable)each 210.0 RESP174 *1940-46 GMC Big truck (attaches to square type cable)each 210.0 RESP174 *1940-46 GMC Big truck (attaches to square type cable)each 210.0 RESP174 *1940-46 GMC Big truck (attaches to square type cable)each 210.0 RESP174 *1940-46 GMC Big truck (attaches to square type cable)each 210.0 SP187 Core charge for speedometers listed above | ply 00 00 00 00 00 00 00 |
| RESP231 | Gauge Clusters - Professionally Rebuilt We can restore your 1940-46 cluster to excellent condition including new glass, chrome beze gaskets, painted metal, new decals on working checked gauges, rebuilt speedometer, er You will really like this! Exchange only. Part No. Description RESP230 1940-46 Chevrolet | etc. 00 00 00 00 00 00 00 ire |
| 122 oldchevyt | | 57 |

SPEEDOMETER AND GAUGE

...visit our website for SPECIAL savings!



| GAU | GES |
|-----|-----|
|-----|-----|

We have new (or restored to look and operate new) gauges for the 1934-46 trucks. Let us know your specific needs if you don't require our complete restored clusters listed in this catalog. Important: We can restore your other GM truck gauges. Send us your cores. Inquire about other years. Inquire about other New Gauges!

| | • Oil Gauge, GM Rebuilt Part No.Description DescriptionRESP2651934-35 Chevrolet 30lbseach each RESP273RESP2731936-39 GMC 80lbseach RESP269RESP2691936-39 Chevrolet 30lbseach RESP234RESP2341940-46 Chevrolet 30lbseach RESP239RESP2391940-46 GMC 80lbseach core chargeME679core chargecore | 55.00 55.00 55.00 55.00 65.00 35.00 |
|--|---|---|
| | •Amp Gauge, GM Rebuilt Part No.Description each RESP264RESP2641934-35 Chevrolet each RESP270each each each each RESP235RESP2351940-46 Chevrolet each RESP237each each each each core charge | 45.00 45.00 40.00 40.00 35.00 |
| | •Fuel Gauge, GM Rebuilt Part No. Description RESP266 1934-35 Chevrolet 6 volt | 60.00 60.00 60.00 60.00 60.00 60.00 35.00 |
| | •Fuel Gauge, New, Looks just like GM! Part No. Description SP256 1940-46 Chevrolet 12 volt, White needleeach | 85.00 |
| 1934-35 Chevrolet 1936-39 Chevrolet 1940-46 Chevrolet | Temperature Sending Unit - GM Mechanical Rebuilt Complete recharged GM gas filled unit, including dash gauge new, line, engine head unit, and new face decal. Note: We now offer extended tubing line for V8's. Part No. Description REME920 1934-35 Chevrolet | 80.00 80.00 80.00 80.00 80.00 95.00 89.00 89.00 89.00 89.00 50.00 |

ORDERS 1-800-862-1913 TECH HELP 2-4pm 1-816-252-5857 oldchevytrucks.com 123



SPEEDOMETER AND GAUGE

| Truck Parts | visit our website for SPECIAL savings! | |
|----------------------|--|--|
| 1940-46 Chevrolet | • Temperature Sending Unit - New Mechanical Six Cylinder, Looks just like CPart No.DescriptionMEE0011940-46 Chevrolet | 59.95 59.95 59.95 59.95 59.95 |
| | SPEEDOMETER CABLES AND GROMMETS• Speedometer Cables with Metal Wrap Housing Exact as original. Made in the USA! Show quality.Part No.DescriptionME4851934-36 Chevrolet and 1936-46 GMC with square end connect at speedometer end - 65" | 46.50 39.50 46.50 |
| \mathbf{x} | Speedometer Cables with Black Vinyl Housing Excellent replacement. Part No. Description ME2274 1937-46 65" longeach ME811 1939-59 Cab Over Engine body - 108 1/2" longeach | 26.50 42.50 |
| \bigcirc | • Speedometer Cable Firewall Grommet Part No. Description FP183 1936-59each | 1.75 |
| Special order! | Speedometer Ratio Adapter Corrects the error in your speedometer when your rear tires or total differential h changed. Fits all GM applications. Simply follow a vehicle with a correct speedometer us what correction you need. We will have a ratio adapter custom built for you takes minutes to install to your transmission! Made in the USA. Part No. Description SP249 1934-72 Special order per your specifications, NO refundseach | eter and |
| | GLASS DASH BEZELS, PANELS, NEEDLES, ETC.• Bezel for Gauge ClusterChromed steel. Show quality!Part No.DescriptionSPS4001940-46 Chrome, not paintedeach | 39.00 |
| 2.57 | Speedometer Glass Panels Has white lettering, as original. Exact for 1940-46. Made in the USA. Part No. Description SP189 Chevrolet, 100 mpheach Like SP189 above except is printed with higher maximum oil pressure and water tem numbers. Excellent if you have a more modern 235 six cylinder. Oil pressure is Temperature is 220 degrees. Part No. Description SPS001 1940-46 Chevrolet, 100 mph with higher numberseach | 29.00 16.95 perature s 60 lbs. 18.50 |
| \bigcirc | Speedometer Bezel to Glass Gasket Part No. Description SP188 1940-46 Use with SP189 and SP190set | 4.75 |
| | Speedometer Needles, All Metal Part No. Description SP223 1940-46 Chevrolet, whiteeach SP224 1940-46 GMC, redeach | 9.65 9.65 |

124 oldchevytrucks.com ORDERS 1-800-862-1913 TECH HELP 2-4pm 1-816-252-5857

TRIM



| TR102 | EMBLEMS AND ORNAMENTS • Grille Emblems Chevrolet only. Part No. Description TR283 1934-35 Three color porcelin over metal | 48.00 25.50 |
|---|---|--|
| TR101 CHEVROLET M Restoration Parts | Hood Side Emblem Show chrome with dark blue background as original. Show quality. Part No. Description TR101 1936-38 Chevrolet | 69.50 |
| TR143 | Hood Ornaments Finally, we have these in demand, front chrome ornaments. Necessary to hold the hood in place. Made in USA! Part No. Description TR143 1937 Chevrolet | e front of 249.00 155.00 249.00 155.00 249.00 155.00 |
| | WHEEL RINGS • Stainless Steel Wheel Rings As used on deluxe pickups. Top quality! The mirror finish looks great in combina our hub caps. 1 3/4" wide. Part No. Description TR146 15" | tion with 26.00 26.00 |
| Constant of the second | HUB CAPS For Chevrolet and GMC pickups, we are the hubcap source! Like original in sh color. A perfect addition for your special truck. Fits factory inside clip wheels. Part No. Description TR300 1935-36 Chevrolet. As TR118 below except is a complete wire wheel with stainless skin | |



UPHOLSTERY

...visit our website for SPECIAL savings!



UPHOLSTERED SEAT KITS

| | UPHOLSTERED SEAT KITS Quality interiors to complete your restoration. Now available, interiors for the perference Complete seat kits for the old GM pickups. These are pre-made with piping, dimerence and stitching, as original. These covers are ready for you to install on your sprint frame. Seat material available in grain brown or black. Very close to the original. kits below require UP100 Installation Kit. Part No. Description UP150BN 1937-Early 38 Grain Brown (with split bottom seat) | ensions, ngs and |
|---------|--|---------------------------------|
| | | 170.35 |
| | | 130.80 |
| | | 130.80 |
| | UP101BN 1939-46 Grain Browneach | 135.00 |
| | UP101BK 1939-46 Blackeach | 135.00 |
| | Seat Kits, Installation Kit Part No. Description | |
| | UP100 Installation kit includes cotton, burlap, clips, and instructionskit | 43.50 |
| | | |
| | Seat to Frame "C" Clips If your originals are broken, we have the replacements. Secures seat material to edges with no holes. Part No. Description | |
| | UP220 1937-59 70 clipsset | 4.95 |
| | Sunvisor Bracket Not marketed in 50 years! This rare accessory is now available. Exact copy of an including chrome plating. Bracket only. Right or left. (This should even work on the 38 body style. Part No. Description UPV138 1939-46each | |
| | Sunvisor Bare Pad A GM accessory installed by the authorized Chevrolet and GMC dealers. Right or I Sold Each. Excellent for those who want to cover their visor for a custom look o beige cloth covered pad close to original. Also used on other cars and trucks in the 1950"s and 1960"s. Dimensions 6" x 15 1/2". Can be used with UPV138 chrome being Part No. | or use a 1940"s, pracket. |
| UPV129 | UPV129 1939-46 Uncovered Board as original, you covereach UPV127 1939-46 Beige Cloth Upholstered Padeach | 29.95 49.50 |
| OF V125 | | 49.00 |
| | • Sunvisor Combo - Pad and Chrome Bracket A new chrome bracket and cloth upholstered pad. Made from a 65 year old orig borrowed from a customer. The beige cloth covered pad is 6" x 15.25". Show qual unusual accessory was available at the Chevrolet dealers in the 1940"s. As trucks w | ity. This |
| | work only and money way limited, few visors found buyers.Part No.DescriptionUPV1281939-46 | 69.95 |
| | | |

 ORDERS
 1-800-862-1913
 TECH HELP 2-4pm
 1-816-252-5857
 oldchevytrucks.com
 127



UPHOLSTERY

...visit our website for SPECIAL savings!

HEADLINERS AND KICK PANELS

| • H | eadlin | ers, | Fibe | rg | lass |
|-----|---------|------|------|----|------|
| | 1 1.4.4 | | | | |

| | In addition t are easy to | rs, Fiberglass o our original cardboard style, we now have one piece fiberglass install and are already formed to the shape of your cab. Can be h cloth. Made in the USA. Description 1937-38 1936 Correct rear cab panel, will also fit 1937-38 1939-46. | painted .each .each | |
|---------|--|--|--|---|
| Z NEW Z | Preformed truck; some them fiberg the strength the polybut | ABS Plastic 1939-1946 One Piece Formed ABS plastic headliner has leather grain texture. Depending on trimming is required on driver and passenger sides. Ships over lass. Made in the USA! The advantage of ABS is that this man and rigidity of the acrylonitrile and styrene polymers with the adiene rubber. The most important mechanical properties of A and toughness. Improve impact resistance, toughness, and hear Description 1939-46 | rsized b terial co e tough ABS are at resista | out small ombines nness of e impact |
| | All headline 1937-38, 19 Part No. UP2391 UP2392 UP1051 UP1052 UP1054 UP1062 UP1062 UP1141 UP1142 UP1144 UP2431 UP2432 UP2071 UP2072 | ad Larger Truck Headliners, Heavy Fiberboard rrs from 1936 to 1953 were originally Medium Brown. You hand 039, and 1940-mid 41. Die cut "two piece" mid 1941-46. Description 1934-36 Medium Brown. Two sheets provided for you to cut and form. Also good for Universal use | pair pair .each .each .each .each .each .each .each .each .each .each .each .each | 48.00 48.00 40.00 40.00 40.00 40.00 40.00 40.00 40.00 40.00 40.00 35.50 35.50 |
| | UP2074 | 1942-46 Gray. Two piece type | pair | 35.50 |

UPHOLSTERY

...visit our website for SPECIAL savings!



| Panel Truck Headliners, Heavy Fiberboard Part No. Description UP1111 1939-46 Medium Brown. One pieceeach UP1112 1939-46 Black. One pieceeach | 39.00 39.00 |
|---|--|
| • Headliner Washers Necessary to hold the above factory cardboard sheet against cab roof. Exact as c (These were used to hold up center of the one piece headliner prior to center bow in Part No. Description UP112 1934-41 Black rubber over metal. Set of 3set | • |
| Kick Panels, Heavy Fiberboard, Made in USA! Part No. Description *UP2461 1936-38 Medium Brownpair *UP2462 1936-38 Blackpair UP2471 1939-46 Medium Brownpair UP2472 1939-46 Blackpair *Note: These 1936-38 units even include the sewed-on edge welting just like origin | 37.50 37.50 15.50 15.50 nal! |

1939 Chevrolet

A LINE OF "HUSKIES" ON HITLER'S TRAIL

"Somewhere in Africa" these and other long lines of Chevrolet trucks are moving forward with our fighting men in irresistible pursuit of the Axis. . . . And all over the embattled world Chevrolet-built airplane engines, antiaircraft guns, armor-piercing shells and other war equipment are likewise serving side by side with our fighting men. . . They're the world's best fighting men, and they deserve the world's best equipment—in a great, growing, inexhaustible stream—in VOLUME FOR VICTORY!

Chevrolet trucks on duty in the North African campaign.

CHEVROLET DIVISION OF GENERAL MOTORS

130 oldchevytrucks.com ORDERS 1-800-862-1913 TECH HELP 2-4pm 1-816-252-5857

USED PARTS

...visit our website for SPECIAL savings!



We are the leader in sales of used truck parts for 1934-72. Chances are good we will find your needs in our large inventory. The items are very restorable and are not rebuilt or upgraded. Inquire about items not listed here. **Note:** These parts are in good restorable condition.

| • Air Breather 1937-40 and 1941-46 Oil bath | • Exhaust and Intake Manifold Combination Specify Chevrolet 216 or 235 engine (inquire) |
|--|--|
| • Ash Tray 1940-46 | • Glovebox Lock with Key 1940-53 Nice appearance. |
| Axle, front | Glovebox Doors |
| • Bed Sides A major price drop from our new bed sides. May have | 1936-38, 1939, or 1940-46 Specify year. |
| some scrapes and minor tears. Includes stake pockets. 1941-53 1/2 ton | Headlight Stand 1939-40 Left or right |
| • Brake Drums - Front or Rear Turned, ready to install. | Headlight Buckets 1941 or 1942-46 Left or right |
| 1938-50 Rear 1938-50 Front with hubs | • Hoods 1941-46 Chevrolet |
| • Bumpers Many available for 1 1/2 ton large trucks \$50. | • Hood Strips Horizontal trim on hood sides. Specify left or right. |
| Bumper Braces | 1941-46 Chevrolet |
| 1941-46 Chevrolet or GMC | |
| Cab Interior Sheet Metal Most items available. | • Grille Emblem Will have some pits and fair chrome. 1941-46 Chevrolet |
| Cylinder Heads | • Horns |
| No valves or guides. Chevrolet six cylinder, cleaned and checked for cracks | 1937-52 Original, 6 volt, works good, but needs cosmetics |
| GMC six cylinder, cleaned and checked for cracks | Ignition Housing with Key and Cylinder |
| Deere Without Herdurer | 1940-46 Without cable to coil |
| • Doors, Without Hardware Check on condition. Will ship by UPS. 1939-46 | 1940-46 With cable to coil |
| 1909-40 | Lower Air Filler Panel |
| • Distributor | 1941-46 |
| 1937-53 Chevrolet 216 engine | Oil Filter Assembly |
| 1941-53 Chevrolet 235 engine | The outer housing needs cleaning and painting. |
| • Engine To Frame Side Plates 216 six cylinder | Chevrolet, six cylinder, with new lines and new cartridge |
| | |



USED PARTS

...visit our website for SPECIAL savings!

 Oil Pans Six cylinder (specify year)

- Radiators 1946 and older. Pressure checked. When available
- Rear Window Die Cast Metal Frame 1936-38
- Running Boards 1937-38, 1939-40, and 1941-46 1-1/2 and 2 ton, left or right. Check on availability.
- Seat Cushion Springs 1939-46 Needs totally reupholstered.
- Shock Absorbers 1946 and older, single action lever type with arms
- Spindle 1941-50 1/2 or 3/4, and 1 ton, for front axle



- Steering Column Complete with good box and shaft (specify year)
- Valve Cover Stock both Chevrolet and GMC style.

Valve Cover Kits

If you place a late model 235 engine in your 1937-46 Chevrolet truck, we can help you disguise its appearance. It will then look much like your trucks original 216 engine. Specify your year of truck.

1937-46 Chevrolet. This set includes a used valve cover with new gasket, attaching studs with seals and cap nuts, engine breather tube with oil cap.

Wheels

We attempt to stock 16" to 20" units from 1/2 to 1 1/2 ton. Check our supplies. All need bead blasting and paint.

 Window Crank or Inside Door Handles 1939-46

 U-Joint Bell Excellent, original aluminum.



It doesn't cost any more to work with Jim Carter **Truck Parts.**

It Pays!!

1939-46

...visit our website for SPECIAL savings!



Attention! No dealer supplies more different

styles of glass for the 1936 -46 Chevrolet / GMC trucks. These are clear glass as original, however light green tint is available on special order. Windshields are safety glass while other panels are usually tempered for your safety.

NOTE: For "clear" glass use numbers listed under main headings below. For light green tint add the part # plus G. There are two additional windshield tint options. Light green with Blue Upper Band = part # plus B and Clear with Blue Upper Band (only the 1939-46 V shape one piece) = part # plus CB.

| 60 | • Windshiel Part No. WI441 | lds Description 1939-46 Sold in halves, cleareach | 59.95 |
|-------|----------------------------------|--|-------|
| | | ss, Clear (Also Suburban and Panel) | |
| CONC. | Part No. | Description | |
| | WI444 | 1936 low cab-1938each | 42.00 |
| 100 | WI445 | 1939-40each | 52.00 |
| WI444 | WI446 | 1941-46 Must have steel outer frame, not includedeach | 52.00 |
| | Rear Glas | s, Clear | |
| | Part No. | Description | |
| | WI450 | 1936 high cab-1938each | 33.00 |
| | WI451 | 1939-41 Must have die-cast outer frame, not includedeach | 39.00 |
| WI451 | WI452 | 1942-46each | 39.00 |
| | • Surburba | n and Panel Truck Body Glass, Clear | |
| | Part No. | Description | |
| | WI224 | 1939-46 rear double door glasseach | 35.00 |
| | WI454 | 1939-46 Suburban, front quarter sideeach | 68.00 |
| | WI455 | 1939-46 Suburban, rear quarter sideeach | 72.00 |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |



...visit our website for SPECIAL savings!

| | Window Channel Premium quality. Properly cloth coated and lined. Stops the rattling or breaking of y up door glass. Will give years of top service. Glues in place. Part No. Description WI201 1934-46 Black (cut into 3 pcs per side for 1934-35)pair | your roll 69.50 |
|----------|--|-------------------------|
| | Glass Setting Tape, (Tightens glass in metal frame.) Part No. Description WI101 For roll-up windows and windshield frames (sold per foot)foot | .90 |
| | Window, Outer Seal Slides into horizontal track on inside and outside of door. Helps stop rattles and Identical to original. Four pieces. Part No. Description WI416 1936-46set | d drafts. 12.75 |
| | • Windsheild Wing Nut Holds swing out windsheild frame. Brass. You paint black as original. Made in the Part No. Description WI412 1929-36each | USA! 29.95 |
| | Window Handle, Chrome Part No. Description WIH345 1936-38 with chrome knob, left or righteach WIH349 1939 With black knob, left or righteach WIH350 1940-46 With tan knob, left or righteach | 39.50 35.00 35.00 |
| 0 | • Window Handle Escutcheon Fits between inside handle and door panel. Part No. Description WIH346 1934-38pair | 29.95 |
| | Window Handle Screw, Chrome Made one at a time to give you this correct Fillister head. Part No. Description WIB204 1929-46, Includes lock washer (3/4" long)each | 3.90 |
| 0 | Window, Side Rubber Bumper Stops (Close to original, glue in place.) Part No. Description WI197 1934-36 (set of 4) High cabset WI230 1936-46 Low cab, set of 2pair | 3.75 1.90 |
| } | Windshield Gaskets New black rubber as original. Part No. Description WI122 1932-36 High cabeach WI123 1936-46 Low cabeach WI460 1939-46 Low cab, one piece (meeting ends glued)each | 25.95 19.95 37.75 |
| | Window Regulator Repair Kit Replace the worn gear to give a much smoother operation. Part No. Description WI198 1934-46kit TUCKS.com ORDERS 1-800-862-1913 TECH HELP 2-4pm 1-816-25 | 26.95 |

134 oldchevytrucks.com ORDERS 1-800-862-1913 TECH HELP 2-4pm 1-816-252-5857



| | Window Regulator Gear, Made in the USA! Part No. Description WI247 1934-46 metal geareach | 18.75 |
|-------------|--|---|
| | Window Regulator Repair Spring Holds window in raised postion. Zinc plated. Part No. Description WIR208 1936-46each | 10.50 |
| | Windshield Frames Formed with same gauge material as original. Includes metal connectors. Top qua chrome steel. You paint or chrome. Made in USA! Part No. Description WI152 1934-35each WI154 1936 High Cab with top hingeeach WI158 1936 Low Cabeach WI159 1937-38each WI200 1939-46 Without center vertical (see below)each | ity! Non- 550.00 550.00 399.00 399.00 425.00 |
| to- | Windshield Center Division Bar Includes a high polished vertical and the necessary rubber seals to fit your windshie Part No. Description WIB202 1939-46set Windshield Post Covers, Hand made in the USA! | ld frame. 85.50 |
| ₽ /~ | Extend vertical from top to bottom.Part No.DescriptionWI3951937-38, metal as originalpair | 48.75 |
| C. Marine | Windshield Crank Handle, Chrome Show quality, equal or better than original. Part No. Description WIH347 1936-38 with chrome knobeach WIH348 1939 Chrome with black knobeach WIH355 1940-46 Chrome with tan knobeach | 37.50 35.50 35.50 |
| WIB208 | Windshield Crank Handle Screws, Chrome Made one at a time to give you the correct Fillister head. Part No. Description WIB204 1936-39 (3/4" inch long) lock washer includedeach WIB208 1940-46 (1 3/8" inch long)each | 3.90 3.90 |
| | Windshield Crank-Out Assembly Reconditioned to operate as original. Exchange only. Core must be complete v stainless tongue and non-cracked housing or it may not be repairable. Part No. Description REWI161 1936-38each REWI162 1939each REWI163 1940-46each | vith good 185.00 185.00 185.00 |
| 0. AND 10 | Windshield Connector Attaches the crankout assembly to windshield frame. Hand made in the USA to specifications. Part No. Description WIC300 1936-38each WIC301 1939-46each | 27.50 35.00 |

| Narter | |
|----------|-----|
| Truck Pa | rts |
| | 115 |

| | Windshield Crank Grommet for Part No. Description WI165 1936-39 | Dash Handle each | 1.50 |
|-------|---|--|---|
| 0 | Windshield Crank Fiber Washer Part No. Description WI166 1940-46 | for Dash Handle each | 1.25 |
| | surrounding metal washer. Part No. Description | between lower windshield frame and cab. kpair | Rubber 5.95 |
| WI141 | These are included with windshieldPart No.DescriptionWI3681936-38 straight | ether windshield halves. Includes necessary frames above. Chevrolet and GMC. | screws. 19.95 27.95 |
| | WI132 1939-41 Fits behind r WI133 1942-59 With black fi WI134 1942-59 With chrome | netal rear window frame (1 piece)each netal rear window frame (1 piece)each ler lock strip. (2 pieces)kit filler lock strip. (2 pieces)kit 4) is not original but a nice addition to the custo | 29.95 19.00 21.50 24.75 om truck. |
| | • Window, Rear Rubber Kits for F Part No. Description WI1371 1939-59 Close to ori | Panel or Suburban ginal style (for double doors)pair | 24.50 |
| 0 | Part No. Description | ation Tool for installing lock strip-1942 and newer. h tooleach | 9.50 |
| | • Window, Rear Molding Screw S The proper pan head fine thread so Part No. Description WI138 1936-42 14 pieces . | | 7.95 |
| L. | Part No.DescriptionTRC1451936-38 | er interior window trim. Two required per truck. each each | 10.50 10.50 |


...visit our website for SPECIAL savings!

We have sets of patterns on heavy paper. A great help when



Window Glass Patterns

| you need new glass cut at your local shop. | | | | |
|--|---------------------|-------|--|--|
| Part No. | Description | | | |
| WI173 | 1934-36 High cabkit | 21.00 | | |
| WI169 | 1936-38kit | 19.00 | | |
| WI170 | 1939-46kit | 19.00 | | |



They're the outstanding trucks for 1937... because they're modern to the minute ... because they give "more power per gallon, lower cost per load"... and because they're good for years of dependable service. Powerful beyond their price, modern to the minute, famous for economical transportation, Chevrolet trucks are earrying an ever-increasing volume of the daily shipments of truck users throughout the country. They're the thrift carriers for the nation . . . staying on the job day after day . . . requiring a minimum of gas, oil and upkeep . . . giving many thousands of miles of safe, dependable service. Extra-rugged construction explains their dependability; Perfected Hydraulic Brakes, their safety; and a New High-Compression Valve-in-Head Engine, their ability to give more power per gallon, lower cost per load.

General Motors Installment Plan—monthly payments to suit your purse. CHEVROLET MOTOR DIVISION, General Motors Sales Corporation, DETROIT, MICHIGAN

"MORE POWER per gallon LOWER COST per load !"



WIPER ITEMS


| | | Also includes Fits in origina the right side in our Electric Part No. | avy duty electric wiper motor for those not requiring the original vacu s one wiper blade,wiper arm, and metal cover plate. Easy bolt-in ap al location and is hidden by the wiper cover plate that is normally a bla . To regulate speed, use with our under dash rheostat switch EL117 | plication. hk-out for |
|-----|------------|--|---|--------------------------|
| | | | and Blade Replacement, (for WW349 AND WW350 Only.) | 07.50 |
| | | Part No. WW351 | Description 1939-46 Sold as 1 pair (1 arm and 1 blade)pair | 19.95 |
| م | | A newly desi through a sp | or, Electric 12 Volt (Deluxe Design) gned US made assembly. One 12 volt motor operates the pair of wi becially designed linkage. Arms move together at the same speed! n,wiring,linkage, arms, and blades. Description 1936 low cab-1938 | Includes 369.00 |
| Ŕ | | Double action vacuum pum | , Double-Action In type. To help stop vacuum wiper slow down, this combination fuel p p may be appropriate. Keeps constant vacuum on to the original wip upment on large commercial trucks. Optional on smaller trucks. Description 1937-62 Chevrolet and 1939-59 GMC six cylindereach | |
| | | • Wiper Beze Part No. WW137 WW138 | els, Chrome (Above Windshield) Made in the USA! Description 1936-38each 1939-46each | 19.75 19.75 |
| | | • Wiper Chro Part No. WW346 | ome Bezel Nut Description 1936-46each | 6.50 |
| | | • Wiper Blad Part No. WW108 | les Description 1929-46 Original flat blade type (approximately 8")each | 7.00 |
| est | | • Wiper Arm As original. U Part No. WW136 WW122 | s Used with original type blades only. Description 1934-38 Left or right, stainless steel (8" long)each 1939-46 Left or right, chrome (9 1/4" long)each | 15.00 18.00 |
| | \bigcirc | • Wiper Shat Part No. WW104 | ft Gasket Description 1936-46 Fits between chrome bezel and roofeach | .95 |

WIPER ITEMS




| | Wiper Motor Cover Plate Grommets Part No. Description |
|------------|--|
| | WW213 1936-46 Fits in cover plate in cabpair 2.50 |
| \bigcirc | • Wiper Vacuum Tubing Part No. Description WW114 Vacuum tubingfoot .95 |
| | Vacuum Line Firewall Grommet For line leading to wiper motor. Part No. Description FP104 1936-59each 1.00 Wiper Motor Cover Plates We now have the plates that cover the wiper panel rectangular hole above windshield. |
| | <text></text> |















...visit our website for SPECIAL savings!


EVRO

ruck Parts






...visit our website for SPECIAL savings!





...visit our website for SPECIAL savings!



ORDERS 1-800-862-1913 TECH HELP 2-4pm 1-816-252-5857 oldchevytrucks.com 145





| Carter Carter Truck Parts |
|---------------------------------|
| |

Order Date _____

Invoice No. _____

Salesperson _____

Order No. _____

MAIL ORDER FORM

1508 East 23rd Street • Independence, Missouri 64055-1657 Phone 1-816-833-1913 24 Hour Fax Lines: 1-816-252-3749, 1-800-262-3749 Outside US and Canada

oldchevytrucks.com

| Name | Customer No |
|-----------|-------------|
| Address | Year |
| | Chevy GMC |
| City | Model |
| State Zip | Engine Size |
| Phone () | E-MAIL: |

| PART NO. | QTY. | DESCRIPTION | PRICE | TOTAL |
|----------|------|-------------|-------|-------|
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| L | | | | |

Sub Total

| CREDIT CARD NUMBER | Inquire on Shipping & Handling | |
|--------------------------------|---|--|
| Visa 🗌 MasterCard 🔲 Discover 🔄 | Missouri Residents Add 7.725 % | |
| | Sales Tax Pay by Check, Money Order, | |
| My card expires | or Charge Your Order | |
| | TOTAL | |
| Name on Card | • | |

(OVER)

| PART NO. | QTY. | DESCRIPTION | PRICE | TOTAL |
|----------|------|---------------------------------|---------------|-------|
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | · | |
| | | Pag | e 2 Sub Total | |
| | | CHEVROLET Inquire on Shipping | & Handling | |
| | | Missouri Residents | Add 7.725% | |
| | 10 | | Sales Tax | |
| | | Pay by Check, N | Ioney Order, | |
| | | <i>k</i> Parts or Charge | e Your Order | |
| | | | TOTAL | |
| | | | L | |

| MAIL ORDER FC oldchevytrucks.com | Phone 1-816-833-191 1-800-262-3749 Outs | Order No et • Independence, Missouri 64055-1657 3 24 Hour Fax Lines: 1-816-252-3749, | |
|--|--|--|-------|
| Name Address City State Zip _ Phone () | Year Chevy D Model Engine Size | o GMC | |
| PART NO. QTY. | | PRICE PRICE PRICE | TOTAL |
| CREDIT CARD NUMBER Visa MasterCard Discov Image: Image of Card Image of Card Image of Card | /er | Sub Total Inquire on Shipping & Handling Missouri Residents Add 7.725 % Sales Tax Pay by Check, Money Order, or Charge Your Order TOTAL | |

(OVER)

| PART NO. | QTY. | DESCRIPTION | | PRICE | TOTAL |
|--------------------------------|------------------|-------------|----------------------|------------|-------|
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | | | | | |
| | Page 2 Sub Total | | | | |
| Inquire on Shipping & Handling | | | & Handling | | |
| | <u>i</u> | CMC CMC | Missouri Residents A | .dd 7.725% | |

Sales Tax Pay by Check, Money Order, or Charge Your Order

TOTAL



| | | Order No t • Independence, Missouri 64055-1657 3 24 Hour Fax Lines: 1-816-252-3749, | |
|---|--|--|--|
| Name Address City State Zip Phone () | Year Chevy D Model Engine Size_ | о GMC [] | |
| PART NO. QTY. | DESCRIPTION | PRICE | |
| CREDIT CARD NUMBER Visa MasterCard Discover Image: Imag | res | Sub Total Inquire on Shipping & Handling Missouri Residents Add 7.725 % Sales Tax Pay by Check, Money Order, or Charge Your Order TOTAL | |

| PART NO. | QTY. | DESCRIPTION | PRICE | TOTAL |
|----------|------------------|-----------------------------------|-------------------------------------|----------|
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | 1 |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | _ |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | | | | |
| | Page 2 Sub Total | | | |
| J | | Inquire on Ship Missouri Resid | pping & Handling ents Add 7.725% | |

Sales Tax Pay by Check, Money Order, or Charge Your Order

TOTAL

